CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Program Types

AIRCRAFT	**SERIAL/REGNO:**	S550-0086 / VH-SQM	**MODEL:**	S550 - CITATION SII	**MANUFACTURER:**	TEXTRON AVIATION INC.	
UTILIZATION:	N/A						
OPERATING REGULATION:	N/A						
REGION OF OPERATION:	N/A						
OPTIONAL EQUIPMENT:	N/A						
ENGINE NO. 1	**SERIAL/PART:**	PCE-102251 / JT15D-4B	**MODEL:**	JT15D-1/-1A/-1B/-4/-4B/-4D	**MANUFACTURER:**	PRATT & WHITNEY CANADA CORP.	
UTILIZATION:	N/A						
OPERATING REGULATION:	N/A						
REGION OF OPERATION:	N/A						
OPTIONAL EQUIPMENT:	N/A						
ENGINE NO. 2	**SERIAL/PART:**	PCE-102009 / 3035800	**MODEL:**	JT15D-1/-1A/-1B/-4/-4B/-4D	**MANUFACTURER:**	PRATT & WHITNEY CANADA CORP.	
UTILIZATION:	N/A						
OPERATING REGULATION:	N/A						
REGION OF OPERATION:	N/A						
OPTIONAL EQUIPMENT:	N/A						

These program types are defined in the OEM manual and can differ from your other settings. These selections will impact the active OEM interval defined on the aircraft status.

As an example,

1. Your aircraft might be EASA registered but you choose to follow the OEM recommended interval for Transport Canada. In that case the operating regulation would be TCCA and can be set to EASA if OEM did not specify intervals for EASA operation.
2. Region of Operation is driven from the OEM manual and the selection between Airframe, Engine and APU can differ since the OEM manual can have requirements dependent on different regions of operation.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
C55S-121005	REVIEW CAMP CHANGE FORM - MM CHAPTER 4 REVISION 7, DATED 23 APRIL 2012 AND CHAPTER 5 REVISION 17, DATED 1 AUGUST 2012				MTH		-			
051020	WEIGHT & BALANCE	YPAD			DAYS 01-Jul-2021 HRS 13322.6 LDG 10796		1095		30-Jun-2024	-24 m 24 d **Over Due**
051220 12	INSPECT 12MONTH RVSM INSP REQUIREMENTS	UNK			MTH 21-Dec-2022 HRS 13355.2 LDG 10819		12		31-Dec-2023	-30 m 24 d **Over Due**
052003	INSPECT MAINTENANCE RELEASE	UNK			DAYS 20-Dec-2022 HRS 13355.2 LDG 10819		730 180		20-Dec-2024 13535.2	-19 m 4 d 152.5 **Over Due**
052019	PERFORM ANNUAL TCAS/ACAS TEST	UNK			MTH 02-Dec-2022 HRS 13355.2 LDG 10819		12		31-Dec-2023	-30 m 24 d **Over Due**
052039	INSPECT ANNUAL RADIO INSP	UNK			DAYS 13-Aug-2024 HRS 13382.7 LDG 10844		365		13-Aug-2025	-11 m 11 d **Over Due**
052503	INSPECT LIFE VEST INSPECTION	YPAD			MTH 01-Jul-2021 HRS 13322.6 LDG 10796		36		31-Jul-2024	-23 m 24 d **Over Due**
052800	INSPECT FUEL CALIBRATION	YMEN			DAYS 24-Sep-2015 HRS 13279.9 LDG 10742		N/A			
053424	INSPECT NAV DATABASE UPDATE	UNK			MTH 15-Jul-2023 HRS 13379.2 LDG 10843		DUE DUE DUE DUE		10-Aug-2023	-35 m 14 d **Over Due**
055009	INTERIOR CABIN/TAILCONE FLUID SPILL						A/R			
055010	EXPOSURE TO HIGH WINDS WHILE THE AIRCRAFT IS PARKED						A/R			
055601 LEFT	INSPECT COCKPIT SIDE WINDOW INSPECTION	YPAD			MTH 01-Jul-2021 HRS 13322.6 LDG 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9 **Over Due**
5-12-01 *051201*	PHASE 1	YPAD			MTH 01-Jul-2021 HRS 13322.6 LDG 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9 **Over Due**
5-12-02 *051202*	PHASE 2	YPAD			MTH 01-Jul-2021 HRS 13322.6 LDG 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9 **Over Due**
5-12-03 *051203*	PHASE 3	YPAD			MTH 01-Jul-2021 HRS 13322.6 LDG 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9 **Over Due**

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
5-12-04 *051204*	PHASE 4	YPAD			MTH HRS LDG	01-Jul-2021 13322.6 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9
											Over Due
5-12-05 *051205*	PHASE 5	YPAD			MTH HRS LDG	01-Jul-2021 13322.6 10796		36 1200		31-Jul-2024 14522.6	-23 m 24 d 1139.9
											Over Due
5-12-0B *051200B*	PHASE B	UNK			MTH HRS LDG	21-Dec-2022 13355.2 10819		150		13505.2	122.5
5-12-11	PHASE 11 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)										
		UNK			MTH HRS LDG	05-Apr-2023 13357.9 10821		6			
B342004 *051211*	INSPECT/OPERATIONAL TEST STANDBY GYRO POWER SUPPLY LEAD ACID PS835 BATTERY PACK: PHASE 11			501-1228-04 13713	MTH	08-Aug-2024		6		28-Feb-2025	-16 m 24 d
											Over Due
5-12-12	PHASE 12				MTH HRS			3600		15442	2059.3
5-12-13 *051213*	PHASE 13	SAT			MTH HRS	12-Jun-1999 9403		5000		14403	1020.3
5-12-14 *051214*	PHASE 14	MGL			MTH HRS LDG	09-Nov-2011 12377 10145		3000		15377	1994.3
5-12-15 *051215*	PHASE 15	SAT			MTH HRS	12-Jun-1999 9403		5000		14403	1020.3
5-12-16 *051216*	PHASE 16	SAT			MTH HRS	12-Jun-1999 9403		5000		14403	1020.3
5-12-17 *051217*	PHASE 17	SAT			MTH HRS	12-Jun-1999 9403		10000		19403	6020.3
5-12-18 *051218*	PHASE 18	UNK			MTH HRS LDG	02-Dec-2022 13355.2 10819		12		31-Dec-2023	-30 m 24 d
											Over Due
A262003 AFT *051208 : A*	AFT PORTABLE HAND FIRE EXTINGUISHER - INSPECT. TASK 26-22-00-783	UNK		B385TS X67110	MTH	04-Apr-2023		12		30-Apr-2024	-26 m 24 d
											Over Due
Weight Check Date: 04-Apr-2023											
A262003 FORWARD *051208 : F*	FORWARD PORTABLE HAND FIRE EXTINGUISHER - INSPECT. TASK 26-22-00-783	UNK		B385TS Y-549288	MTH	04-Apr-2023		12		30-Apr-2024	-26 m 24 d
											Over Due
Weight Check Date: 04-Apr-2023											
5-12-20	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)										
		YPAD			MTH HRS LDG	13-Aug-2024 13382.7 10844		24			
B341001 LEFT *051220 : L-A/S*	CALIBRATION TEST AIR SPEED INDICATOR OVERSPEED WARNING SWITCH, DIFFERENTIAL PRESSURE SWITCH (AIRPLANES NOT CERTIFIED FOR RVSM): PHASE 20	YPAD		C661063-0105 181	MTH	01-Jul-2021		24		31-Jul-2023	-35 m 24 d
											Over Due
Calibration Date: 01-Jul-2021											

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
B341001 RIGHT *051220 : R-A/S*	CALIBRATION TEST AIR SPEED INDICATOR OVERSPEED WARNING SWITCH, DIFFERENTIAL PRESSURE SWITCH (AIRPLANES NOT CERTIFIED FOR RVSM): PHASE 20	YPAD		C661063-0104 178	MTH 01-Jul-2021		24		31-Jul-2023 **Over Due**	-35 m 24 d
Calibration Date: 01-Jul-2021										
B341003 STANDBY *051220 : STDBY*	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK		C661072-0101 W203902	MTH 13-Aug-2024 HRS 13382.7 LDG 10844		24		31-Aug-2026	1 m 7 d
Calibration Date: 13-Aug-2024										
B341004 STANDBY *051220 : STDBY*	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK		C661072-0101 W203902	MTH 13-Aug-2024 HRS 13382.7 LDG 10844		24		31-Aug-2026	1 m 7 d
Calibration Date: 13-Aug-2024										
B341005 LEFT *051220 : L*	LEAK TEST STATIC SYSTEM: PHASE 20	UNK			MTH 13-Aug-2024 HRS 13382.7 LDG 10844		24		31-Aug-2026	1 m 7 d
B341005 RIGHT *051220 : R*	LEAK TEST STATIC SYSTEM: PHASE 20	UNK			MTH 13-Aug-2024 HRS 13382.7 LDG 10844		24		31-Aug-2026	1 m 7 d
B341107 STANDBY *051220 : STDBY*	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	UNK		C661072-0101 W203902	MTH 13-Aug-2024 HRS 13382.7 LDG 10844		24		31-Aug-2026	1 m 7 d
Calibration Date: 13-Aug-2024										
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	YPAD			MTH 01-Jul-2021 HRS 13322.6 LDG 10796		24			
A237003 *051221 : CVR*	INSPECT COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON : PHASE 21	YPAD		DK120 DU2876	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		24		31-Jul-2023 **Over Due**	-35 m 24 d
A313002	INSPECT FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON UNDERWATER LOCATOR BEACON INSTALLED ON FLIGHT DATA RECORDER: PHASE 21	YPAD		DK100 DR3453	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		24		31-Jul-2023 **Over Due**	-35 m 24 d
B237004 *051221 : CVR*	OPERATIONAL TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON : PHASE 21	YPAD		DK120 DU2876	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		24		31-Jul-2023 **Over Due**	-35 m 24 d
B313002	OPERATIONAL TEST FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON UNDERWATER LOCATOR BEACON INSTALLED ON FLIGHT DATA RECORDER: PHASE 21	YPAD		DK100 DR3453	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		24		31-Jul-2023 **Over Due**	-35 m 24 d
B345001 LEFT *051221*	CALIBRATION TEST TRANSPONDER TRANSPONDER SYSTEM: PHASE 21	UNK		066-01143-2101 2295	MTH 13-Aug-2024 HRS 13382.7 LDG 10844		24		31-Aug-2026	1 m 7 d
Calibration Date: 13-Aug-2024										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
B345001	CALIBRATION TEST TRANSPONDER TRANSPONDER SYSTEM: PHASE 21										
RIGHT		UNK		066-01143-2101	MTH	13-Aug-2024		24		31-Aug-2026	1 m 7 d
051221 : R				2296	HRS	13382.7					
					LDG	10844					
Calibration Date: 13-Aug-2024											
5-12-22	PHASE 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)										
		EDLN			MTH	28-Mar-2013		36			
					HRS	12903					
					LDG	10486					
B326003	HYDROSTATIC TEST EMERGENCY GEAR AIR BOTTLE : PHASE 22										
051222 : GEAR		YPAD		212940-2	MTH	31-Oct-2020		36		31-Oct-2023	-32 m 24 d
				-							
											Over Due
Hydro Check Date: 31-Oct-2020											
5-12-23	PHASE 23 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)										
		UNK			MTH	05-Apr-2023		60			
					HRS	13357.9					
					LDG	10821					
B262002	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER : PHASE 23										
AFT		UNK		32700015	MTH	05-Apr-2023		60		30-Apr-2028	21 m 6 d
051223 : ATR				13022C1							
Hydro Check Date: 05-Apr-2023											
B262002	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER : PHASE 23										
FORWARD		UNK		32700015	MTH	05-Apr-2023		60		30-Apr-2028	21 m 6 d
051223 : FTR				16796C1							
Hydro Check Date: 05-Apr-2023											
5-12-26	PHASE 26	YPAD			MTH	01-Jul-2021		24		31-Jul-2023	-35 m 24 d
051226					HRS	13322.6		3000		16322.6	2939.9
					LDG	10796					
											Over Due
B243002	MARATHON NI-CAD BATTERY FUNCTIONAL CHECK (CAPACITY CHECK). THE INSPECTION INTERVAL CAN BE ADJUSTED AFTER THE WATER LOSS PER CELL IS ESTABLISHED. REFER TO THE BATTERY SERVICE TABLE. TASK 24-32-00-721										
		YPAD		ATSP-44	MTH	16-Mar-2018		12		31-Mar-2019	-87 m 24 d
				10100104	HRS	13316.3		150		13466.3	83.6
											Over Due
5-12-30	PHASE 30	EDLN			MTH	28-Mar-2013					
051230 : ACM					HRS	12903		600		13503	120.3
					LDG	10486					
5-12-32	PHASE 32	*CF			MTH	13-Mar-1986					
051232					LDG	0		15000		15000	4156
5-12-33	PHASE 33	*CF			MTH	13-Mar-1986					
051233					LDG	0		15000		15000	4156
5-12-40	PHASE 40 NOT USED				MTH	21-Jun-2001		A/R			
051240		HRZ			HRS	10135					
5-12-43	PHASE 43 NOT USED				MTH	01-Jun-2011		A/R			
051243		MGL			HRS	12079					
					LDG	9976					
B262003	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : PHASE 47										
AFT		YBSU		B385TS	MTH	31-Aug-2017		144		31-Aug-2029	37 m 7 d
051247 : A				X67110							
Hydro Check Date: 31-Aug-2017											
B262003	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : PHASE 47										
FORWARD		YBSU		B385TS	MTH	31-Aug-2017		144		31-Aug-2029	37 m 7 d
051247 : F				Y-549288							
Hydro Check Date: 31-Aug-2017											

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
B262004 AFT *051248 : A*	INSPECT PORTABLE FIRE EXTINGUISHER FIRE EXTINGUISHERS-EMPTY, FOR DAMAGE AND RECHARGE: PHASE 48	YBSU		B385TS X67110	MTH HRS LDG	31-Aug-2017 13312.4 10788		72		31-Aug-2023	-34 m 24 d
											Over Due
Inspection Date: 31-Aug-2017											
B262004 FORWARD *051248 : F*	INSPECT PORTABLE FIRE EXTINGUISHER FIRE EXTINGUISHERS-EMPTY, FOR DAMAGE AND RECHARGE: PHASE 48	YBSU		B385TS Y-549288	MTH HRS LDG	31-Aug-2017 13312.4 10788		72		31-Aug-2023	-34 m 24 d
											Over Due
Inspection Date: 31-Aug-2017											
5-12-49 *051249*	PHASE 49	YPAD			MTH HRS LDG	01-Jul-2021 13322.6 10796		36 1200		31-Jul-2024 14522.6	-23 m 24 d 1139.9
											Over Due
5-12-51	PHASE 51 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)				MTH HRS LDG	13-Mar-1986 0 0		60			
5-12-52 *051252*	PHASE 52	UNK			MTH HRS LDG	02-Dec-2022 13355.2 10819		12		31-Dec-2023	-30 m 24 d
											Over Due
5-12-53 *051253*	PHASE 53	YPAD			MTH HRS LDG	01-Jul-2021 13322.6 10796		72 2400		31-Jul-2027 15722.6	12 m 7 d 2339.9
5-12-54	PHASE 54				MTH HRS LDG	20-Nov-2013 13219.25 10713		1200		14419.25	1036.55
5-12-55	PHASE 55				MTH HRS	13-Mar-1986 0		15600		15600	2217.3
5-12-56	PHASE 56				MTH HRS	13-Mar-1986 0		15600		15600	2217.3
5-12-57	PHASE 57				MTH HRS			1200		13891	508.3
5-12-58	PHASE 58				MTH HRS			300		13546.37	163.67
5-12-59	PHASE 59	YBSU			MTH HRS LDG	08-Nov-2016 13303.1 10775		500		13803.1	420.4
5-12-60	INSPECTION PHASE 60				MTH			6		30-Apr-2024	-26 m 24 d
											Over Due
5-12-MA	PHASE MA				MTH HRS LDG	29-Mar-2023 13357.9 10821		N/A			
5-12-MB	PHASE MB				MTH LDG	13-Mar-1986 0		1000		10976	132
057110 E1	MINOR INSPECTION	YPAD			MTH HRS LDG	01-Jul-2021 13322.6 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9
											Over Due
057110 E2	MINOR INSPECTION	YPAD			MTH HRS LDG	01-Jul-2021 13322.6 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9
											Over Due

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
12-22-01-601	15 DAY HIGH EXPOSURE AREA WASH						A/R			
12-22-01-602	45 DAY MEDIUM EXPOSURE AREA WASH						A/R			
12-22-01-603	90 DAY LOW EXPOSURE AREA WASH						A/R			
211001	AIR CONDITIONING SYSTEM COMPONENTS, COMPRESSOR BELT AND EVAPORATOR CONDENSER COILS ANNUAL INSPECTION	UNK			MTH 21-Dec-2022 HRS 13355.2 LDG 10819		12		31-Dec-2023	-30 m 24 d **Over Due**
262003 AFT LEFT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) Installation (Serv. Life) Date: 01-Jul-2021	YPAD		13083-5 SN-UNKNOWN	MTH 01-Jul-2021		72	38	31-May-2024	-25 m 24 d **Over Due**
262003 AFT RIGHT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) Installation (Serv. Life) Date: 01-Jul-2021	YPAD		13083-5 SN-UNKNOWN	MTH 01-Jul-2021		72		31-Jul-2027	12 m 7 d
262003 FORWARD LEFT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) Installation (Serv. Life) Date: 01-Jul-2021	YPAD		13083-5 SN-UNKNOWN	MTH 01-Jul-2021		36		31-Jul-2024	-23 m 24 d **Over Due**
262003 FORWARD RIGHT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) Installation (Serv. Life) Date: 01-Jul-2021	YPAD		13083-5 SN-UNKNOWN	MTH 01-Jul-2021		36		31-Jul-2024	-23 m 24 d **Over Due**
28-00-02-220	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES NOT USING THE BIOCIDAL PREVENTATIVE TREATMENT)				MTH		3		31-Jan-2024	-29 m 24 d **Over Due**
28-00-02-221	MICROBIOLOGICAL CONTAMINATION INSPECTION (AIRPLANES USING THE BIOCIDAL PREVENTATIVE TREATMENT)						N/A			
314002	FDR FUNCTIONAL CHECK 12 MONTH.	UNK			MTH 02-Dec-2022 HRS 13355.2 LDG 10819		12		31-Dec-2023	-30 m 24 d **Over Due**
B350004 *051222 : OXY*	HYDROSTATIC TEST OXYGEN CYLINDER ASSEMBLY DOT 3HT 1850 OR DOT 3FC1850 OR MANUFACTURED UNDER DOT-SP-8162. Hydro Check Date: 01-Jul-2021	YPAD		176176-64 808777	MTH 01-Jul-2021		36		31-Jul-2024	-23 m 24 d **Over Due**
710000 E1	TURBINE WASH	YPAD			MTH 01-Jul-2021 HRS 13322.6 LDG 10796		A/R			
710000 E2	TURBINE WASH	YPAD			MTH 01-Jul-2021 HRS 13322.6 LDG 10796		A/R			
710010 E1	OVERHAUL				MTH 10-Jul-2008 HRS 9998.8		3500		13498.8	116.1

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
710010 E2	OVERHAUL				MTH HRS	10-Jul-2008 10170.6		 3500		 13670.6	 287.9
710020 E1	HOT SECTION INSPECTION	CEL			HRS	11748.2		1750		13498.2	115.5
710020 E2	HOT SECTION INSPECTION	CEL			HRS	11970.8		1750		13720.8	338.1
710030 E1	INSPECT INTERMEDIATE CASE FOR CORROSION				MTH			A/R			
710030 E2	INSPECT INTERMEDIATE CASE FOR CORROSION				MTH			A/R			
710040 E1	APPLYING CORROSION-INHIBITING COMPOUNDS				MTH	30-Sep-1986		A/R			
710040 E2	APPLYING CORROSION-INHIBITING COMPOUNDS				MTH	08-May-1985		A/R			
720010 E1	OIL ANALYSIS				MTH	30-Sep-1986		A/R			
720010 E2	OIL ANALYSIS				MTH	08-May-1985		A/R			
731025 E1	VISUALLY INSPECT FUEL-OIL COOLER	YPAD		3015303 2476	MTH HRS LDG	01-Jul-2021 13322.6 10796		A/R			
731025 E2	VISUALLY INSPECT FUEL-OIL COOLER	YPAD		3015303 3050	MTH HRS LDG	01-Jul-2021 13322.6 10796		A/R			
731035 E1	VISUALLY INSPECT MOTIVE FLOW VALVE	YPAD		 2524995-1 A90619	MTH HRS LDG	01-Jul-2021 13322.6 10796		A/R			
731035 E2	VISUALLY INSPECT MOTIVE FLOW VALVE			 2524995 A90372	MTH	08-May-1985		A/R			
731090 E1	VISUALLY INSPECT FLOW DIVIDER VALVE			 25607-2 1991	MTH	30-Sep-1986		A/R			
731090 E2	VISUALLY INSPECT FLOW DIVIDER VALVE			 25607-2 3075	MTH	08-May-1985		A/R			
741030 E1 LOWER	VISUAL INSPECT IGNITION EXCITER	YPAD		NB01201 U4331	MTH HRS LDG	01-Jul-2021 13322.6 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9 **Over Due**
741030 E1 UPPER	VISUAL INSPECT IGNITION EXCITER	YPAD		NB01201 W5418	MTH HRS LDG	01-Jul-2021 13322.6 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9 **Over Due**
741030 E2 LOWER	VISUAL INSPECT IGNITION EXCITER	YPAD		NB01201 SN-UNKNOWN	MTH HRS LDG	01-Jul-2021 13322.6 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9 **Over Due**
741030 E2 UPPER	VISUAL INSPECT IGNITION EXCITER	YPAD		NB01201 SN-UNKNOWN	MTH HRS LDG	01-Jul-2021 13322.6 10796		24 300		31-Jul-2023 13622.6	-35 m 24 d 239.9 **Over Due**

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Maintenance Inspections

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
770010	INSPECT T1 PROBE THERMOCOUPLE HARNESS FOR DAMAGE OR PROBES TOUCHING EACH OTHER										
E1					MTH	30-Sep-1986		24		31-Jul-2023	-35 m 24 d
					HRS	2992.5		300		13622.6	239.9
											Over Due
770010	INSPECT T1 PROBE THERMOCOUPLE HARNESS FOR DAMAGE OR PROBES TOUCHING EACH OTHER										
E2					MTH	08-May-1985		24		31-Jul-2023	-35 m 24 d
					HRS	3193.9		300		13622.6	239.9
											Over Due
792010	CHANGE OIL	CEL			MTH	30-Mar-2010		O/C			
E1					HRS	10726.5					
792010	CHANGE OIL	CEL			MTH	30-Mar-2010		O/C			
E2					HRS	10897.9					
792020	INSPECT/CLEAN OR REPLACE OIL FILTER ELEMENT				MTH	01-Jul-2021					
E1		YPAD			HRS	13322.6		200		13522.6	139.9
					LDG	10796					
792020	INSPECT/CLEAN OR REPLACE OIL FILTER ELEMENT				MTH	01-Jul-2021					
E2		YPAD			HRS	13322.6		200		13522.6	139.9
					LDG	10796					

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
211002	EMERGENCY PRESSURIZATION VALVE			27441482-06	MTH	04-Apr-1997		O/C			
		CMH		10AM76	HRS	8214			0		
212002	AVIONICS COOLNG FAN --			19A608	MTH	08-Apr-1991		O/C			
		CMH		R3562	HRS	2428			0		
212003	BLOWER	MCO		19A2338	MTH	13-Oct-1993		O/C			
	9912070-1			694	HRS	4713			0		
212004	CABIN OVERHEAD FAN			BC61A-901-2	MTH	04-Aug-2017					
	9912323-2	YBSU		615A	HRS	13312.4		1000	0	14312.4	929.7
					LDG	10788					
212005	CABIN DIVIDER BLOWER			WS2107F30	MTH	13-Mar-1986		O/C			
LEFT	5515129-4	*CF		SN-UNKNOWN							
212005	CABIN DIVIDER BLOWER			WS2107F30	MTH	13-Mar-1986		O/C			
RIGHT	5515129-4	*CF		SN-UNKNOWN							
212009	CABIN UNDERFLOOR ACTUATOR			NYLC50466	MTH	13-Mar-1986		O/C			
		*CF		655							
212010	DOOR ACTUATOR MOTOR ASSY			5A3032	MTH	13-Mar-1986		O/C			
	9910059-3	*CF		SN-UNKNOWN							
212027	DEFOG FAN	ODE		5703-4	MTH	02-Apr-2004					
212006				1359	HRS	10156		3500	0	13656	273.3
213001	CABIN PRESS INDICATOR			C668511-0102	MTH	13-Mar-1986		O/C			
	3001J14	*CF		13229							
213002	OUTFLOW VALVE CONTROLLER			130356-15	MTH	03-Jul-1998		O/C			
		LUK		108222	HRS	9124			4730		
213003	CABIN RATE OF CLIMB INDICATOR			C668513-0101	MTH	13-Mar-1986		O/C			
	35060-1128	*CF		W13119H							
213007	OUTFLOW VALVE	CMH		103576-36	MTH	24-May-1993		O/C			
LEFT				741537	HRS	4313			0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
213007 RIGHT	OUTFLOW VALVE	CMH		103576-36 741538	MTH HRS	24-May-1993 4313		O/C	 0		
213009 LEFT	BLEED AIR FLOW CONTROL VALVE	YBSU	I	1988-00-1 0480	MTH HRS LDG	16-Feb-2022 13345.4 10814		O/C			
213009 RIGHT	BLEED AIR FLOW CONTROL VALVE	MCO		1988-00-1 273	MTH HRS	14-Dec-1995 6819		O/C	 0		
213013	PNUEMATIC RELAY	*CF		130358-1 1141995	MTH	13-Mar-1986		O/C			
215001	REFRIGERATION PACKAGE 9912069-25	LUK		782343-1 851222	MTH HRS	09-Oct-1997 8698		O/C	 0		
215004	ENVIRONMENT CONTROL UNIT (HAMILTON STANDARD) 9912069-1	*CF		738384-26P1 850772	MTH HRS	13-Mar-1986 0		5000	0	5000	-8382.7
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.											**Over Due**
215005	BYPASS VALVE 9912069-1	ICT		754751-2 86111287	MTH HRS	20-Jun-1997 8398		O/C	 0		
215015	COMPRESSOR DRIVE MOTOR			PN SN-UNKNOWN	MTH	13-Mar-1986		O/C	0		
215027	ACM OVER HEAT SWITCH --	CMH		746833-1 488	MTH HRS	21-Sep-1996 7653		O/C	 0		
216002	TEMP CONTROL UNIT 9912069-22	*CF		754661-5 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
216003	DUCT TEMP SENSOR 9912069-14	ICT		754691-1 88704328	MTH HRS	31-May-1989 1213		O/C	 0		
216004	CABIN TEMP SENSOR 9912069-15	*CF		754681-1 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
216005	CENTRIFUGAL BLOWER	*CF		3A1003-10 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
221008	AUTOPILOT COMPUTER SP-200	CMH		4008519-945 85033926	MTH HRS	28-Jul-1997 8493		O/C	 1653		
221009	AUTOPILOT CONTROLLER PC-500	CMH		4018639-909 85022582	MTH HRS	02-Aug-1993 4496		O/C	 0		
221010 AFT	AILERON AUTOPILOT SERVO SM-200	ICT		4006719-906 81016503	MTH HRS	13-Jun-1989 1231		O/C	 0		
221010 FORWARD	ELEVATOR AUTOPILOT SERVO SM-200	*CF		4006719-914 85092215	MTH	13-Mar-1986		O/C			
221010 MID	RUDDER AUTOPILOT SERVO SM-200	*CF		4006719-906 85082127	MTH	13-Mar-1986		O/C			
230010 *237001*	COCKPIT VOICE RECORDER GA-100	MGL		GA100-0000 01561	MTH HRS	21-Jan-2010 11325		O/C	 0		
230017 *237010*	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON 266-E0305-00			DK120 DU2876	MTH HRS LDG	13-Jan-2015 13246.37 10731		72	0	28-Feb-2025	-16 m 24 d **Over Due**

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
232002 NO. 2	COMM ANTENNA	*CF		VFS10-108-1 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
232003 NO. 1	COMM ANTENNA	SAT		VFS10-90-7 455	MTH HRS	12-Jun-1999 9403		O/C	 0		
232004	AIRBIRNE COMMUNICATION TRANSCEIVER RT-18E	ICT		400-0125 600	MTH HRS	26-Oct-1988 925		O/C	 0		
232005 CABIN	CONTROL PHONE	CMH		400-0123-113 7473	MTH HRS	23-Jun-1995 6396		O/C	 0		
232007	AIRBORNE COMMUNICATION ANTENNA	MKE		50-95-01 2691	MTH HRS	03-Mar-1995 6000		O/C	 0		
232010 BOTTOM	NO.2 COMM TRANSCEIVER VHF-22C	FXE		822-1113-001 36143	MTH HRS	17-Aug-2006 10545		O/C	 1142		
232010 TOP	NO.1 COMM TRANSCEIVER	MGL		011-00864-10 85800120	MTH HRS LDG	09-Nov-2011 12377 10145		O/C			
232011 LEFT	COMM CONTROL CTL-22C	SAT		822-1120-005 20684	MTH HRS	08-Jul-1999 9403		O/C	 0		
235001 LEFT	AUDIO AMPLIFIER	MGL		5640-1 490	MTH HRS	27-Oct-2009 11259		O/C	 204		
235001 RIGHT	AUDIO AMPLIFIER	MGL		5640-1 678	MTH HRS	27-Oct-2009 11259		O/C	 1124		
237006	REMOTE MIKE --	CMH		93-A055-95 68	MTH HRS	14-Mar-1991 2423		O/C	 0		
237009	CVR INERTIA SWITCH --	BNE		3LO-453/3 L4728	MTH HRS LDG	16-Nov-2017 13315.6 10794		O/C	0 0		
242001 BOTTOM	NO.2 AC INVERTER	MGL		9914254-1 1690	MTH HRS LDG	01-Jun-2011 12079 9976		O/C			
242001 TOP	NO.1 AC INVERTER	MGL		9914254-1 787	MTH HRS LDG	01-Jun-2011 12079 9976		O/C			
243001 LEFT	STARTER/GENERATOR 9912125-4	MGL		23085-004 92068	MTH HRS	11-Jun-2012 12656		1000	0	13656	273.3
243001 RIGHT	STARTER/GENERATOR	MGL		9912125-4 95067	MTH HRS LDG	03-Feb-2012 12480 10203		1000	0	13480	97.3
243003 LEFT	GENERATOR CONTROL UNIT 9912039-6	DLN		51539-006F 2416A	MTH HRS	25-Jan-2008 10881		O/C	 0		
243003 RIGHT	GENERATOR CONTROL UNIT 9912039-6	DLN		51539-006F 7061A	MTH HRS	25-Jan-2008 10881		O/C	 0		
243004 LEFT	AMMETER	LUK		C662501-0104 1099	MTH	14-Aug-1997		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
243004 RIGHT	AMMETER	SWF		153LA30C 438	MTH HRS	13-Jul-1995 6467		O/C	 0		
243005	VOLTMETER	*CF		C662502-0101 1412	MTH	13-Mar-1986		O/C			
243007	BATTERY -			ATSP-44 10100104	MTH HRS LDG	03-Jul-2013 13024 10576		O/C			
243008	BATTERY TEMPERATURE MODULE	KIA		1529-1 289	MTH HRS	10-May-1995 6240		O/C	 0		
243009	BATTERY TEMPERATURE GAGE	LUK		1229-1 112595	MTH HRS	06-May-1996 7200		O/C	 273		
243010	OVR HEAT TEMP SENSOR --	*CF		1166-1 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
243011	CURRENT VOLTAGE CONTROLLER	YBSU		1301-1 918A	MTH HRS LDG	11-Jan-2016 13282.8 10746		O/C			
243012	CURRENT SENSOR	CMH		1302-1 1318A	MTH HRS	25-Apr-1993 4209		O/C	 0		
243013	BATT DISCONNECT K69 RELAY	*CF		A876K SN-UNKNOWN	MTH	13-Mar-1986		O/C			
243014 *243010*	BATTERY TEMPERATURE SENSOR	*CF		1166-1 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
243015 *243010 : G*	TEMPERATURE SENSOR GAGE	*CF		1166-1 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
245001 CENTER	5 VOLT LIGHT DIMMER	MCO		273-1 3408	MTH HRS	14-Dec-1995 6819		O/C	 0		
245001 LEFT	5 VOLT LIGHT DIMMER	CMH		1505-1 4300	MTH HRS	16-Nov-1992 3781		O/C	 0		
245001 RIGHT	5 VOLT LIGHT DIMMER	MGL	A	273-1 3652	MTH HRS LDG	19-Apr-2010 11487 9632		O/C			
245002	BAROMETRIC PRESSURE SWITCH 9910095-6	MKE		GB300NA161 9430674	MTH HRS	03-Mar-1995 6000		O/C	 0		
245003 LEFT	START K7 RELAY	CMH		A703C CE84756	MTH HRS	15-Jan-1990 1473		O/C	 0		
245003 RIGHT	START K8 RELAY	*CF		A703C SN-UNKNOWN	MTH	13-Mar-1986		O/C			
245004 LEFT	POWER K13 RELAY	*CF		A703P SN-UNKNOWN	MTH	13-Mar-1986		O/C			
245004 RIGHT	POWER K12 RELAY	*CF		A703P SN-UNKNOWN	MTH	13-Mar-1986		O/C			
252012	LIFE RAFT --	FXE		1400-1 7541ES	MTH HRS	20-Dec-2005 10376		O/C	0		
256002	LOCATOR BEACON TRANSMITTER	YMEN		453-5000-218 09127	MTH HRS LDG	24-Sep-2015 13279.9 10742		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
256003	REPLACE LOCATOR BEACON TRANSMITTER BATTERY				MTH	01-Jul-2021		60	0	30-Apr-2025	-14 m 24 d
	C406-2	YPAD		452-0133	HRS	13322.6			0		
				SN-UNKNOWN	LDG	10796			0		
											Over Due
261001 LEFT	ENGINE FIRE DETECTOR SENSOR			244-18882	MTH	13-Mar-1986		O/C			
	9912036-3	*CF		SN-UNKNOWN							
261001 RIGHT	ENGINE FIRE DETECTOR SENSOR			244-18882	MTH	13-Mar-1986		O/C			
	9912036-3	*CF		SN-UNKNOWN							
261002 LEFT	FIRE DETECTION CONTROL UNIT			377-02808	MTH	13-Mar-1986		O/C			
	9912036-2	*CF		8509012							
261002 RIGHT	FIRE DETECTION CONTROL UNIT			377-02808	MTH	13-Mar-1986		O/C			
	9912036-2	*CF		8509008							
262001 AFT	ENGINE FIRE EXTINGUISHER			32700015	MTH	05-Apr-2023		O/C	98		
	9912048-3	UNK		13022C1	HRS	13357.9			111.53		
					LDG	10821			90		
262001 FORWARD	ENGINE FIRE EXTINGUISHER			32700015	MTH	05-Apr-2023		O/C	101		
	9912048-3	UNK		16796C1	HRS	13357.9					
					LDG	10821					
262002 AFT	PORTABLE FIRE EXTINGUISHER			B385TS	MTH	04-Aug-2017		O/C	68		
		YBSU		X67110	HRS	13312.4					
					LDG	10788					
262002 FORWARD	PORTABLE FIRE EXTINGUISHER			B385TS	MTH	04-Aug-2017		O/C	41		
		YBSU		Y-549288	HRS	13312.4					
					LDG	10788					
262101 AFT LEFT *262003 : AL*	FIRE EXTINGUISHER CARTRIDGE			13083-5	MTH	01-Jul-2021		72	37	31-May-2024	-25 m 24 d
		YPAD		SN-UNKNOWN	HRS	13322.6					
					LDG	10796					**Over Due**
Manufacture Date: 31-May-2018											
262101 AFT RIGHT *262003 : AR*	FIRE EXTINGUISHER CARTRIDGE			13083-5	MTH	01-Jul-2021		72		31-Jul-2027	12 m 7 d
		YPAD		SN-UNKNOWN	HRS	13322.6			0		
					LDG	10796			0		
Manufacture Date: 01-Jul-2021											
262101 FORWARD LEFT *262003 : FL*	FIRE EXTINGUISHER CARTRIDGE			13083-5	MTH	01-Jul-2021		72	37	31-May-2024	-25 m 24 d
		YPAD		SN-UNKNOWN	HRS	13322.6					
					LDG	10796					**Over Due**
Manufacture Date: 31-May-2018											
262101 FORWARD RIGHT *262003 : FR*	FIRE EXTINGUISHER CARTRIDGE			13083-5	MTH	01-Jul-2021		72	19	30-Nov-2025	-7 m 24 d
		YPAD		SN-UNKNOWN	HRS	13322.6					
					LDG	10796					**Over Due**
Manufacture Date: 30-Nov-2019											
271001	AILERON TRIM TAB ACTUATOR			6660361-25	MTH	01-Jun-2011		O/C	0		
		MGL		NA	HRS	12079			0		
					LDG	9976					
272001	RUDDER TRIM TAB ACTUATOR			5565450-63	MTH	13-Mar-1986		O/C			
	5565450-53	*CF		SN-UNKNOWN							
273002	ELECTRIC ELEVATOR TRIM ACTUATOR				MTH	04-Oct-1996		O/C			
		GSO	2	44430-3657	HRS	7682			0		
				T394							
273003 LEFT	ELEVATOR TRIM TAB ACTUATOR			5565450-79	MTH	31-May-1989		O/C			
		ICT		1-79	HRS	1213			0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
273003 RIGHT	ELEVATOR TRIM TAB ACTUATOR 5565450-80	 *CF		5565450-80 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
275003 LEFT	FLAP ACTUATOR 9912007-1	YPAD		55800-1 -	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	0 0		
275003 RIGHT	FLAP ACTUATOR 9912007-1	*CF		55800-1 243	MTH	13-Mar-1986		O/C			
275004 LEFT WING LEFT INBOARD	-AFT FLAP ROLLER	FXE		CC50380 SN-UNKNOWN	MTH HRS LDG	23-Aug-2006 10545 8755		5000	0	13755	2911
275004 LEFT WING LEFT OUTBOARD	-AFT FLAP ROLLER	ODE		CC50380 SN-UNKNOWN	MTH HRS LDG	02-Apr-2004 10156 8464		5000	0	13464	2620
275004 LEFT WING RIGHT INBOARD	-AFT FLAP ROLLER	ODE		CC50380 SN-UNKNOWN	MTH HRS LDG	02-Apr-2004 10156 8464		5000	0	13464	2620
275004 LEFT WING RIGHT OUTBOARD	-AFT FLAP ROLLER	ODE		CC50380 SN-UNKNOWN	MTH HRS LDG	02-Apr-2004 10156 8464		5000	0	13464	2620
275004 RIGHT WING LEFT INBOARD	-AFT FLAP ROLLER	ODE		CC50380 SN-UNKNOWN	MTH HRS LDG	02-Apr-2004 10156 8464		5000	0	13464	2620
275004 RIGHT WING LEFT OUTBOARD	-AFT FLAP ROLLER	FXE		CC50380 SN-UNKNOWN	MTH HRS LDG	23-Aug-2006 10545 8755		5000	0	13755	2911
275004 RIGHT WING RIGHT INBOARD	-AFT FLAP ROLLER	ODE		CC50380 SN-UNKNOWN	MTH HRS LDG	02-Apr-2004 10156 8464		5000	0	13464	2620
275004 RIGHT WING RIGHT OUTBOARD	-AFT FLAP ROLLER	ODE		CC50380 SN-UNKNOWN	MTH HRS LDG	02-Apr-2004 10156 8464		5000	0	13464	2620
276001 LEFT	SPEED BRAKES ACTUATOR 6527550-1	 *CF		50115-1 63	MTH	13-Mar-1986		O/C			
276001 RIGHT	SPEED BRAKES ACTUATOR 6527550-1	 *CF		50115-1 272	MTH	13-Mar-1986		O/C			
282001 LEFT	MOTOR DRIVEN FUEL PUMP 9912017-2	 ICT		1C7-12 2AN0000Z1	MTH HRS	23-Jun-1997 8401		O/C	 0		
282001 RIGHT	MOTOR DRIVEN FUEL PUMP 9912017-2	 *CF		1C7-12 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
284001 LEFT	LOW LEVEL FUEL SWITCH	 ICT		L15H-3 989	MTH HRS	20-Jun-1997 8398		O/C	 0		
284001 RIGHT	LOW LEVEL FUEL SWITCH	 ICT		L15H-3 5007	MTH HRS	20-Jun-1997 8398		O/C	 0		
284002 LEFT	FUEL QUANTITY COMPENSATOR 9912019-4	 *CF		300047-13001 14975R	MTH	13-Mar-1986		O/C			
284002 RIGHT	FUEL QUANTITY COMPENSATOR 9912019-4	 *CF		300047-13001 15424R	MTH	13-Mar-1986		O/C			
284007	FUEL QUANTITY INDICATOR 9912147-12	 MGL		VSDL-OC403D-1 223	MTH HRS	27-Oct-2009 11259		O/C	 0		
291001	HYDRAULIC RESERVOIR ASSEMBLY 9912052-12			40500-7 882	MTH HRS	24-Jan-2000 9587		O/C	 0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
291002 LEFT	ENGINE HYDRAULIC PUMP 9912062-3	*CF		4120-004000 80	MTH	13-Mar-1986		O/C			
291002 RIGHT	ENGINE HYDRAULIC PUMP 9912062-3	*CF		4120-004000 85	MTH	13-Mar-1986		O/C			
291005 LEFT	HYDRAULIC W/FLOW DETECTOR CHECK VALVE 9912194-3	*CF		3520020100-4 2116	MTH	13-Mar-1986		O/C			
291005 RIGHT	HYDRAULIC W/FLOW DETECTOR CHECK VALVE 9912194-3	*CF		3520020100-4 2106	MTH	13-Mar-1986		O/C			
291007 LEFT	HYDRAULIC FIREWALL SHUTOFF VALVE	*CF		149145 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
291007 RIGHT	HYDRAULIC FIREWALL SHUTOFF VALVE	*CF		149145 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
291012	HYDRAULIC BY-PASS VALVE -	*CF		2710971 768	MTH	13-Mar-1986		O/C			
301001 AFT	ANTI-ICE PUMP	HPN		XA9511C010 L11484	MTH HRS	07-Nov-1996 7757		O/C	0		
301001 FORWARD	ANTI-ICE PUMP	TOL		XA9511C005 C29585	MTH HRS	24-Nov-1996 7825		O/C	0		
301002 LEFT	LOW PRESSURE SWITCH	*CF		PO67B078 T55984	MTH	13-Mar-1986		O/C			
301002 RIGHT	LOW PRESSURE SWITCH	HPN		PO67B078 J7486	MTH HRS	07-Nov-1996 7757		O/C	0		
301003	ANTI-ICE TANK ASSY	*CF		6514007-5 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
301004	ANTI-ICE FLUID INDICATOR	TOL		19-435-04 SN-UNKNOWN	MTH HRS	17-Aug-1992 3627		O/C	0		
301005 LEFT	SURF SOLENOID VALVE	*CF		FV137 H11285	MTH	13-Mar-1986		O/C			
301005 RIGHT	SURF SOLENOID VALVE	*CF		FV137 H12185	MTH	13-Mar-1986		O/C			
301005	SOLENOID VALVE	*CF		FV137 H11985	MTH	13-Mar-1986		O/C			
301006 LEFT INBOARD	HORIZONTAL STABILIZER PANEL	*CF		D3717 853K17	MTH	13-Mar-1986		O/C			
301006 LEFT OUTBOARD	HORIZONTAL STABILIZER PANEL	FXE		D3715 SN-UNKNOWN	MTH HRS	23-Aug-2006 10545		O/C	0		
301006 RIGHT INBOARD	HORIZONTAL STABILIZER PANEL	*CF		D3718 853L18	MTH	13-Mar-1986		O/C			
301006 RIGHT OUTBOARD	HORIZONTAL STABILIZER PANEL	*CF		D3716 853G16	MTH	13-Mar-1986		O/C			
301007 LEFT NO.1	WING PANEL	*CF		D3709 851X9	MTH	13-Mar-1986		O/C			
301007 LEFT NO.2	WING PANEL	*CF		D3731 852C7	MTH	13-Mar-1986		O/C			
301007 LEFT NO.3	WING PANEL	*CF		D3729 852C5	MTH	13-Mar-1986		O/C			
301007 LEFT NO.4	WING PANEL	*CF		D3703 852B3	MTH	13-Mar-1986		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
301007 LEFT NO.5	WING PANEL	*CF		D3701 851U1	MTH	13-Mar-1986		O/C			
301007 RIGHT NO.1	WING PANEL	*CF		D3710 853L10	MTH	13-Mar-1986		O/C			
301007 RIGHT NO.2	WING PANEL	*CF		D3732 852G8	MTH	13-Mar-1986		O/C			
301007 RIGHT NO.3	WING PANEL	*CF		D3730 852G6	MTH	13-Mar-1986		O/C			
301007 RIGHT NO.4	WING PANEL	*CF		D3704 851Y4	MTH	13-Mar-1986		O/C			
301007 RIGHT NO.5	WING PANEL	*CF		D3702 852A2	MTH	13-Mar-1986		O/C			
301008 LEFT	FAIRING PANEL	*CF		D3714 851Y14	MTH	13-Mar-1986		O/C			
301008 RIGHT	FAIRING PANEL	*CF		D3713 852D13	MTH	13-Mar-1986		O/C			
301009 LEFT	SURF PROPORTIONER	MCO		PU306DW38 L9685	MTH HRS	20-Mar-1987 568		O/C	0		
301009 RIGHT	SURF PROPORTIONER	*CF		PU306DW38 E9885	MTH	13-Mar-1986		O/C			
301010	ENGINE PROPORTIONER	TOL		PU306DC62 T61783	MTH HRS	17-Aug-1992 3627		O/C	0		
301011	HOR/STB PROPORTIONER	LUK		PU306DT41 H6287	MTH HRS	09-Aug-1998 9202		O/C	0		
301012	ICE DETECTOR			871DN1 204	MTH HRS	16-Jun-2000 9733		O/C	0		
301013 *301016*	SURF PUMP CHECK VALVE	*CF		FV121 T50284	MTH	13-Mar-1986		O/C			
301014 LEFT	FAIRING PANEL PRESSURE SWITCH	*CF		PO67L025 K6385	MTH	13-Mar-1986		O/C			
301014 LEFT INBOARD	FAIRING PANEL PRESSURE SWITCH	*CF		PO67L025 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
301014 RIGHT	FAIRING PANEL PRESSURE SWITCH	MCO		PO67L015 B27485	MTH HRS	21-Mar-1992 3201		O/C	0		
301014 RIGHT INBOARD	FAIRING PANEL PRESSURE SWITCH	*CF		PO67L025 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
301016 LEFT	WING PANEL PRESSURE SWITCH	CMH		PO67LC035 D985	MTH HRS	16-Nov-1992 3781		O/C	1341		
301016 RIGHT	WING PANEL PRESSURE SWITCH	*CF		PO67LC050 K7285	MTH	13-Mar-1986		O/C			
301017 LEFT INBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH	*CF		PO67L015 J4285	MTH	13-Mar-1986		O/C			
301017 LEFT OUTBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH	*CF		PO67L015 J4185	MTH	13-Mar-1986		O/C			
301017 RIGHT INBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH	*CF		PO67L015 J4985	MTH	13-Mar-1986		O/C			
301017 RIGHT OUTBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH	*CF		PO67L015 J40585	MTH	13-Mar-1986		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
301018 *301015 : PUMP*	ENGINE PUMP CHECK VALVE	*CF		FV147 J10085	MTH	13-Mar-1986		O/C			
301019 LEFT	SURF TEE CHECK VALVE	*CF		FV147 J8185	MTH	13-Mar-1986		O/C			
301019 RIGHT	SURF TEE CHECK VALVE	*CF		FV147 J8585	MTH	13-Mar-1986		O/C			
301020	SURF INBD CHECK VALVE	*CF		FV147 J8985	MTH	13-Mar-1986		O/C			
301021	SURF TO ENGINE CHECK VALVE	*CF		FV147 J8785	MTH	13-Mar-1986		O/C			
302003 LEFT	ENGINE BLEED AIR VALVE 9912086-3	SWF		229715-1 1290	MTH HRS	23-Jul-1996 7415		O/C	0		
302003 RIGHT	ENGINE BLEED AIR VALVE 9912086-3	LUK		229715-1 199	MTH HRS	06-May-1996 7200		O/C	0		
302004 LEFT	ANTI ICE TEMP SWITCH	*CF		21548-2-19-6 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
302004 RIGHT	ANTI ICE TEMP SWITCH	*CF		21548-2-19-6 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
303001 LEFT	PITOT TUBE	FXE		PH502 SN-UNKNOWN	MTH HRS	18-May-2005 10261		O/C	0		
303001 RIGHT	PITOT TUBE	FXE		PH502 SN-UNKNOWN	MTH HRS	18-May-2005 10261		O/C	0		
303002 LEFT	PILOT STATIC PORT	*CF		CM2933-7 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
303002 RIGHT *303003 : RT*	CO-PILOT STATIC PORT	*CF		CM2933-7 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
303003 LEFT	CO-PILOT STATIC PORT	*CF		CM2933-7 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
303003 RIGHT *303002 : RB*	PILOT STATIC PORT	*CF		CM2933-7 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
304001	HOT AIR TEMPERATURE MONITOR- 5514120	FXE		1169-1 551	MTH HRS	29-Jul-2005 10277		O/C	8102		
304002	HEAT EXCHANGER 9912041-4	*CF		10663A 235	MTH	13-Mar-1986		O/C			
304005	TEMPERATURE CONTROL VALVE 9912085-1	*CF		27241287 12M138	MTH	13-Mar-1986		O/C			
304006	TEMPERATURE CONTROLLER 9912085-2	*CF		27231272 6AA0050	MTH	13-Mar-1986		O/C			
304009	WINDSHIELD BLEED AIR VALVE 9912086-2	LUK		226395-1 1276	MTH HRS	13-Jun-1996 7287		O/C	0		
312001 RIGHT	CLOCK	UNK		811B-24A 11652	MTH HRS LDG	02-Dec-2022 13355.2 10819		O/C			
312002 LEFT	CLOCK BATTERY	UNK		811-BATT-1 N/A	MTH HRS LDG	02-Dec-2022 13355.2 10819		36	0	31-Dec-2025	-6 m 24 d **Over Due**

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
312002 RIGHT	CLOCK BATTERY	UNK		811-BATT-1 N/A	MTH HRS LDG	02-Dec-2022 13355.2 10819		36	0	31-Dec-2025	-6 m 24 d Over Due
312003 LEFT *312001 : L*	DIGITAL CLOCK	CMH		811B24A 31506	MTH HRS	11-Sep-1996 7608		O/C	0		
313001	FLIGHT HOURMETER 85071	CMH		C664503-0104 SN-UNKNOWN	MTH HRS	11-Oct-1993 4711		O/C	0		
313003	ACCELEROMETER AG-222	*CF		7000992 4639	MTH	13-Mar-1986		O/C			
313014	FLIGHT DATA RECORDER	YMEN		S703-1000-00 001034663	MTH HRS LDG	24-Sep-2015 13279.9 10742		O/C			
313105	FLIGHT DATA RECORDER UNDERWATER LOCATOR BEACON	MGL		DK100 DR3453	MTH HRS LDG	11-Oct-2010 11820 9816		O/C	0 0 0		
321001 LEFT	MAIN LANDING GEAR ASSY 6641000	*CF		6641000-3 S0087	MTH LDG	13-Mar-1986 0		25800	0	25800	14956
321002 RIGHT	MAIN LANDING GEAR ASSY 6641000	*CF		6641000-4 S0087	MTH LDG	13-Mar-1986 0		25800	0	25800	14956
321003 LEFT MAIN LANDING GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH LDG	13-Mar-1986 0	2156	21500	2156	21500	10656
321003 RIGHT MAIN LANDING GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH LDG	13-Mar-1986 0	2156	21500	2156	21500	10656
322001	NOSE LANDING GEAR ASSY 6642000-2	*CF		6642000-2 1	MTH LDG	13-Mar-1986 0		23900	0	23900	13056
322002	NOSE GEAR SHIMMY DAMPER	TOL		5543001-3 1421	MTH HRS LDG	12-Dec-1986 442 370		O/C	0		
322004	NOSE LANDING GEAR FORK	SAT		5542300-2 SN-UNKNOWN	MTH HRS LDG	12-Jun-1999 9403 7929		13800	0	21729	10885
322005	NOSE GEAR ACTUATOR FITTING	*CF		5511169-1 SN-UNKNOWN	MTH LDG	13-Mar-1986 0		23900	0	23900	13056
322006 LEFT	NOSE GEAR TRUNNION SUPPORT ASSEMBLY 5513056-5	MKE		6613056-1 SN-UNKNOWN	MTH HRS LDG	03-Mar-1995 6000 5208		11600	0	16808	5964
322006 RIGHT	NOSE GEAR TRUNNION SUPPORT ASSEMBLY 5513056-5	MKE		6613056-2 SN-UNKNOWN	MTH HRS LDG	03-Mar-1995 6000 5208		11600	0	16808	5964
322007	NOSE GEAR TRUNNION	*CF		5542301-9 SN-UNKNOWN	MTH LDG	13-Mar-1986 0		23900	0	23900	13056
322008	NOSE LANDING GEAR PISTON WELD ASSEMBLY	*CF		6642100-2 SN-UNKNOWN	MTH LDG	13-Mar-1986 0		13800	0	13800	2956
323001 LEFT MAIN LANDING GEAR	SIDE BRACE ACTUATOR 9912111-3	EDLN		1523100-7 432B	MTH HRS LDG	07-Feb-2012 12480 10203		25800	5167	30836	19992
323002 RIGHT MAIN LANDING GEAR	SIDE BRACE ACTUATOR 9912111-2	CMH		2-7442-4 DA1313	MTH HRS LDG	28-Mar-1993 4127 3670		25800	0	29470	18626

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
323003	ACTUATOR	UNK		1523200-5	MTH	05-Apr-2023					
NOSE LANDING GEAR	9912120-2			1209	HRS	13357.9			205		
					LDG	10821		23900	406	34315	23471
323004	LANDING GEAR UPLOCK ACTUATOR			5527504-2	MTH	02-Aug-1993		O/C			
LEFT	5527500	CMH		432	HRS	4496					
					LDG	3987			0		
323004	LANDING GEAR UPLOCK ACTUATOR			5527504-2	MTH	21-May-2008		O/C			
NOSE	5527500-2	MGL		WMP3656	HRS	11019					
					LDG	9222			0		
323004	LANDING GEAR UPLOCK ACTUATOR			5527504-2	MTH	28-Mar-1993		O/C			
RIGHT	5517000	CMH		58	HRS	4127					
					LDG	3670			0		
323006	EMERGENCY GEAR AIR BOTTLE			212940-2	MTH	01-Jul-2021		288	9	31-Oct-2044	219 m 7 d
	9912103-3	YPAD		-	HRS	13322.6					
					LDG	10796					
Manufacture Date: 31-Oct-2020											
323007	GEAR CONTROL VALVE			66710	MTH	13-Mar-1986		O/C			
		*CF		27							
323008	DUMP VALVE	*CF		AS19400-1	MTH	13-Mar-1986		O/C			
				SN-UNKNOWN							
323019	EMERGENCY AIR BOTTLE GAGE			2341128	MTH	13-Mar-1986		O/C	0		
		*CF		SN-UNKNOWN							
324001	MAIN WHEEL ASSEMBLY			40-202	MTH	04-Aug-2017		O/C	0		
LEFT	9912222-2	YBSU		212/ASI2481	HRS	13312.4			0		
					LDG	10788					
324001	MAIN WHEEL ASSEMBLY			40-202	MTH	28-Mar-2013		O/C			
RIGHT	9912222-2			264	HRS	12903			-11952		
					LDG	10486					
324002	NOSE WHEEL ASSEMBLY			3-1418	MTH	09-Jul-2013		O/C			
	9914069-2			3311	HRS	13027					
					LDG	10580			3201		
324003	BRAKE ASSEMBLY	EDLN		30-161A	MTH	28-Mar-2013		O/C	0		
LEFT				455	HRS	12903			0		
					LDG	10486					
324004	BRAKE ASSEMBLY	EDLN		30-161A	MTH	28-Mar-2013		O/C	0		
RIGHT				ASI1672	HRS	12903			0		
					LDG	10486					
324005	MAIN TIRE	YBSU		220K28-1	MTH	04-Aug-2017		O/C	0		
LEFT				71452665	HRS	13312.4			0		
					LDG	10788					
324005	MAIN TIRE	EDLN		028-700-0	MTH	27-Aug-2013		O/C	0		
RIGHT				2209S00074	HRS	13114			0		
					LDG	10637					
324006	NOSE TIRE	EDLN		184F08-1	MTH	09-Jul-2013		O/C	0		
				73000736	HRS	13027			0		
					LDG	10580					

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
324011 LEFT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-11	*CF		12A085-11 2900	MTH	13-Mar-1986		O/C			
324011 RIGHT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-11	*CF		12A085-11 2903	MTH	13-Mar-1986		O/C			
324012 LEFT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-12	*CF		12A085-12 2950	MTH	13-Mar-1986		O/C			
324012 RIGHT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-12	*CF		12A085-12 2916	MTH	13-Mar-1986		O/C			
324014	EMERGENCY AIR BRAKE VALVE 9912105-1	*CF		53640 713A	MTH	13-Mar-1986		O/C			
324019	BRAKE PRESSURE PUMP ASSY 9912166-2	*CF		634343 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
324020	BRAKE CONTROL BOX	MGL		9912305-06 189A	MTH HRS LDG	01-Jun-2011 12079 9976		O/C			
324021	POWER BRAKE ANTI-SKID VALVE 9912305-7	*CF		38-707-1 269	MTH	13-Mar-1986		O/C			
324023	ACCUMULATOR	*CF		57C57652 165	MTH	13-Mar-1986		O/C			
324024 LEFT	WHEEL TRANSDUCER 9912305-2	EDLN		40-955 1101	MTH HRS LDG	08-Feb-2011 11935 9893		O/C			
324024 RIGHT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 1607	MTH	13-Mar-1986		O/C			
324025	PRESSURE SWITCH 9912163-1	SWF		1206P25 2265	MTH HRS LDG	05-Feb-1997 8089 6864		O/C	 0		
324026	POWER BRAKE ASSEMBLY MOTOR	HOU		30-2 2476	MTH HRS	03-Jan-1997 7993		O/C	 0		
324101	PARKING BRAKE VALVE	*CF		AS20800 1207	MTH	13-Mar-1986		O/C			
325001	BUNGEE ASSEMBLY 5565624-19	*CF		5565624-19 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
326002 LEFT	M/G UP & LOCKED SWITCH	YBSU		65-430087 NSN	MTH HRS LDG	04-Aug-2017 13312.4 10788		O/C	0 0		
326002 RIGHT	M/G UP & LOCKED SWITCH	*CF		65430087 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
326003 LEFT	M/G DOWN & LOCK SWITCH 9912053-13	*CF		1CH106-6 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
326003 RIGHT	M/G DOWN & LOCK SWITCH	N66		602EN16-6B SN-UNKNOWN	MTH HRS LDG	18-Dec-1997 8880 7497		O/C	 0		
326004	N/G DOWN & LOCK SWITCH	*CF		1CH106-6 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
326005	N/G UP&LOCKED SWITCH	*CF		CM3597-1 SN-UNKNOWN	MTH	13-Mar-1986		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
331001	ANNUNCIATOR PANEL --			950D-0240-008	MTH	25-Apr-1993		O/C			
	9912119-8	CMH		187	HRS	4209			0		
331011	EL PANEL-115V INVERTER			EM2044-1	MTH	13-Mar-1986		O/C			
		*CF		705							
332001	INDIRECT LIGHTING POWER UNIT			AL-5112	MTH	07-Dec-1995		O/C			
NO.1		LNN		16178	HRS	6803			0		
332001	INDIRECT LIGHTING POWER UNIT			AL5112	MTH	07-Dec-1995		O/C			
NO.2		LNN		16173	HRS	6803			0		
332001	INDIRECT LIGHTING POWER UNIT			AL5112	MTH	07-Dec-1995		O/C			
NO.3		LNN		16185	HRS	6803			0		
332001	INDIRECT LIGHTING POWER UNIT			AL5112	MTH	07-Dec-1995		O/C			
NO.4		LNN		16175	HRS	6803			0		
332001	INDIRECT LIGHTING POWER UNIT			AL5112	MTH	07-Dec-1995		O/C			
NO.5		LNN		16170	HRS	6803			0		
332001	INDIRECT LIGHTING POWER UNIT			AL5112	MTH	07-Dec-1995		O/C			
NO.6		LNN		16174	HRS	6803			0		
332001	INDIRECT LIGHTING POWER UNIT			AL5112	MTH	07-Dec-1995		O/C			
NO.7		LNN		16169	HRS	6803			0		
332001	INDIRECT LIGHTING POWER UNIT			AL5112	MTH	07-Dec-1995		O/C			
NO.8		LNN		16181	HRS	6803			0		
332002	INDIRECT LIGHTING INVERTER			18.996	MTH	13-Mar-1986		O/C			
AFT		*CF		3360							
332002	INDIRECT LIGHTING INVERTER			18.996-1	MTH	12-Jul-1990		O/C			
FORWARD		CMH		3231	HRS	1838			0		
332003	NO. 1 CAN/AC/12R LIGHTED EXIT SIGN			PN	MTH			72		31-Oct-2029	39 m 7 d
NO. 1				SN-UNKNOWN							
332003	NO. 2 CAN/AC/12R LIGHTED EXIT SIGN			PN	MTH			72		31-Oct-2029	39 m 7 d
NO. 2				SN-UNKNOWN							
332004	NO. 1 CAN/AC/12RGA LIGHTED EXIT SIGN				MTH			72		31-Oct-2029	39 m 7 d
NO. 1				PN							
				SN-UNKNOWN							
332004	NO. 2 CAN/AC/12RGA LIGHTED EXIT SIGN				MTH			72		31-Oct-2029	39 m 7 d
NO. 2				PN							
				SN-UNKNOWN							
334002	VERT FIN ANTI-COLLISION LIGHT ASSEMBLY				MTH	04-Nov-1990		O/C			
		CMH		90033-5	HRS	2071			0		
				998049							
334003	STROBE LIGHT POWER SUPPLY			60-2799-1	MTH	04-Feb-2015		O/C	0		
LEFT	9910368-2			17272	HRS	13246.37			0		
					LDG	10731			0		
334003	STROBE LIGHT POWER SUPPLY			60-2799-1	MTH	04-Feb-2015		O/C	0		
RIGHT	9910368-2			16598	HRS	13246.37			0		
					LDG	10731			0		
334004	STROBE LITE TUBE	CMH		31-3172-11	MTH	21-Nov-1997		O/C			
RIGHT				SN-UNKNOWN	HRS	8812			0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
335001	EMERGENCY BATTERY PACK			24621-3	MTH	01-Jul-2021		O/C	0		
	5518109	YPAD		SN-UNKNOWN	HRS	13322.6			0		
					LDG	10796			0		
341001	AIR SPEED INDICATOR			C661063-0105	MTH	02-Feb-1989		O/C			
LEFT		ICT		181	HRS	1043			0		
341001	AIR SPEED INDICATOR			C661063-0104	MTH	17-Oct-2012		O/C	0		
RIGHT	AW2837AB05	EDLN		178	HRS	12885			0		
					LDG	10478					
341002	ALTIMETER	COU		C661072-0101	MTH	24-Jun-2005		O/C			
STANDBY				W203902	HRS	10265			0		
341004	OAT GAUGE	*CF		C668510-0401	MTH	13-Mar-1986		O/C			
	162BL507D			2154							
341005	OVERSPEED WARNING SWITCH			D2RA45C-24	MTH	27-Jun-2005		O/C			
	9912076-12	COU		134	HRS	10265			0		
341010	AOA INDICATOR	CMH		SLZ9987	MTH	20-Jul-1988		O/C			
				CR1137C	HRS	784			0		
341012	AOA POTENTIOMETER			MOD202-5K	MTH	13-Mar-1986		O/C			
	5518132-1	*CF		SN-UNKNOWN							
341013	AOA TRANSMITTER	CMH		SLZ7306	MTH	20-Jul-1988		O/C			
				LS1074A	HRS	784			0		
341014	AOA TRANSMITTER INDEXER			SLZ9374	MTH	13-Mar-1986		O/C			
		*CF		SN-UNKNOWN							
341019	ALTIMETER	MGL		4016341-905	MTH	11-Oct-2010		O/C			
LEFT	BA-141			N/A	HRS	11820					
					LDG	9816					
341020	V-NAV COMPUTER CONTROL			4020571-904	MTH	24-Jul-1993		O/C			
	VN-212	CMH		83011833	HRS	4496			0		
341021	RADIO ALTIMETER INDICATOR			7000839-903	MTH	13-Mar-1986		O/C			
RIGHT	RA-315	*CF		85043061							
342001	MAGNETIC COMPASS			C2400L4V2W-5B	MTH	24-Sep-2015		O/C			
		YMEN		CE-04140	HRS	13279.9					
					LDG	10742					
342002	TURN AND BANK INDICATOR			C661004-0101	MTH	19-Sep-1998		O/C			
		LUK		880250	HRS	9289			711		
342003	HORIZON GYRO	MGL		C661056-0202	MTH	03-Dec-2009		O/C			
RIGHT	1U149-002-2			A17930H	HRS	11297			0		
342021	VERTICAL SPEED INDICATOR			C661006-0101	MTH	13-Mar-1986		O/C			
LEFT		*CF		W15543H							
342021	VERTICAL SPEED INDICATOR			30260-1117	MTH	05-Nov-1994		O/C			
RIGHT		CMH		SN-UNKNOWN	HRS	5718			0		
342041	FLIGHT DIRECTOR COMPUTER			4018369-905	MTH	11-May-2005		O/C			
	FZ-500	FXE		82063653	HRS	10251			8479		
342042	AP/FD MODE SELECTOR			4020570-905	MTH	13-Mar-1986		O/C			
LEFT		*CF		84011265							

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
342043 LEFT	VERTICAL GYRO VG-14A	MGL		7000622-901 81063000	MTH HRS	19-Feb-2010 11404		O/C	0		
342044 LEFT	RATE GYRO RG-204	*CF		7007453-903 85030283	MTH	13-Mar-1986		O/C			
342047 LEFT	ADI INDICATOR AD-650	MGL		7000466-951 88072775	MTH HRS LDG	19-Apr-2010 11487 9632		O/C			
342048 LEFT *342048I : L*	ADDU INDICATOR	COU		9D-80130-16 47563	MTH HRS	24-Jun-2005 10265		O/C	0		
342048 RIGHT *342048I : R*	ADDU INDICATOR	COU		9D-80130-16 47567	MTH HRS	24-Jun-2005 10265		O/C	0		
342048 STANDBY	ADC/ALTIMETER --	MGL		PN NOT INSTALLED	MTH HRS LDG	11-Oct-2010 11820 9816		O/C			
342048J LEFT	ADDU CONFIGURATION MODULE --	COU		9B-03508-38 45275	MTH HRS	24-Jun-2005 10265		O/C	0		
342048J RIGHT	ADDU CONFIGURATION MODULE --	COU		9B-03508-38 45277	MTH HRS	24-Jun-2005 10265		O/C	0		
342049 LEFT	DIR GYRO SYN COMPASS C-14D	FXE		4020577-3 83103119	MTH HRS	29-Dec-2006 10636		O/C	0		
342049 RIGHT	DIR GYRO SYN COMPASS C-14D	MKE		4020577-3 90114807	MTH HRS	23-Apr-1994 5175		O/C	0		
342050 LEFT	FLUX VALVE FX-220	ICT		2594484 86078806	MTH HRS	12-Sep-1986 344		O/C	0		
342050 RIGHT	FLUX VALVE FX-220	*CF		2594484 673	MTH	13-Mar-1986		O/C			
342052	REMOTE COMPENSATOR CS-412	*CF		2593379-1 85078142	MTH	13-Mar-1986		O/C			
342053 LEFT	HSI INDICATOR RD-650A	SAT		7000469-909 87032332	MTH HRS	12-Jun-1999 9403		O/C	109		
342053 RIGHT	HSI INDICATOR RD-450	CMH		7002493-903 85090569	MTH HRS	05-Nov-1994 5718		O/C	0		
342063	REMOTE HDG CONTROL RI-106	CMH		4026206-923 85082810	MTH HRS	21-May-1995 6277		O/C	206		
342064	STANDBY GYRO POWER SUPPLY PS-835			501-1228-04 13713	MTH HRS LDG	16-Aug-2024 13382.7 10844		O/C			
342065	STAND-BY GYRO AI-804	RNO		501-1197-05 5025	MTH HRS	24-Mar-1998 9103		O/C	0		
342072	JET STATIC CONVERTER	*CF		501-1318-01 2160	MTH	13-Mar-1986		O/C			
344002	RADAR INDICATOR DI-2007	LUK		MI585277-4 4259	MTH HRS	09-Aug-1998 9202		O/C	1524		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
344004	RADAR RECEIVER/TRANSMITTER			MI585222-1	MTH	19-Sep-2011		O/C			
	RT-3002	MGL		3061	HRS	12313					
					LDG	10110					
344005	RADAR ANTENNA	LUK		MI585224-2	MTH	03-Mar-1997		O/C			
	AP-3001			3025	HRS	8140			1588		
344021	TAWS/RMI INDICATOR			ST3400-001	MTH	25-Mar-2011		O/C	5		
LEFT				3780	HRS	12008			188		
					LDG	9945			129		
344021	TAWS/RMI INDICATOR			622-4938-004	MTH	13-Mar-1986		O/C			
RIGHT	RMI-30	*CF		6603							
344022	RADIO ALTIMETER TRANSCEIVER			7001840-905	MTH	13-Mar-1986		O/C			
	RT-300	*CF		85081636							
344023	RADIO ALTM ANTENNA			4010504	MTH	13-Mar-1986		O/C			
AFT	AT-224	*CF		4546							
344023	RADIO ALTM ANTENNA			4010504	MTH	13-Mar-1986		O/C			
FORWARD	AT-224	*CF		4493							
344041	STORMSCOPE DISPLAY			78-8060-5900-9	MTH	11-Oct-2010		O/C			
	WX-1000	MGL		80074	HRS	11820					
					LDG	9816					
344049	BFG SKYWATCH SYSTEM RCVR --			805-11900-001	MTH	11-Oct-2010		O/C			
	SKY-497	MGL		81041	HRS	11820					
					LDG	9816					
344049A	BFG SKYWATCH SYSTEM ANTENNA --			805-10890-001	MTH	11-Oct-2010		O/C			
		MGL		83435	HRS	11820					
					LDG	9816					
345004	TRANSPONDER ANTENNA			DMN150-2	MTH	13-Mar-1986		O/C			
LEFT		*CF		26906							
345004	TRANSPONDER ANTENNA			DMN150-2	MTH	13-Mar-1986		O/C			
RIGHT		*CF		26886							
345007	DME ANTENNA	*CF		DMNI50-2	MTH	13-Mar-1986		O/C			
LEFT				26891							
345007	DME ANTENNA	CMH		DMNI50-2	MTH	12-Jun-1992		O/C			
RIGHT				27882	HRS	3458			0		
345010	NAV ANTENNA	MKE		DMN4-17/P	MTH	03-Mar-1995		O/C			
				6354	HRS	6000			0		
345011	ADF RECEIVER	FXE		622-2362-001	MTH	29-Dec-2006		O/C			
LEFT	ADF-60A			18265	HRS	10636			0		
345011	ADF RECEIVER	FXE		622-2362-001	MTH	29-Dec-2006		O/C			
RIGHT	ADF-60A			1L8VF	HRS	10636			0		
345012	ADF CONTROL	LUK		156MI	MTH	14-Aug-1997		O/C			
RIGHT				1829A							
345012	ADF CONTROL	HRZ		622-6522-005	MTH	23-Feb-2001		O/C			
	CTL-62			8042	HRS	10038			3303		
345014	ADF LOOP ANTENNA			622-2363-001	MTH	21-May-2008		O/C			
LEFT	APA-80	MGL		30888	HRS	11019			0		
345014	ADF LOOP ANTENNA			622-2363-001	MTH	11-Jan-1990		O/C			
RIGHT	APA-80	CMH		22981							

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
345017	MARKER BEACON ANTENNA	*CF		16D00400-2 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
345018	GLIDESCOPE ANTENNA	*CF		RGS1048 9410	MTH	13-Mar-1986		O/C			
345021 NO. 1	RVSM ANALOG INTERFACE UNIT	COU		9B-81040-26 47797	MTH HRS	24-Jun-2005 10265		O/C	 0		
345032 BOTTOM	NO.2 NAVIGATION TRANSCEIVER VIR-32	YMEN		622-6137-201 13657	MTH HRS LDG	24-Sep-2015 13279.9 10742		O/C			
345033 TOP	NAVIGATION NO. 1 CONTROL UNIT CTL-32	COU		622-6521-013 4014	MTH HRS	24-Jun-2005 10265		O/C	 716		
345034 LEFT	TRANSPONDER MST-67A	MGL		066-01143-2101 2295	MTH HRS LDG	11-Oct-2010 11820 9816		O/C	0 0		
345034 RIGHT	TRANSPONDER MST-67A	MGL		066-01143-2101 2296	MTH HRS LDG	11-Oct-2010 11820 9816		O/C	0 0		
345035 LEFT	DME INDICATOR 339F-12B	FXE		622-2175-201 3069	MTH HRS	19-May-2006 10502		O/C	 10502		
345035 RIGHT	DME INDICATOR 339F-12B	LGB		622-2175-201 1366	MTH HRS	14-Jan-1997 8001		O/C	 0		
345036 LEFT	DME INTERROGATOR DME-42	CMH		622-6263-001 3426	MTH HRS	29-Feb-1996 7062		O/C	 3084		
345036 RIGHT	DME INTERROGATOR DME-42	PIM		622-6263-001 4890	MTH HRS	10-Dec-2004 10214		O/C	 0		
345039 NO. 1	CONTROL ADF ADAPTER CAD-62	COU		622-6590-001 6749	MTH HRS	24-Jun-2005 10265		O/C	 0		
345040	TRANSPONDER CONTROL	MGL		071-01619-0121 272	MTH HRS LDG	11-Oct-2010 11820 9816		O/C	0 0 0		
345042	VLF LOOP COUPLER	*CF		11444-1 2722	MTH	13-Mar-1986		O/C			
345053	VLF ANTENNA	*CF		11455-2 1480	MTH	13-Mar-1986		O/C			
345057A	GNS BATTERY PACK --	MGL		10648-1 648	MTH HRS LDG	11-Oct-2010 11820 9816		O/C			
345133	GNS530 NAV/COM/GPS COMP	MGL		011-0550-10 78402091	MTH HRS LDG	03-Aug-2011 12219 10058		O/C			
346011	TCAS PROCESSOR TPU-67A			066-01146-1211 41785	MTH HRS LDG	04-Feb-2015 13246.37 10731		O/C	0 0 0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
346093	GPS ANTENNA			071-01553-0200	MTH	04-Feb-2015		O/C	0		
	KA-92			465856	HRS	13246.37			0		
					LDG	10731			0		
346098	GPS RECEIVER	SAT		066-04034-0204	MTH	08-Jul-1999		O/C			
	KLN-900			M2307	HRS	9403			0		
347005	TCAS/VSI INDICATOR			066-01171-1804	MTH	11-Oct-2010		O/C	0		
LEFT		MGL		27190	HRS	11820			0		
					LDG	9816			0		
347005	TCAS/VSI INDICATOR			066-01171-1804	MTH	11-Oct-2010		O/C	0		
RIGHT		MGL		27189	HRS	11820			0		
					LDG	9816			0		
351001	OXYGEN PRESSURE GAUGE			C668512-0101	MTH	13-Mar-1986		O/C	0		
	MD-97	*CF		6264							
351004	CREW OXYGEN MASK			174045-15	MTH	27-Oct-2009		O/C	132		
LEFT		MGL		07476	HRS	11259					
351004	CREW OXYGEN MASK			174045-15	MTH	27-Oct-2009		O/C	0		
RIGHT		MGL		7367	HRS	11259					
351005	OXYGEN REGULATOR			ZR807	MTH	04-Oct-1985		O/C	0		
		*CF		363							
351006	OXYGEN CYLINDER ASSEMBLY			176176-64	MTH	28-Mar-2013		288	68	31-Jul-2031	60 m 7 d
	ZC369-64			808777	HRS	12903					
					LDG	10486					
361003	PNEUMATIC REGULATOR			38E85-5C	MTH	13-Mar-1986		O/C			
	9912043-2	*CF		RF1377							
361005	GYRO PRESSURE GAGE			C668515-0101	MTH	13-Mar-1986		O/C			
RIGHT		*CF		15003H							
361006	FORWARD INST BA PRESS REGULATOR				MTH	13-Mar-1986		O/C			
BOTTOM		*CF		3H64-4							
				SN-UNKNOWN							
361006	FORWARD INST BA PRESS REGULATOR				MTH	13-Mar-1986		O/C			
TOP		*CF		3H64-4							
				SN-UNKNOWN							
361007	PRESSURE DOOR SEAL HOSE			CM2939-4-15	MTH	13-Mar-1986		O/C			
		*CF		SN-UNKNOWN							
361008	CHECK VALVE	CMH		1H95-3	MTH	22-May-1992		O/C			
LEFT				10AB0007	HRS	3382			0		
361008	CHECK VALVE	ICT		1H95-3	MTH	02-Jun-1989		O/C			
RIGHT				2AB009AB	HRS	1213			0		
383002	TOILET PUMP	CMH		17000-382	MTH	17-Jul-1997		O/C			
				6267	HRS	8454			0		
521001	CABIN DOOR SEAL	FXE		S15501-4	MTH	23-Aug-2006		O/C			
	9912075-4			SN-UNKNOWN	HRS	10545			0		
526001	CABIN DOOR STEP	*CF		6519009-44	MTH	13-Mar-1986		O/C			
	6519009			SN-UNKNOWN							
561001	MAIN WINDSHIELD ASSY, (LH)			E149000-9	MTH	03-Mar-1997		O/C			
LEFT	9912064-11	LUK		3025	HRS	8140			2639		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
561002 RIGHT	MAIN WINDSHIELD ASSY, (LH)	MGL		9912064-16R 2448	MTH HRS LDG	01-Jun-2011 12079 9976		O/C	0 0		
561003	FOUL WEATHER WINDOW	FXE		5511275-17 978	MTH HRS	18-May-2005 10261		O/C	0		
561005 LEFT INBOARD	FLIGHT COMPARTMENT WINDOW	SAT		5511285-5 101185	MTH HRS	12-Jun-1999 9403		O/C	0		
561005 LEFT OUTBOARD	FLIGHT COMPARTMENT WINDOW	*CF		5511285-3 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
561005 RIGHT INBOARD	FLIGHT COMPARTMENT WINDOW	SAT		5511285-6 11099	MTH HRS	12-Jun-1999 9403		O/C	0		
561005 RIGHT OUTBOARD	FLIGHT COMPARTMENT WINDOW	SAT		5511285-48 2298	MTH HRS	12-Jun-1999 9403		O/C	0		
562001 LEFT NO. 1	CABIN WINDOW	ODE		PAS9912207-8 0607	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 LEFT NO. 2	CABIN WINDOW	ODE		PAS9912207-8 0608	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 LEFT NO. 3	CABIN WINDOW	ODE		PAS9912207-1 0609	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 LEFT NO. 4	CABIN WINDOW	ODE		PAS9912207-8 0610	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 LEFT NO. 5	CABIN WINDOW	ODE		PAS9912207-8 0611	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 LEFT NO. 6	CABIN WINDOW	ODE		PAS9912207-8 0612	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 RIGHT NO. 1	CABIN EMERGENCY DOOR WINDOW	ODE		PAS9912207-8 0613	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 RIGHT NO. 2	CABIN WINDOW	ODE		PAS9912207-8 0614	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 RIGHT NO. 3	CABIN WINDOW	ODE		PAS9912207-8 0615	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 RIGHT NO. 4	CABIN WINDOW	ODE		PAS9912207-8 0616	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 RIGHT NO. 5	CABIN WINDOW	ODE		PAS9912207-8 0617	MTH HRS	02-Apr-2004 10156		O/C	0		
562001 RIGHT NO. 6	CABIN WINDOW	ODE		PAS9912207-8 0618	MTH HRS	02-Apr-2004 10156		O/C	0		
575001 LEFT INBOARD	FLAP --	CMH		6525121-1 A002-00135	MTH HRS	20-Jun-1996 7312		O/C	0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
576002 LEFT	AILERON --	ICT		6590029-1 A00100098	MTH HRS	20-Jun-1997 8398		O/C	 0		
576002 RIGHT	AILERON --	ICT		6590039-2 A00600093	MTH HRS	20-Jun-1997 8398		O/C	 0		
712001 LEFT	AFT ENGINE ISOLATOR 9912455-2	EDLN		LM420SA6-1 2533	MTH HRS LDG	28-Mar-2013 12903 10486		 3500	 0	 16403	 3020.3
712001 RIGHT	AFT ENGINE ISOLATOR 9912455-2	EDLN		LM420SA6-1 2507	MTH HRS LDG	28-Mar-2013 12903 10486		 3500	 0	 16403	 3020.3
712002 LEFT BOTTOM	FWD ENGINE ISOLATOR 9912172-9	EDLN		LM420SA31 N/A	MTH HRS LDG	28-Mar-2013 12903 10486		 3500	 0	 16403	 3020.3
712002 LEFT TOP	FWD ENGINE ISOLATOR 9912172-8	EDLN		LM420SA30 N/A	MTH HRS LDG	28-Mar-2013 12903 10486		 3500	 0	 16403	 3020.3
712002 RIGHT BOTTOM	FWD ENGINE ISOLATOR 9912172-9	EDLN		LM420SA31 N/A	MTH HRS LDG	28-Mar-2013 12903 10486		 3500	 0	 16403	 3020.3
712002 RIGHT TOP	FWD ENGINE ISOLATOR 9912172-8	EDLN		LM420SA30 N/A	MTH HRS LDG	28-Mar-2013 12903 10486		 3500	 0	 16403	 3020.3
71EN1 NO. 1 *710001 : E1**L*	ENGINE 3018700	YPAD		JT15D-4B PCE-102251	MTH HRS LDG	01-Jul-2021 13322.6 10796		E/C	 8071.9		
71EN2 NO. 2 *710001 : E2**R*	ENGINE	YPAD		3035800 PCE-102009	MTH HRS LDG	01-Jul-2021 13322.6 10796		E/C	 8036.1		
722001 E1	OIL PUMP	YPAD		3104289-06 2P272	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	 3323.8		
722001 E2	OIL PUMP	YPAD		3104289-06 PWC9JM443	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	 3152		
723001 E1	ENGINE FAN --	CEL		3018020 NSN	MTH HRS	10-Jul-2008 9998.5		O/C	 3496		
723001 E2	ENGINE FAN --	CEL		3018020 NSN	MTH HRS	10-Jul-2008 10169.9		O/C	 3496		
723010 E1	CENTRIFUGAL IMPELLER	YPAD		3036108 6C596	MTH HRS LDG ACCC YC	01-Jul-2021 13322.6 10796		 8200	 7744 7744	 11252	 408 408
723010 E2	CENTRIFUGAL IMPELLER	YPAD		3036625 8200	MTH HRS LDG ACCC YC	01-Jul-2021 13322.6 10796		 8200	 6438 6438	 12558	 1714 1714

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
723020	LOW PRESSURE BOOST COMPRESSOR HUB				MTH	01-Jul-2021					
E1		YPAD		3021112	HRS	13322.6					
				2R116	LDG	10796			7744	17052	6208
					ACCC YC			14000	7744		6208
723020	LOW PRESSURE BOOST COMPRESSOR HUB				MTH	01-Jul-2021					
E2		YPAD		3021112	HRS	13322.6					
				3N015	LDG	10796			7900	16896	6052
					ACCC YC			14000	7900		6052
723030	LOW PRESSURE COMPRESSOR HUB			3018018	MTH	01-Jul-2021					
E1		YPAD		9R679	HRS	13322.6					
					LDG	10796			13357	24939	14095
					ACCC YC			27500	13357		14095
723030	LOW PRESSURE COMPRESSOR HUB			3018018	MTH	01-Jul-2021					
E2		YPAD		7N120	HRS	13322.6					
					LDG	10796			13777	24519	13675
					ACCC YC			27500	13777		13675
725010	HIGH PRESSURE TURBINE ROTOR DISK				MTH	01-Jul-2021					
E1		YPAD		3023411	HRS	13322.6					
				8R266	LDG	10796			7744	17052	6208
					ACCC YC			14000	7744		6208
725010	HIGH PRESSURE TURBINE ROTOR DISK				MTH	01-Jul-2021					
E2		YPAD		3036411	HRS	13322.6					
				86A688	LDG	10796			4275	20521	9677
					ACCC YC			14000	4275		9677
725020	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK				MTH	01-Jul-2021					
E1		YPAD		3022212	HRS	13322.6					
				6R652	LDG	10796			7744	17052	6208
					ACCC YC			14000	7744		6208
725020	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK				MTH	01-Jul-2021					
E2		YPAD		3022212	HRS	13322.6					
				6N944	LDG	10796			7900	16896	6052
					ACCC YC			14000	7900		6052
725030	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK				MTH	01-Jul-2021					
E1		YPAD		3036113	HRS	13322.6					
				8R190	LDG	10796			7744	17052	6208
					ACCC YC			14000	7744		6208
725030	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK				MTH	01-Jul-2021					
E2		YPAD		3021213	HRS	13322.6					
				6N966	LDG	10796			7900	16896	6052
					ACCC YC			14000	7900		6052
725071	COMBUSTION LINER			3105143-01	MTH	10-Jul-2008		O/C			
E1		CEL		SN-UNKNOWN	HRS	9998.5			3496		
725071	COMBUSTION LINER			3105143-01	MTH	10-Jul-2008		O/C			
E2		CEL		SN-UNKNOWN	HRS	10169.9			3496		
725101	REPLACE HIGH TURBINE BLADES				MTH	10-Jul-2008		O/C			
E1 NO. 1		CEL			HRS	9998.5					

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
725101 E2 NO. 1	REPLACE HIGH TURBINE BLADES	CEL			MTH HRS	10-Jul-2008 10169.9		O/C			
731004 LEFT	LOW FUEL PRESSURE SWITCH 9912033-1	*CF		1103P92 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
731004 RIGHT	LOW FUEL PRESSURE SWITCH 9912033-1	*CF		1103P92 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
732002	ENGINE SYNC CONTROL 5560001	LUK		213787 2257313H	MTH HRS	05-Apr-1994 5100		O/C	0		
732003	ENGINE SYNC ACTUATOR	CMH		5485-066 11433547	MTH HRS	16-Mar-1998 9092		O/C	0		
733002	FUEL FLOW INDICATOR 9912147-16	*CF		VSDL-OC208E 347	MTH	13-Mar-1986		O/C			
731010 E1	FUEL PUMP 3031632	YPAD		025493-402-05 2930	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	3323.8		
731010 E2	FUEL PUMP 3032203	YPAD		398601-2 0228	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C			
731020 E1	FUEL-OIL COOLER	YPAD		3015303 2476	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	3323.8		
731020 E2	FUEL-OIL COOLER	YPAD		3015303 3050	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	3152		
731030 E1	MOTIVE FLOW VALVE 3017930	YPAD		2524995-1 A90619	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	3323.8		
731030 E2	MOTIVE FLOW VALVE 3017930	CEL		2524995 A90372	MTH HRS	10-Jul-2008 10169.9		O/C	3496		
731040 E1	FLOW DIVIDER VALVE 3024476	CEL		25607-2 1991	MTH HRS	10-Jul-2008 9998.5		O/C	3496		
731040 E2	FLOW DIVIDER VALVE 3024476	CEL		25607-2 3075	MTH HRS	10-Jul-2008 10169.9		O/C	3496		
732004 E1	SOLENOID FUEL VALVE 3029591	YPAD		3244758-1 8715	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	3323.8		
732004 E2	SOLENOID FUEL VALVE 3029591	YPAD		3244758-1 8716	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	3152		
732010 E1	FUEL CONTROL UNIT 3030251	YPAD		3244759-4 A58805	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	3323.8		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
732010 E2	FUEL CONTROL UNIT 3030251	YPAD		3244759-4 A92329	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	3152		
733010 E1	FUEL FLOW TRANSMITTER 9912031-6			3268014-0201 731	MTH	14-Sep-1984		O/C			
733010 E2	FUEL FLOW TRANSMITTER 9912031-6			3268014-0201 749	MTH	14-Sep-1984		O/C			
741010 E1 LOWER	IGNITION EXCITER	CEL		NB01201 U4331	MTH HRS	10-Jul-2008 9998.5		O/C	3496		
741010 E2 LOWER	IGNITION EXCITER	CEL		NB01201 SN-UNKNOWN	MTH HRS	10-Jul-2008 10169.9		O/C	153		
741015 E1 UPPER	IGNITION EXCITER 3033378	CEL		NB01201 W5418	MTH HRS	10-Jul-2008 9998.5		O/C	3496		
741015 E2 UPPER	IGNITION EXCITER 3033378	CEL		NB01201 SN-UNKNOWN	MTH HRS	10-Jul-2008 10169.9		O/C	153		
742010 E1 OUTBOARD	IGNITER PLUG	CEL		FHE-246-4 0004087	MTH HRS	10-Jul-2008 9998.5		O/C	1013		
742010 E2 OUTBOARD	IGNITER PLUG	CEL		FHE-246-4 NSN	MTH HRS	10-Jul-2008 10169.9		O/C	153		
742020 E1 INBOARD	IGNITER PLUG 3030595	CEL		FHE-246-4 0004040	MTH HRS	10-Jul-2008 9998.5		O/C	1013		
742020 E2 INBOARD	IGNITER PLUG 3030595	CEL		FHE-246-4 NSN	MTH HRS	10-Jul-2008 10169.9		O/C	153		
742030 E1 SHORT	IGNITER LEAD 3027939	CEL		10-395428-1 NSN	MTH HRS	10-Jul-2008 9998.5		O/C	3349		
742030 E2 SHORT	IGNITER LEAD 3027939	CEL		10-395428-1 NSN	MTH HRS	10-Jul-2008 10169.9		O/C	3496		
742040 E1 LONG	IGNITER LEAD 3027939	CEL		10-395428-2 NSN	MTH HRS	10-Jul-2008 9998.5		O/C	3349		
742040 E2 LONG	IGNITER LEAD	CEL		3103936-03 NSN	MTH HRS	10-Jul-2008 10169.9		O/C	3496		
750010 E1	LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE 3018531	YPAD		KW15632 2834	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	3323.8		
750010 E2	LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE 3018531	YPAD		KW15632 3300	MTH HRS LDG	01-Jul-2021 13322.6 10796		O/C	3152		
761005	SOLENOID ASSEMBLY 9912110-1	*CF		U-183238-001 SN-UNKNOWN	MTH	13-Mar-1986		O/C			
771001 LEFT BOTTOM	TACH N2 GENERATOR 9912034-1	*CF		22A623 7393	MTH	13-Mar-1986		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
771001 LEFT TOP	TACH N1 GENERATOR 9912034-1	 *CF		22A623 7345	MTH	13-Mar-1986		O/C			
771001 RIGHT BOTTOM	TACH N2 GENERATOR 9912034-1	 SAT		22A623 76582	MTH HRS	29-Mar-1998 9106		O/C	 0		
771001 RIGHT TOP	TACH N1 GENERATOR 9912034-1	 *CF		22A623 H8521	MTH	13-Mar-1986		O/C			
771002	N2 TURBINE RPM INDICATOR 9912147-25	 YBSU		DDL-OC110A 74BA	MTH HRS LDG	11-Jan-2016 13282.8 10746		O/C			
771003	N1 FAN RPM INDICATOR 9912147-24	 EDLN		VSDL-OC410AD 42EA	MTH HRS LDG	27-Aug-2013 13114 10637		O/C			
772003 *772001*	ITT INDICATOR 9912147-34	FXE		VSDL-OC419L 166BA	MTH HRS	07-Jul-2005 10277		O/C	 1322		
781001 LEFT	EXHAUST NOZZLE CONE	LUK		9912110-9-S9 SN-UNKNOWN	MTH HRS	19-Sep-1998 9289		O/C	 0		
781001 RIGHT	EXHAUST NOZZLE CONE	LUK		9912110-7-S7 SN-UNKNOWN	MTH HRS	19-Sep-1998 9289		O/C	 0		
783001 LEFT	THRUST REVERSER ASSEMBLY	UNK		202.0100.501 RC1458	MTH HRS LDG	21-Dec-2022 13355.2 10819		O/C			
783001 RIGHT	THRUST REVERSER ASSEMBLY	UNK		202.0100.503 RC1459	MTH HRS LDG	21-Dec-2022 13355.2 10819		O/C			
783002 LEFT	CONTROL VALVE	*CF		65680 900	MTH	13-Mar-1986		O/C			
783002 RIGHT	CONTROL VALVE	*CF		65680 779	MTH	13-Mar-1986		O/C			
783003 LEFT	THREE WAY VALVE	*CF		13027-4 1402	MTH	13-Mar-1986		O/C			
783003 RIGHT	THREE WAY VALVE	*CF		13027-4 1394	MTH	13-Mar-1986		O/C			
783005 LEFT	THRUST REVERSER DOOR 9912110-1	 SAT		202-0001-501 RC1648	MTH HRS LDG	12-Jun-1999 9403 7929		O/C	 7929		
783005 RIGHT	THRUST REVERSER DOOR 9912110-1	 SAT		202-0001-502 RC1719	MTH HRS LDG	12-Jun-1999 9403 7929		O/C	 7929		
783006 LEFT	THRUST REVERSER DOOR 9912110-1	 SAT		202-0002-501 RC1648	MTH HRS LDG	12-Jun-1999 9403 7929		O/C	 7929		
783006 RIGHT	THRUST REVERSER DOOR 9912110-1	 SAT		202-0002-502 RC1719	MTH HRS LDG	12-Jun-1999 9403 7929		O/C	 7929		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
783007	THRUST REVERSER MECH ASSEMBLY			202-0004-1	MTH	12-Jun-1999		O/C			
LEFT	9912110-1	SAT		RC1648	HRS	9403					
					LDG	7929			7929		
783007	THRUST REVERSER MECH ASSEMBLY			202-0004-1	MTH	12-Jun-1999		O/C			
RIGHT	9912110-1	SAT		RC1719	HRS	9403					
					LDG	7929			7929		
783008	THRUST REVERSER MECH ASSEMBLY			202-0004-3	MTH	12-Jun-1999		O/C			
LEFT	9912110-1	SAT		RC1648	HRS	9403					
					LDG	7929			7929		
783008	THRUST REVERSER MECH ASSEMBLY			202-0004-5	MTH	12-Jun-1999		O/C			
RIGHT	9912110-1	SAT		RC1719	HRS	9403					
					LDG	7929			7929		
783009	THRUST REVERSER FAN DUCT			202-0012-1	MTH	12-Jun-1999		O/C			
LEFT	9912110-1	SAT		RC1648	HRS	9403					
					LDG	7929			7929		
783009	THRUST REVERSER FAN DUCT			202-0012-1	MTH	12-Jun-1999		O/C			
RIGHT	9912110-1	SAT		RC1719	HRS	9403					
					LDG	7929			7929		
783010	THRUST REVERSER ACTUATOR			62270	MTH	12-Jun-1999		O/C			
LEFT INBOARD	9912110-1	SAT		SN-UNKNOWN	HRS	9403					
					LDG	7929			0		
783010	THRUST REVERSER ACTUATOR			62270	MTH	12-Jun-1999		O/C			
LEFT OUTBOARD	9912110-1	SAT		SN-UNKNOWN	HRS	9403					
					LDG	7929			0		
783010	THRUST REVERSER ACTUATOR			62270	MTH	12-Jun-1999		O/C			
RIGHT INBOARD	9912110-1	SAT		SN-UNKNOWN	HRS	9403					
					LDG	7929			0		
783010	THRUST REVERSER ACTUATOR			62270	MTH	12-Jun-1999		O/C			
RIGHT OUTBOARD	9912110-1	SAT		SN-UNKNOWN	HRS	9403					
					LDG	7929			0		
793001	OIL TEMPERATURE INDICATOR			VSDL-OC219F	MTH	04-Aug-2017		O/C			
	9912147-11	YBSU		706A	HRS	13312.4					
					LDG	10788					
793002	OIL TEMPERATURE TRANSMITTER			MS28034-3	MTH	13-Mar-1986		O/C			
LEFT		*CF		66938							
793002	OIL TEMPERATURE TRANSMITTER			MS28034-3	MTH	13-Mar-1986		O/C			
RIGHT		*CF		71883							
793003	OIL PRESSURE INDICATOR			VSDL-OC204H	MTH	15-May-1986		O/C			
	9912147-10	ICT		233FCA	HRS	127			0		
793004	OIL PRESSURE TRANSMITTER			123479	MTH	20-Mar-1987		O/C			
LEFT	9912164-1	MCO		39244	HRS	568			0		
793004	OIL PRESSURE TRANSMITTER			123479	MTH	13-Aug-1996		O/C			
RIGHT	9912164-1	CMH		33309	HRS	7498			0		

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Components

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
792003	OIL FILTER	YPAD		3015330	MTH	01-Jul-2021		O/C	0		
E1				SN-UNKNOWN	HRS	13322.6			0		
					LDG	10796			0		
792003	OIL FILTER	YPAD		3015330	MTH	01-Jul-2021		O/C	0		
E2				SN-UNKNOWN	HRS	13322.6			0		
					LDG	10796			0		
832001	MAIN GEAR BOX ASSY	--		3018390	MTH	10-Jul-2008		O/C			
E1		CEL		NSN	HRS	9998.5			3496		
832001	MAIN GEAR BOX ASSY	--		3018390	MTH	10-Jul-2008		O/C			
E2		CEL		NSN	HRS	10169.9			3496		

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)										
				INFORMATIONAL				-			
	MOC :										
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)										
				RECOMMENDED				-			
	MOC :										
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)										
				RECOMMENDED	MTH			-			
	MOC :										
SL S550-01-02	CORRECTION TO INSTALLED EQUIPMENT LIST				MTH	02-Feb-1989		A/R			Complete
01SL-02		ICT		RECOMMENDED	HRS	1043					
	MOC : COMPLIED WITH										
SL S550-03-02 R01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)										
				INFORMATIONAL				-			
	MOC :										
SL S550-99-04 R07	CESCOM PRICES (THIS SL IS CANCELS SLS550-99-04 R6 AND PREVIOUS)										
				INFORMATIONAL				-			
	MOC :										
SL S550-99-07	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS										
				INFORMATIONAL				A/R			
	MOC :										
SL S550-99-08	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION										
				INFORMATIONAL				A/R			
	MOC :										
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW										
				INFORMATIONAL				-			
	MOC :										
SB S550-11-03	SEAT PLACARD INSTALLATIONS AND EMERGENCY EXIT HANDLE GUARD DECAL REPLACEMENT (SUPERSEDED BY S550-11-03 R01)										
11SB-03		TOL		MANDATORY	MTH	09-Jul-1987		A/R			Complete
					HRS	667					
	MOC : COMPLIED WITH										
SB S550-11-04	AIRSPEED LIMITATIONS PLACARD REPLACEMENT				MTH	23-Sep-1988		A/R			Complete
11SB-04		ICT		MANDATORY	HRS	886					
	MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-11-05 *11SB-05*	FLAP NO STEP PLACARD INSTALLATION	CMH		RECOMMENDED	MTH HRS	22-Feb-1993 4007		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-11-06 *11SB-06*	FIRE EXTINGUISHER PLACARD INSTALLATION			OPTIONAL	MTH			A/R			
	MOC :										
SL S550-11-01 *11SL-01*	DATA PLATE RELOCATION			OPTIONAL	MTH			A/R			
	MOC :										
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R02)			INFORMATIONAL				-			
	MOC :										
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL				-			
	MOC :										
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R01)			INFORMATIONAL				-			
	MOC :										
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			RECOMMENDED	MTH			-			
	MOC :										
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL				-			
	MOC :										
SL CIL-20-01 R03-CN	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			CANCELLED				-			
	MOC :										
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)			INFORMATIONAL				-			
	MOC :										
SL S550-20-01 R27	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SLS550-20-01 R28)			INFORMATIONAL				A/R			
	MOC :										
SL S550-20-04	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL				-			
	MOC :										
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT			INFORMATIONAL				-			
	MOC :										
SL CIL-21-02 R01	ENVIRONMENTAL HOUR METER INSTALLATION	YMEN		MANDATORY	MTH HRS LDG	24-Sep-2015 13279.9 10742		-			N/A
	MOC : NOT APPLICABLE - COMMENTS: CESSNA SERVICE LETTER (SL) CIL-21-02 R1 ENVIRONMENTAL HOUR METER INSTALLATION NOT CARRIED OUT DUE NOT BEING MANDATORY.PLEASE REMOVE FROM "OVER DUE" LIST.										
SB S550-21-03 R01 *21SB-03 : S55R1*	FREON AIR CONDITIONING SYSTEM INSTALLATION - CANCELLED			CANCELLED	MTH			A/R			
	MOC :										
SB S550-21-05 *21SB-05*	SUPPLEMENTAL COCKPIT AIR DISTRIBUTION SYSTEM			OPTIONAL	MTH			A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-21-08 *21SB-08*	TAILCONE RAM AIR INLET PRESSURIZATION VALVE INSTALLATION			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-21-09 R02 *21SB-09 : S55R2*	TAILCONE FRESH AIR DUCT MODIFICATION (SUPERSEDED BY S550-21-09 R03)			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-21-10 *21SB-10*	AIR DUCT RETENTION IMPROVEMENT (SUPERSEDED BY S550-21-10 R01)	CMH		RECOMMENDED	MTH 29-Apr-1991 HRS 2497		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-21-11 *21SB-11*	ACM BLEED AIR DUCT SUPPORT CLAMP INSTALLATION			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-21-12 *21SB-12*	TAILCONE PRESSURE VALVE ACTUATOR WIRING MODIFICATION			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-21-14 *21SB-14*	ADDITIONAL OUTFLOW VALVE REPLACEMENTS	MKE		MANDATORY	MTH 03-Mar-1995 HRS 6000		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-21-15 *21SB-15*	AIR CONDITIONING - COCKPIT SIDE WINDOW DEFOG SYSTEM MODIFICATION	HRZ		OPTIONAL	MTH 26-Oct-2000 HRS 9897		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-21-16 *21SB-16*	CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT			DISCRETIONARY	MTH		A/R			
	MOC :									
SB S550-21-17	AIR CONDITIONING - TEMPERATURE CONTROLLER IMPROVEMENT			OPTIONAL			A/R			
	MOC :									
SL S550-21-02 *21SL-02*	TAILCONE FRESH AIR DUCT ROUTING INSPECTION	BAF		RECOMMENDED	MTH 07-Jun-1991 HRS 2620		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-21-05 *21SL-05*	AIR CONDITIONING - TRANSMITTAL OF FORT WORTH AIRWORKS, INC. SERVICE BULLETIN 99-101, EVAPORATOR MODULE INSTALLATION 1250240 AND 1134240 SERIES.			RECOMMENDED	MTH 09-May-2000 HRS 9673		A/R			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE									
SB S550-23-05 R01 *23SB-05 : S55R1*	ELECTRICAL BONDING FLAP AND SPEED BRAKE PUSHRODS (SUPERSEDED BY S550-23-05 R02)	ICT		RECOMMENDED	MTH 20-Jun-1997 HRS 8398		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-23-05 R03 *23SB-05 : S55R3*	ELECTRICAL BONDING FLAP AND SPEED BRAKE PUSHRODS	MGL		RECOMMENDED	MTH 01-Jun-2011 HRS 12079 LDG 9976		300			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-23-05	ELECTRICAL BONDING FLAP AND SPEED BRAKE PUSHRODS (SUPERSEDED BY S550-23-05 R01)									
23SB-05		MGL		RECOMMENDED	MTH 09-Apr-2010 HRS 11487 LDG 9632		A/R			
	MOC : DEFERRED									
SB S550-23-07	STATIC WICK REPLACEMENT			OPTIONAL	MTH		A/R			
23SB-07		*CF								
	MOC :									
SB S550-23-08 R01	COLLINS 8.33 KHZ COMMUNICATION RADIO INSTALLATION									
23SB-08 : S55R1				OPTIONAL	MTH		A/R			
	MOC :									
SB S550-23-09	VLF NOISE FILTER CAPACITOR REMOVAL/REPLACEMENT (SUPERSEDED BY S550-23-09 R01)									
23SB-09				MANDATORY	MTH 12-Dec-1999 HRS 9566		A/R			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
SL S550-23-01	MICROPHONE REPLACEMENT PROGRAM				MTH 23-Sep-1988		A/R			Complete
23SL-01		ICT		RECOMMENDED	HRS 886					
	MOC : COMPLIED WITH									
SL S550-23-02	STATIC DISCHARGE WICK MODIFICATION				MTH		A/R			
23SL-02				OPTIONAL						
	MOC :									
SL S550-23-14	COMMUNICATIONS - AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE									
23SL-14		MGL		RECOMMENDED	MTH 09-Apr-2010 HRS 11487 LDG 9632		300			
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!									
SB S550-24-04	LEFT CIRCUIT BREAKER PANEL BUSSING MODIFICATION (SUPERSEDED BY S550-24-04 R01)									
24SB-04		ICT		MANDATORY	MTH 05-Nov-1986 HRS 402		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-24-06	TKS FLUID PUMP SEPARATE CIRCUIT BREAKER INSTALLATION (SUPERSEDED BY S550-24-06 R01)									
24SB-06				OPTIONAL	MTH		A/R			
	MOC :									
SB S550-24-08	LH AND RH PITOT STATIC CIRCUIT BREAKER REPLACEMENT AND CABIN FAN POWER BUS BAR CHANGE									
24SB-08		MCO		MANDATORY	MTH 13-Jan-1987 HRS 481		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-24-11	RIGHT PYLON WIRE BUNDLE PROTECTION				MTH 22-May-1990		A/R			Complete
24SB-11		LGB		MANDATORY	HRS 1721					
	MOC : COMPLIED WITH									
SB S550-24-12	CONTROL WHEEL ELECTRICAL CABLE REPLACEMENT (SUPERSEDED BY S550-24-12 R01)									
24SB-12				OPTIONAL	MTH		A/R			
	MOC :									
SB S550-24-14 R01	MAIN LANDING GEAR AXLE ANTISKID WIRE BUNDLE PROTECTION									
24SB-14 : S55R1		CMH		RECOMMENDED	MTH 13-Oct-1992 HRS 3712		A/R			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-24-14 *24SB-14*	MAIN LANDING GEAR AXLE ANTISKID WIRE BUNDLE PROTECTION (SUPERSEDED BY S550-24-14 R01)	CMH		RECOMMENDED	MTH 13-Oct-1992 HRS 3712		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-24-15 *24SB-15*	WING WIRE BUNDLE ROUTING MODIFICATION	CMH		RECOMMENDED	MTH 13-Oct-1992 HRS 3712		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-24-17 *24SB-17*	AVIONICS POWER RELAYS REPLACEMENT	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB S550-24-18 *24SB-18*	WING TIP WIRE BUNDLE PROTECTIVE COVER INSTALLATION	MKE		RECOMMENDED	MTH 03-Mar-1995 HRS 6000		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-24-19 R01 *24SB-19 : S55R1*	ELECTRICAL CABLE CHAFING PROTECTION INSTALLATION W.S. 44.0 AND W.S. 54.07	CMH		RECOMMENDED	MTH 22-Feb-1996 HRS 7001		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-24-19 *24SB-19*	ELECTRICAL CABLE CHAFING PROTECTION INSTALLATION W.S. 44.0 AND W.S. 54.07 (SUPERSEDED BY S550-24-19 R01)	CMH		RECOMMENDED	MTH 05-Nov-1994 HRS 5718		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-24-21 R01 *24SB-21 : S55R1*	OVERVOLTAGE MONITOR SYSTEM INSTALLATION			OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-24-22 *24SB-22*	BATTERY DISCONNECT RELAY ACCESS IMPROVEMENT			OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-24-23 R01 *24SB-23 : S55R1*	MAIN POWER WIRE ANCHOR IMPROVEMENT	MGL		RECOMMENDED	MTH 09-Apr-2010 HRS 11487 LDG 9632		300			
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!									
SB S550-24-24	ELECTRICAL POWER - MAGNETIC CIRCUIT BREAKER REPLACEMENT			OPTIONAL			A/R			
	MOC :									
SB S550-24-25 R01	ELECTRICAL POWER - TIME DELAY RELAY INSTALLATION			OPTIONAL	MTH		-			
	MOC :									
SL S550-24-01 R01 *24SL-01 : S55R1*	TAILCONE WIRE BUNDLE REROUTING AND CLAMPING	CMH		RECOMMENDED	MTH 20-Jul-1988 HRS 784		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-24-01 *24SL-01*	TAILCONE WIRE BUNDLE REROUTING AND CLAMPING	TOL		RECOMMENDED	MTH 24-Feb-1988 HRS 727		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-24-06 *24SL-06*	500 HOUR MID-LIFE BEARING CHANGE FOR 9912125-1 (23085-004 AND 23085-004 MOD A) STARTER GENERATORS	CMH		RECOMMENDED	MTH 17-Sep-1991 HRS 2917		A/R			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SL S550-24-07 *24SL-07*	COCKPIT CIRCUIT BREAKER INSPECTION/REPLACEMENT	CMH		RECOMMENDED	MTH HRS	05-Sep-1990 1948		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-24-08 *24SL-08*	DELETE THE 500 HOUR MID-LIFE BEARING CHANGE REQUIREMENT FOR THE 9912125-1 (23085-004 MOD A) STARTER/GENERATOR	MGL		RECOMMENDED	MTH HRS LDG	09-Apr-2010 11487 9632		300			
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!										
SL S550-24-10 *24SL-10*	ANTI-ICE RELAY BASE ORIENTATION INSPECTION/MODIFICATION (SUPERSEDED BY SLS550-24-10 R01)	CMH		RECOMMENDED	MTH HRS	21-Apr-1992 3295		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-24-25	ELECTRICAL POWER - TIME DELAY RELAY INSTALLATION			OPTIONAL				-			
	MOC :										
SB S550-25-09 *25SB-09*	CREW SEAT BACK MODIFICATION			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-25-11 *25SB-11*	LOCATOR BEACON RESET CIRCUIT VOLTAGE LIMIT RESISTOR REMOVAL	TOL		MANDATORY	MTH HRS	25-Aug-1986 301		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-25-12 *25SB-12*	TAILCONE ACCESS DOOR STRAP INSTALLATION			OPTIONAL	MTH			A/R			
	MOC :										
ASB S550-25-16A *25SBA16*	INTERIOR CABINETRY ELECTRICAL POWER SOURCE DISABLEMENT	LEX		MANDATORY	MTH HRS	04-Feb-1987 516		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-25-18 *25SB-18*	PASSENGER SEAT ARMREST RELEASE LEVER REPLACEMENT			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-25-20 *25SB-20*	FORWARD REFRESHMENT CENTER OVERBOARD DRAIN RELOCATION (SUPERSEDED BY S550-25-20 R01)	CMH		RECOMMENDED	MTH HRS	18-Dec-1990 2198		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-25-21 *25SB-21*	CREW SEAT PAN REPLACEMENT			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-25-29 R03	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL				A/R			
	MOC :										
SB S550-25-29 *25SB-29*	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY S550-25-29 R01)			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-25-30 R01 *25SB-30 : S55R1*	GLARESHIELD LEATHER STRIP INSTALLATION			OPTIONAL	MTH			A/R			
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SL S550-25-02 R03 *25SL-02 : S55R3*	INTERIOR CABINETRY WIRING AND ELECTRICAL COMPONENT INSPECTION AND MODIFICATION (SUPERSEDED BY SLS550-25-02 R04)	MCO		MANDATORY	MTH HRS	20-Mar-1987 568		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-25-02 R04 *25SL-02 : S55R4*	INTERIOR CABINETRY WIRING AND ELECTRICAL COMPONENT INSPECTION AND MODIFICATION	ICT		MANDATORY	MTH HRS	03-Feb-1989 1043		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-25-04 *25SL-04*	SWITLIK INFLATABLE LIFE PRESERVER INSPECTION	ICT		INFORMATIONAL	MTH HRS	23-Sep-1988 886		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-25-07 *25SL-07*	TRANSMITTAL OF EASTERN AERO MARINE SERVICE BULLETIN SBV-25-2, EQUIPMENT/FURNISHINGS - LIFE PRESERVERS AND INDIVIDUAL FLOTATION DEVICES REPLACEMENT OF CO2 INFLATOR - MANDATORY	SAT		MANDATORY	MTH HRS	12-Jun-1999 9403		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-25-08 *25SL-08*	EQUIPMENT/FURNISHINGS - GLARESHIELD ATTACHMENT SCREW(S) INSPECTION/REPLACEMENT	MGL		RECOMMENDED	MTH HRS LDG	09-Apr-2010 11487 9632		 300			
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!										
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	YPAD		MANDATORY	MTH HRS LDG	01-Jul-2021 13322.6 10796		-			Complete
	MOC : COMPLIED WITH - INSPECTION C/O. IAW CIL-26-01 R1. NO 1 BOTTLE FOUND TO BE SATISFACTORY. NO 2 BOTTLE CARTRIDGES FOUND TO HAVE LATERAL MOVEMENT AND FAILED TORQUING TEST.										
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)			MANDATORY	MTH			-			
	MOC :										
SB S550-26-02 *26SB-02*	FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION	FXE		MANDATORY	MTH HRS	18-May-2005 10261		A/R			Complete
	MOC : COMPLIED WITH										
ASL SLS550-26-01A *26ASL01*	TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 -THERMISTORS DETECTORS	DLN		MANDATORY	MTH HRS	25-Jan-2008 10881		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-27-04 *27SB-04*	TRIM TAB ACTUATOR INSPECTION AND LUBRICATION (SUPERSEDED BY S550-27-04 R01)	BAF		RECOMMENDED	MTH HRS	05-Jul-1990 1817		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-27-05 *27SB-05*	RUDDER TRIM WHEEL BEARING INSPECTION/REPLACEMENT (SUPERSEDED BY S550-27-05 R01)	CMH		RECOMMENDED	MTH HRS	05-Sep-1990 1948		A/R			Complete
	MOC : COMPLIED WITH										

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-27-06	EXTENDED PEDESTAL AILERON PULLEY BRACKET MODIFICATION (SUPERSEDED BY S550-27-06 R01)									
27SB-06		CMH		RECOMMENDED	MTH 13-Oct-1992 HRS 3712		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-27-07 R01	AILERON CONTROL QUADRANT BOLT INSPECTION/REPACEMENT (SUPERSEDED BY S550-27-07 R02)									
27SB-07 : S55R1		CMH		MANDATORY	MTH 05-Mar-1992 HRS 3159		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-27-08	AILERON/RUDDER INTERCONNECT CLAMP MODIFICATION									
27SB-08		LUK		RECOMMENDED	MTH 09-Aug-1998 HRS 9202		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-27-09	FLIGHT CONTROLS - TRIM TAB ACTUATOR GREASE FITTING INSTALLATION									
27SB-09				OPTIONAL	MTH		A/R			
	MOC :									
SL S550-27-01	ELEVATOR CONTROL PUSH ROD ASSEMBLY INSPECTION/RIVET REPLACEMENT									
27SL-01		TOL		RECOMMENDED	MTH 09-Jul-1987 HRS 667		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-27-05	FLAP/ELEVATOR TRIM MIXER ACTUATOR ASSEMBLY INSPECTION/REPLACEMENT									
27SL-05		CMH		RECOMMENDED	MTH 21-Nov-1992 HRS 3790		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-27-07 R01	RUDDER/AILERON INTERCONNECT BOLT INSPECTION				MTH 09-Apr-2010		A/R			
27SL-07 : S55R1		MGL		MANDATORY	HRS 11487 LDG 9632					
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!									
SL S550-27-07	RUDDER/AILERON INTERCONNECT BOLT INSPECTION (SUPERSEDED BY SLS550-27-07 R01)									
27SL-07		CMH		SUPERSEDED	MTH 08-Sep-1997 HRS 8609		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-27-08	RUDDER PEDAL SUPPORT INSPECTION				MTH 09-Apr-2010					
27SL-08		MGL		RECOMMENDED	HRS 11487 LDG 9632		300			
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!									
SL CIL-28-01	FUEL - MICROBIOLOGICAL CONTAMINATION IN AIRCRAFT FUEL TANKS AND FUEL SYSTEMS									
				INFORMATIONAL			-			
	MOC :									
SB S550-28-03	WING LEADING EDGE RIB FLAPPER VALVES INSTALLATION									
28SB-03				OPTIONAL	MTH		A/R			
	MOC :									
SB S550-28-04	MOTIVE FLOW FUEL LINE INSPECTION AND SUPPORT INSTALLATION									
28SB-04		CMH		RECOMMENDED	MTH 25-Apr-1993 HRS 4209		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-28-05	FUEL SYSTEM PLUMBING CLAMP ADDITIONS				MTH 22-Feb-1996		A/R			Complete
28SB-05		CMH		RECOMMENDED	HRS 7001					
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-28-06 *28SB-06*	IMPROVED FUEL CROSSFEED SELECT KNOB AVAILABILITY **MOC :**			OPTIONAL	MTH			A/R			
SB S550-28-07 *28SB-07*	FUEL LINE SUPPORT INSTALLATION **MOC :** COMPLIED WITH	EDLN		RECOMMENDED	MTH HRS LDG	28-Mar-2013 12903 10486		3500			Complete
SB S550-28-08 *28SB-08*	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT **MOC :** COMPLIED WITH	PIM		MANDATORY	MTH HRS	09-Sep-2004 10186		A/R			Complete
SB S550-28-09 R01	FUEL - FUEL CHECK VALVE MODIFICATION **MOC :** DECLINED - OWNER DOES NOT WISH TO COMPLY.	EDLN		RECOMMENDED	MTH HRS LDG	30-Aug-2012 12839 10440		A/R			
SB S550-28-09 *28SB-09*	FUEL CHECK VALVE MODIFICATION (SUPERSEDED BY S550-28-09 R01) OPERATOR CHOOSES TO PERFORM AT NEXT PHASE 5. **MOC :**			RECOMMENDED	MTH		21	A/R			
SL S550-28-01 R03 *28SL-01 : S55R3*	FUEL QUANTITY COMPENSATOR INSTALLATION ATTACHMENT INSPECTION **MOC :** COMPLIED WITH	SWF		RECOMMENDED	MTH HRS	17-Nov-1993 4796		A/R			Complete
ASL SLS550-28-03A *28SLA03*	TRANSMITTAL OF PARKER HANNIFIN CORPORATION -AIRBORNE AIR & FUEL PRODUCTS SERVICE LETTER NO. 41, RAPCO FLEET SUPPORT INC. OVERHAUL OF AIRBORNE FUEL PUMPS (SUPERSEDED BY SLS550-28-03A R01) **MOC :** COMPLIED WITH	SAT		MANDATORY	MTH HRS	12-Jun-1999 9403		A/R			Complete
SB S550-29-01 *29SB-01*	ECOLOGY (OVERFLOW) BOTTLE INSTALLATION **MOC :**			OPTIONAL	MTH			A/R			
SL S550-29-02 *29SL-02*	HYDRAULIC LINE INSPECTION (SUPERSEDED BY SLS550-29-02 R01) **MOC :** COMPLIED WITH	LGB		RECOMMENDED	MTH HRS	22-May-1990 1721		A/R			Complete
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES **MOC :**			INFORMATIONAL				-			
SB S550-30-11 *30SB-11*	ICE DETECTOR REPLACEMENT (SUPERSEDED BY S550-30-11 R01) **MOC :** COMPLIED WITH	CMH		RECOMMENDED	MTH HRS	20-Jul-1988 784		A/R			Complete
SB S550-30-13 *30SB-13*	WING WIRE BUNDLE ROUTING MODIFICATION **MOC :** COMPLIED WITH	CMH		RECOMMENDED	MTH HRS	18-Dec-1990 2198		A/R			Complete
SB S550-30-14 *30SB-14*	FLUID ANTI-ICE SYSTEM WING CUFF AND FAIRING PANELS INSPECTION AND PURGE CYCLE MODIFICATION (SUPERSEDED BY S550-30-14 R01) **MOC :** COMPLIED WITH	CMH		MANDATORY	MTH HRS	08-Apr-1991 2428		A/R			Complete

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-30-15	ANTI-ICE SYSTEM IMPROVEMENT			RECOMMENDED	MTH	17-Aug-1992		A/R			Complete
30SB-15		TOL			HRS	3627					
	MOC : COMPLIED WITH										
SB S550-30-16	ICE DETECTOR TEST CYCLE TIME DELAY MODIFICATION (SUPERSEDED BY S550-30-16 R01)										
30SB-16		TOL		RECOMMENDED	MTH	17-Aug-1992		A/R			Complete
					HRS	3627					
	MOC : COMPLIED WITH										
SB S550-30-17	WINDSHIELD BLEED AIR ORIFICE INSPECTION/REMOVAL (SUPERSEDED BY S550-30-17 R01)										
30SB-17		CMH		MANDATORY	MTH	09-Jul-1991		A/R			Complete
					HRS	2721					
	MOC : COMPLIED WITH										
SB S550-30-18	TKS AUXILIARY TANK SEALER REMOVAL				MTH	17-Nov-1993		A/R			Complete
30SB-18		SWF		RECOMMENDED	HRS	4796					
	MOC : COMPLIED WITH										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION										
				INFORMATIONAL				-			
	MOC :										
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL							-			
				INFORMATIONAL							
	MOC :										
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION				MTH						
				RECOMMENDED	HRS			300		13626.12	243.42
	MOC :										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION										
				INFORMATIONAL				-			
	MOC :										
SL CIL-32-06	LANDING GEAR - WIRELESS TIRE PRESSURE SENSOR FILL VALVE TORQUE VERIFICATION										
				INFORMATIONAL				-			
	MOC :										
SB S550-32-01 R02	LANDING GEAR - INSTALLATION OF CLEVELAND WHEELS AND BRAKES										
32SB-01 : S55R2		CMH		OPTIONAL	MTH	20-Jul-1988		A/R			Complete
					HRS	784					
	MOC : COMPLIED WITH										
SB S550-32-02 R02	ANTI-SKID WIRE BUNDLE ROUTING IMPROVEMENT (SUPERSEDED BY S550-32-02 R03)										
32SB-02 : S55R2		ICT		RECOMMENDED	MTH	02-Feb-1989		A/R			Complete
					HRS	1043					
	MOC : COMPLIED WITH										
SB S550-32-02	ANTI-SKID WIRE BUNDLE ROUTING IMPROVEMENT (SUPERSEDED BY S550-32-02 R01)										
32SB-02		TOL		RECOMMENDED	MTH	09-Jul-1987		A/R			Complete
					HRS	667					
	MOC : COMPLIED WITH										
SB S550-32-04	MAIN LANDING GEAR DOORS REPLACEMENT (IMPROVED SLUSH AND SNOW OPERATION) (SUPERSEDED BY S550-32-04 R01)										
32SB-04				OPTIONAL	MTH			A/R			
	MOC :										
SB S550-32-05 R01	MAIN LANDING GEAR TORQUE LINK MODIFICATION (SUPERSEDED BY S550-32-05 R02)										
32SB-05 : S55R1		CMH		MANDATORY	MTH	08-Apr-1991		A/R			Complete
					HRS	2428					
	MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-32-05	MAIN LANDING GEAR TORQUE LINK MODIFICATION (SUPERSEDED BY S550-32-05 R01)									
32SB-05		ICT		MANDATORY	MTH 26-Oct-1988 HRS 925		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-32-07	BF GOODRICH BRAKES AND WHEELS INSTALLATION (SUPERSEDED BY S550-32-07 R01)									
32SB-07				OPTIONAL	MTH		A/R			
	MOC :									
SB S550-32-08	INCREASED MAXIMUM GEAR EXTEND SPEED				MTH		A/R			
32SB-08				OPTIONAL						
	MOC :									
SB S550-32-11	BF GOODRICH BRAKE BLEEDER BLOCK INSTALLATION AND HOSE REPLACEMENT (SUPERSEDED BY S550-32-11 R01)									
32SB-11				OPTIONAL	MTH		A/R			
	MOC :									
SB S550-32-12	MAIN LANDING GEAR WHEEL WELL AFT SPAR BOX HYDRAULIC/PNEUMATIC LINES GROMMET REPLACEMENT									
32SB-12		CMH		RECOMMENDED	MTH 28-Mar-1993 HRS 4127		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-32-13	ANTISKID DRIVE CLIP REPLACEMENT			RECOMMENDED	MTH 19-Jul-1996		A/R			Complete
32SB-13		CMH			HRS 7400					
	MOC : COMPLIED WITH									
SB S550-32-15	POWER BRAKE HYDRAULIC PUMP SCREW REPLACEMENT									
32SB-15		LUK		RECOMMENDED	MTH 28-Apr-1997 HRS 8302		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-32-16	ANTISKID SYSTEM DIODE REMOVAL			RECOMMENDED	MTH 24-Dec-1997		A/R			Complete
32SB-16		LUK			HRS 8885					
	MOC : COMPLIED WITH									
SB S550-32-18 R02	LANDING GEAR ON GROUND OPERATION MODIFICATION				MTH 09-Apr-2010					
32SB-18 : S55R2		MGL		RECOMMENDED	HRS 11487 LDG 9632		300			
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!									
SB S550-32-19 R01	LANDING GEAR - PARKING BRAKE CABLE REPLACEMENT				MTH		A/R			
32SB-19 : S55R1				OPTIONAL						
	MOC :									
SB S550-32-21 R01	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS									
		UNK		RECOMMENDED	MTH 05-Apr-2023 HRS 13357.9 LDG 10821		-			N/A
	MOC : NOT APPLICABLE - TO THIS AIRCRAFT									
SB S550-32-21	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS (SUPERSEDED BY S550-32-21 R01)									
				RECOMMENDED			-			
	MOC :									
SB S550-32-22	LANDING GEAR - LANDING GEAR WARNING HORN REPLACEMENT									
				OPTIONAL			-			
	MOC :									
SL S550-32-02	MAIN LANDING GEAR WHEEL-HALF SEALS FOR COLD WEATHER OPERATION									
32SL-02				OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SL S550-32-05 *32SL-05*	NOSE GEAR STEERING LOWER JOINT BEARING INSPECTION	ICT		RECOMMENDED	MTH HRS	02-Feb-1989 1043		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-06 *32SL-06*	CLEVELAND BRAKE INSPECTION	CMH			MTH HRS	29-Jul-1988 815		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-07 *32SL-07*	MODIFICATION OF P/N 1523200-3 (CESSNA P/N 9912120) NOSE GEAR ACTUATOR	TOL		RECOMMENDED	MTH HRS	22-Apr-1988 750		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-09 *32SL-09*	MAIN LANDING GEAR PISTON AXLE ADAPTER AND AXLE CORROSION INSPECTION, REMOVAL, AND PREVENTION	ICT		RECOMMENDED	MTH HRS	31-May-1989 1213		A/R			Complete
	MOC : COMPLIED WITH										
ASL SLS550-32-10A *32SLA10*	INSPECTION OF MAIN LANDING GEAR UPPER AND LOWER TORQUE LINK CONNECTING HARDWARE	CMH		MANDATORY	MTH HRS	20-Jul-1988 784		DAILY DAILY DAILY			Complete
	MOC : COMPLIED WITH										
SL S550-32-11 *32SL-11*	UPLOCK ACTUATOR HYDRAULIC LINE INSPECTION	ICT		RECOMMENDED	MTH HRS	31-May-1989 1213		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-13 *32SL-13*	MAIN LANDING GEAR AXLE INTERNAL CORROSION INSPECTION	ICT		RECOMMENDED	MTH HRS	31-May-1989 1213		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-17 *32SL-17*	LANDING GEAR EMERGENCY EXTENSION CONTROL ASSEMBLY PIN INSPECTION	LGB		RECOMMENDED	MTH HRS	22-May-1990 1721		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-21 *32SL-21*	STRUT EXTENSION INSPECTION AND PISTON UPPER BEARING RETENTION IMPROVEMENT (SUPERSEDED BY SLS550-32-21 R01)	CMH		RECOMMENDED	MTH	05-Mar-1993		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-22 *32SL-22*	EMERGENCY LANDING GEAR BLOWDOWN BOTTLE LEVER SAFETY WIRE INSPECTION/REPLACEMENT	CMH		RECOMMENDED	MTH HRS	21-Nov-1992 3790		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-24 *32SL-24*	MAIN LANDING GEAR DRAG BRACE ATTACH NUT REPLACEMENT	CMH		RECOMMENDED	MTH HRS	13-Oct-1992 3712		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-26 *32SL-26*	NOSE AND MAIN LANDING GEAR UPLOCK SPRING INSPECTION/REPLACEMENT (SUPERSEDED BY SLS550-32-26 R01)	CMH		RECOMMENDED	MTH HRS	18-Dec-1990 2198		A/R			Complete
	MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SL S550-32-27 *32SL-27*	ANTI-SKID SYSTEM CONTROL UNIT CALIBRATION VERIFICATION	CMH		RECOMMENDED	MTH HRS	08-Apr-1991 2428		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-29 *32SL-29*	NOSE LANDING GEAR UPLOCK LINE INSPECTION	CMH		RECOMMENDED	MTH HRS	28-Mar-1993 4127		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-30 *32SL-30*	LANDING GEAR HANDLE LOCKING SOLENOID RIGGING INSPECTION	CMH		RECOMMENDED	MTH HRS	28-Mar-1993 4127		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-34 *32SL-34*	NOSE GEAR TRUNNION FINISH INSPECTION/REFINISH	CMH		RECOMMENDED	MTH HRS	28-Mar-1993 4127		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-37 *32SL-37*	BRAKE AND SPOILER/SPEEDBRAKE EXTENDED HYDRAULIC LINE(S) ROUTING INSTPECTION/MODIFICATION	CMH		RECOMMENDED	MTH HRS	13-Oct-1992 3712		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-40 *32SL-40*	CLEVELAND SERVICE BULLETIN ESB7028 BRAKE ASSEMBLY BOLT REPLACEMENT	CMH		MANDATORY	MTH HRS	22-Feb-1993 4007		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-41 R01 *32SL-41 : S55R1*	TEIJIN SEIKI MAIN AND NOSE LANDING GEAR ACTUATOR DOWN AND LOCKED SWITCH INSPECTION/ REPLACEMENT (SUPERSEDED BY SLS550-32-41 R02)	SWF		RECOMMENDED	MTH HRS	17-Nov-1993 4796		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-45 *32SL-45*	NOSE LANDING GEAR WHEEL AND TIRE ASSEMBLY AND WIDE DOOR ATTACH HARDWARE INSPECTION / REPLACEMENT *KAT UPDATED	CMH		RECOMMENDED	MTH HRS	05-Nov-1994 5718		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-46 R01 *32SL-46 : S55R1*	MAIN LANDING GEAR EXTEND PNEUMATIC LINE CLEARANCE INSPECTION	CMH		RECOMMENDED	MTH HRS	22-Feb-1996 7001		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-48 *32SL-48*	TRANSMITTAL OF PARKER HANNIFIN CORP. CLEVELAND WHEEL & BRAKES SERVICE BULLETIN SB7054 - CITATION BRAKE ASSY - BRAKE ROTOR DISC - INSPECT/REPLACE	SAT		MANDATORY	MTH HRS LDG	12-Jun-1999 9403 7929		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-32-49 *32SL-49*	TRANSMITTAL OF BFGOODRICH SERVICE LETTER SL1728 LANDING GEAR - NOSE WHEEL BALANCE WEIGHT FASTERNER PLACEMENT			RECOMMENDED	MTH HRS	05-Dec-1999 9566		A/R			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.										
SL S550-32-52 R01 *32SL-52 : S55R1*	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL	MTH			A/R			
	MOC :										

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SL S550-32-54 *32SL-54*	EMERGENCY GEAR RELEASE INSPECTION	MGL		MANDATORY	MTH 21-Jan-2010 HRS 11325		-			Complete
	MOC : COMPLIED WITH									
SL CIL-33-01	LIGHTS - TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY			INFORMATIONAL			-			
	MOC :									
SB S550-33-01 *33SB-01*	LANDING LIGHT RELOCATION (SUPERSEDED BY S550-33-01 R01)			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-33-04 R01 *33SB-04 : S55R1*	AFT CABIN PSU LIGHT WIRE REPLACEMENT (SUPERSEDED BY S550-33-04 R02)	TOL		MANDATORY	MTH 24-Feb-1988 HRS 727		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-33-04 *33SB-04*	AFT CABIN PSU LIGHT WIRE REPLACEMENT (SUPERSEDED BY S550-33-04 R01)	TOL		MANDATORY	MTH 24-Feb-1988 HRS 727		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-33-06 *33SB-06*	AFT CABIN PSU LIGHT POWER SUPPLY REPLACEMENT	CMH		RECOMMENDED	MTH 09-Sep-1989 HRS 1309		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-33-07 *33SB-07*	LANDING LIGHT ELECTRICAL CIRCUIT MODIFICATION (SUPERSEDED BY S550-33-07 R01)			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-33-08 *33SB-08*	INDIRECT LIGHTING CONNECTOR CONTACT INSPECTION/REPLACEMENT	CMH		RECOMMENDED	MTH 18-Dec-1990 HRS 2198		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-33-09 R01 *33SB-09 : S55R1*	LANDING LIGHT BULB PROTECTION (SUPERSEDED BY S550-33-09 R02)			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-33-11 R01 *33SB-11 : S55R1*	WING TIP NAV/COLLISION LIGHT MODIFICATION	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB S550-33-12 R03 *33SB-12 : S55R3*	WING TIP MOUNTED LANDING LIGHT INSTALLATION	*CF		OPTIONAL	MTH		A/R			
	MOC :									
SB S550-33-13 *33SB-13*	LANDING LIGHT CIRCUIT SWITCH MODULE INSTALLATION			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-33-14 *33SB-14*	INDIRECT LIGHTING LAMP AND CONNECTOR UPGRADE			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-33-15 R01 *33SB-15 : S55R1*	LIGHTS - EMERGENCY LIGHTING BATTERY PACK UPGRADE			OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-33-16 *33SB-16*	LED TAIL POSITION LIGHT INSTALLATION			OPTIONAL	MTH			A/R			
	MOC : - SERVICE BULLETIN ON HOLD.										
SL S550-33-03 R02 *33SL-03 : S55R2*	CABIN INDIRECT LIGHTING SYSTEM INSPECTION			RECOMMENDED	MTH HRS	05-Dec-1999 9566		A/R			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.										
SL S550-33-03 *33SL-03*	CABIN INDIRECT LIGHTING SYSTEM INSPECTION (SUPERSEDED BY SLS550-33-03 R01)	CMH		RECOMMENDED	MTH HRS	18-Dec-1990 2198		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-33-06 *33SL-06*	LANDING LIGHT SWITCH INSPECTION/REPLACEMENT (SUPERSEDED BY SLS550-33-06 R01)	CMH		MANDATORY	MTH HRS	11-Oct-1993 4711		A/R			Complete
	MOC : COMPLIED WITH										
COM MC ALL - 007	GPS/SBAS APPROACH DOWNGRADES DUE TO GEOMAGNETIC ACTIVITY			INFORMATIONAL	MTH			-			
	MOC :										
SB S550-34-17 R01 *34SB-17 : S55R1*	STATIC PORT DOUBLER INSTALLATION	TOL		RECOMMENDED	MTH HRS	09-Jul-1987 667		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-34-25 R01 *34SB-25 : S55R1*	STARTER-GENERATOR AND GCU FILTER INSTALLATION	MGL		RECOMMENDED	MTH HRS LDG	09-Apr-2010 11487 9632		300			
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!										
ASB S550-34-26 R01 *34SBA26 : S55R1*	VG14A VERTICAL GYRO INSPECTION	CMH		MANDATORY	MTH HRS	12-Mar-1990 1517		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-34-27 *34SB-27*	VN-212 SIGNAL GROUND WIRING MODIFICATION			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-34-35 *34SB-35*	COPILOT ALTIMETER INSTALLATION - KOLLSMAN			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-34-36 R02 *34SB-36 : S55R2*	NAVIGATION - REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-34-37 *34SB-37*	TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) II AND MST-67A TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-34-38 *34SB-38*	SANDEL ST3400 TAWS INSTALLATION			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-34-39 *34SB-39*	SIGMA-TEK CONTROL PANEL INSTALLATION			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-34-40	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL				-			
	MOC :										

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SL S550-34-01 *34SL-01*	COLLINS VIR-32 NAVIGATION RECEIVER SERVICE BULLETIN 14	TOL		RECOMMENDED	MTH HRS	30-Oct-1987 724		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-34-06 *34SL-06*	DORNE AND MARGOLIN DMN4-17-4 NAV ANTENNA COUPLER INSPECTION			RECOMMENDED	MTH			A/R			
	MOC :										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	YMCY		MANDATORY	MTH DAYS HRS LDG	 14-Apr-2016 13285.6 10753		-			N/A
	MOC : NOT APPLICABLE - CIL-35-05 NOT APPLICABLE DUE P/N 174045-15 CREW OXYGEN MASKS INSTALLED. PILOT S/N 07476 CO-PILOT S/N 07476										
SB S550-35-03 R01 *35SB-03 : S55R1*	EROS OXYGEN MASK INSTALLATION			OPTIONAL	MTH			A/R			
	MOC :										
SB S550-35-04 *35SB-04*	CHAFING PROTECTION INSTALLATION OF TAILCONE LINES AND WIRE BUNDLES (SUPERSEDED BY S550-35-04 R01)	LUK		RECOMMENDED	MTH HRS	06-May-1996 7200		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-35-03	OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH			A/R			
	MOC :										
SL S550-35-04 R01	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	EDLN		MANDATORY	MTH HRS LDG	28-Mar-2013 12903 10486		-			N/A
	MOC : NOT APPLICABLE - BY MODELS INSTALLED (NO INFLATABLE HARNESSES)										
SL S550-35-04	TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240 (SUPERSEDED BY SLS550-35-04 R01)			MANDATORY				-			
	MOC :										
SB S550-36-02 *36SB-02*	DOOR SEAL PLUMBING INSPECTION AND MODIFICATION	SWF		RECOMMENDED	MTH HRS	17-Nov-1993 4796		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-36-04 R01 *36SB-04 : S55R1*	ENGINE BLEED AIR CONNECTOR IMPROVEMENT	LUK		OPTIONAL	MTH HRS	09-Aug-1998 9202		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-36-05 *36SB-05*	DOOR SEAL VALVE REPLACEMENT			OPTIONAL	MTH			A/R			
	MOC :										
ASL S550-52-03	DOORS - EMERGENCY EXIT INSPECTION	MGL		MANDATORY	DAYS HRS LDG	28-Jan-2012 12456 10191		A/R			Complete
	MOC : COMPLIED WITH - INSPECTED FOUND OK										
SB S550-52-02 *52SB-02*	ENTRY STEP ASSEMBLY IMPROVEMENT (SUPERSEDED BY S550-52-02 R01)	ICT		RECOMMENDED	MTH HRS	05-Nov-1986 402		A/R			Complete
	MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-52-04	TAILCONE BAGGAGE DOOR RESTRAINT CABLE INSTALLATION										
52SB-04		CMH		OPTIONAL	MTH	22-Feb-1993		A/R			Complete
					HRS	4007					
	MOC : COMPLIED WITH										
SB S550-52-05	BAGGAGE DOOR POSITIVE SAFETY LOCK INSTALLATION (SUPERSEDED BY S550-52-05 R01)										
52SB-05		CMH		RECOMMENDED	MTH	15-Jan-1990		A/R			Complete
					HRS	1473					
	MOC : COMPLIED WITH										
SB S550-52-06	WIDE DOOR INSTALLATION (SUPERSEDED BY S550-52-06 R01)										
52SB-06				OPTIONAL	MTH			A/R			
	MOC :										
SB S550-52-08	WIDE DOOR RETRACT CABLE MODIFICATION (SUPERSEDED BY S550-52-08 R01)										
52SB-08				OPTIONAL	MTH			A/R			
	MOC :										
SB S550-52-09	ENTRY DOOR STEP CATCH COVER INSTALLATION (WITH STANDARD DOOR AND STEP)										
52SB-09		MGL		RECOMMENDED	MTH	09-Apr-2010					
					HRS	11487		300			
					LDG	9632					
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!										
SL S550-52-01	NOSE AND TAILCONE BAGGAGE DOOR INSPECTION				MTH	02-Feb-1989		A/R			Complete
52SL-01		ICT		RECOMMENDED	HRS	1043					
	MOC : COMPLIED WITH										
SL S550-52-02	EMERGENCY EXIT INNER HANDLE ATTACH SCREW INSPECTION/REPLACEMENT										
52SL-02		CMH		MANDATORY	MTH	21-Apr-1992		A/R			Complete
					HRS	3295					
	MOC : COMPLIED WITH										
SB S550-53-01	TAILCONE BALLAST INSTALLATION (SUPERSEDED BY S550-53-01 R01)										
53SB-01				OPTIONAL	MTH			A/R			
	MOC :										
SB S550-53-05 R01	TAILCONE BAGGAGE COMPARTMENT GUSSET INSPECTION/INSTALLATION (SUPERSEDED BY S550-53-05 R02)										
53SB-05 : S55R1		TOL		RECOMMENDED	MTH	17-Aug-1992		A/R			Complete
					HRS	3627					
	MOC : COMPLIED WITH										
SB S550-53-08	FRAME BRACE INSPECTION/INSTALLATION (SUPERSEDED BY S550-53-08 R01)										
53SB-08		SWF		RECOMMENDED	MTH	17-Nov-1993		A/R			Complete
					HRS	4796					
	MOC : COMPLIED WITH										
SB S550-53-09	CABIN INTERIOR ATTACH/CONTACT POINT CORROSION PROTECTION (SUPERSEDED BY S550-53-09 R01)										
53SB-09		SWF		RECOMMENDED	MTH	17-Nov-1993		A/R			Complete
					HRS	4796					
	MOC : COMPLIED WITH										
SB S550-53-10	FLIGHT CREW SEAT RAIL AND BEAM RIVETS INSPECTION/INSTALLATION										
53SB-10		MKE		RECOMMENDED	MTH	03-Mar-1995		A/R			Complete
					HRS	6000					
	MOC : COMPLIED WITH										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-53-11	DORSAL FIN INSTALLATION AND MATERIAL IMPROVEMENT										
53SB-11		ICT		OPTIONAL	MTH HRS	20-Jun-1997 8398		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-53-12	MAP COMPARTMENT ASSEMBLY INSPECTION/REPLACEMENT										
53SB-12		MKE		RECOMMENDED	MTH HRS	03-Mar-1995 6000		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-53-14	AN3-5A BOLT INSPECTION/REPLACEMENT				MTH	12-Jun-1999		A/R			Complete
53SB-14		SAT		RECOMMENDED	HRS	9403					
	MOC : COMPLIED WITH										
SB S550-53-15	FUSELAGE MOISTURE DRAIN INSTALLATION				MTH			A/R			
53SB-15				OPTIONAL							
	MOC :										
SB S550-53-16	FUSELAGE - MAIN CARRY-THRU LUG INSPECTION				MTH	23-Feb-2001		A/R			Complete
53SB-16		HRZ		RECOMMENDED	HRS	10038					
	MOC : COMPLIED WITH										
SB S550-53-17	WHEEL WELL BOX/SKIN GAP IMPROVEMENT				MTH			A/R			
53SB-17				OPTIONAL							
	MOC :										
SL S550-53-01	NOSE BAGGAGE AND TAILCONE ACCESS DOOR LATCH INSPECTION										
53SL-01		MCO		RECOMMENDED	MTH HRS	13-Jan-1987 481		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-53-03	DORSAL FIN VANE INSPECTION			RECOMMENDED	MTH	09-Apr-2010					
53SL-03		MGL			HRS LDG	11487 9632		300			
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!										
SL S550-53-04 R01	INTERCOSTAL DRAINAGE PATH INSPECTION				MTH	09-Apr-2010					
53SL-04 : S55R1		MGL		RECOMMENDED	HRS LDG	11487 9632		150			
	MOC : DEFERRED - OWNER DOESE NOT WISH TO COMPLY AT THIS TIME!										
SL S550-55-01 R01	RUDDER TORQUE TUBE INTERNAL CORROSION INSPECTION										
55SL-01 : S55R1		BAF		RECOMMENDED	MTH HRS	19-Nov-1990 2122		A/R			Complete
	MOC : COMPLIED WITH										
SL S550-55-01	RUDDER TORQUE TUBE INTERNAL CORROSION INSPECTION (SUPERSEDED BY SLS550-55-01 R1)										
55SL-01		CMH		RECOMMENDED	MTH HRS	18-Dec-1990 2198		A/R			Complete
	MOC : COMPLIED WITH										
SB S550-57-01	RIGHT WING ACCESS PANEL INSTALLATION				MTH			A/R			
57SB-01				OPTIONAL							
	MOC :										
SB S550-57-02	VORTEX GENERATOR REMOVAL (SUPERSEDED BY S550-57-02 R01)										
57SB-02				OPTIONAL	MTH			A/R			
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB S550-57-03 *57SB-03*	FLAP ACTUATOR UPPER BELLCRANK BRACKET REPLACEMENT (SUPERSEDED BY S550-57-03 R01)	TOL		RECOMMENDED	MTH 17-Aug-1992 HRS 3627		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-57-06 R01 *57SB-06 : S55R1*	STUB WING DOUBLER INSTALLATION			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-57-06 *57SB-06*	STUB WING DOUBLER INSTALLATION (SUPERSEDED BY S550-57-06 R01)			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-57-07 *57SB-07*	FLAP PROTECTOR INSTALLATION (SUPERSEDED BY S550-57-07 R01)			OPTIONAL	MTH		A/R			
	MOC :									
SB S550-57-09 *57SB-09*	FLAP VENT HOLES INSTALLATION	CMH		RECOMMENDED	MTH 16-Mar-1998 HRS 9092		A/R			Complete
	MOC : COMPLIED WITH									
ASL SLS550-57-01A *57SLA01*	FLAP DRAIN HOLE INSPECTION	MDT		MANDATORY	MTH 02-Jun-1988 HRS 775		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-57-02 *57SL-02*	AILERON EXTERNAL BALANCE WEIGHT INSPECTION	ICT		RECOMMENDED	MTH 31-May-1989 HRS 1213		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-71-01 *71SL-01*	JT15D-4B MINIMUM FUEL FLOW ADJUSTMENT	LEX		RECOMMENDED	MTH 05-Jun-1987 HRS 645		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-71-02 *71SL-02*	ENGINE BREATHER TUBE EXTENSION	LEX		OPTIONAL	MTH 15-Feb-1988 HRS 727		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-72-04 *72SL-04*	IMPROVED RETENTION OF P3 AIR-TO-FUEL CONTROL BOSS	TOL		RECOMMENDED	MTH 30-Oct-1987 HRS 724		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-72-05 *72SL-05*	JT15D FAN BLADE INSPECTION	LEX		RECOMMENDED	MTH 20-May-1987 HRS 628		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-72-06 R01 *72SL-06 : S55R1*	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R02)	CMH		RECOMMENDED	MTH 20-Jul-1988 HRS 784		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-72-06 R02 *72SL-06 : S55R2*	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R03)	ICT		RECOMMENDED	MTH 23-Sep-1988 HRS 886		A/R			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SL S550-72-06 *72SL-06*	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R01)	TOL		RECOMMENDED	MTH 24-Feb-1988 HRS 727		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-72-07 *72SL-07*	LOW COMPRESSOR CASE DAMPENING RING INSTALLATION (SUPERSEDED BY SLS550-72-07 R01)	ICT		RECOMMENDED	MTH 23-Sep-1988 HRS 886		A/R			Complete
	MOC : COMPLIED WITH									
ASL SLS550-72-09A LEFT ENGINE *72SLA09 : S550L*	JT15D-4B HIGH TURBINE BLADE SHAFT (CANCELLED)	ICT		CANCELLED	MTH 26-Oct-1988 HRS 925		A/R			Complete
	MOC : COMPLIED WITH									
ASL SLS550-72-09A RIGHT ENGINE *72SLA09 : S550R*	JT15D-4B HIGH TURBINE BLADE SHAFT (CANCELLED)	ICT		CANCELLED	MTH 26-Oct-1988 HRS 925		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-72-11 R01 *72SL-11 : S55R1*	JT15D-4B HIGH TURBINE BLADE SHIFT	SMF		RECOMMENDED	MTH 24-Jan-1992 HRS 3146		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-72-11 *72SL-11*	JT15D-4B HIGH TURBINE BLADE SHIFT (SUPERSEDED BY SLS550-72-11 R01)	CMH		RECOMMENDED	MTH 17-Sep-1991 HRS 2917		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-72-19 *72SL-19*	TRANSMITTAL OF P&WC SERVICE LETTER JT15D-023 REPLACEMENT OF OIL PUMP PLUG			RECOMMENDED	MTH 05-Dec-1999 HRS 9566		A/R			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.									
SB JT15D-72-7001 R25 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R26)			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7001 R25 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R26)			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7001 R26 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R27)			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7001 R26 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R27)			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7001 R27 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7001 R27 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED			-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB JT15D-72-7002 R42 E1	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY SB 72-7002 R43)			CATEGORY 3			A/R			
	MOC :									
SB JT15D-72-7002 R42 E2	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY SB 72-7002 R43)			CATEGORY 3			A/R			
	MOC :									
SB JT15D-72-7002 R43 E1	SERVICE LIVES - ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R43 E2	SERVICE LIVES - ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R44 E1	SERVICE LIVES ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R44 E2	SERVICE LIVES ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R45 E1	ROTOR COMPONENTS - SERVICE LIVES			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R45 E2	ROTOR COMPONENTS - SERVICE LIVES			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R46 E1	SERVICE LIVES ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R46 E2	SERVICE LIVES ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7003 R35 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R36)						-			
	MOC :									
SB JT15D-72-7003 R35 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R36)						-			
	MOC :									
SB JT15D-72-7003 R36 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R37)						-			
	MOC :									
SB JT15D-72-7003 R36 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R37)						-			
	MOC :									

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB JT15D-72-7003 R37 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						(SUPERSEDED BY SB 72-7003 R38) -			
	MOC :									
SB JT15D-72-7003 R37 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						(SUPERSEDED BY SB 72-7003 R38) -			
	MOC :									
SB JT15D-72-7003 R38 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						(SUPERSEDED BY SB 72-7003 R39) -			
	MOC :									
SB JT15D-72-7003 R38 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						(SUPERSEDED BY SB 72-7003 R39) -			
	MOC :									
SB JT15D-72-7003 R40 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7003 R40 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7003 R41 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
	MOC :									
SB JT15D-72-7003 R41 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
	MOC :									
SB JT15D-72-7003 R42 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
	MOC :									
SB JT15D-72-7003 R42 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY						-			
	MOC :									
SB JT15D-72-7144 R20 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING						-			
	MOC :									
SB JT15D-72-7144 R20 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING						-			
	MOC :									
SB JT15D-72-7144 R21 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7144 R21 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
	MOC :									

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB JT15D-72-7144 R22 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7144 R22 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7244 R05 E1	LOW TURBINE DISK AND TURBINE SHAFT ASSEMBLY - IMPROVED DURABILITY			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7244 R05 E2	LOW TURBINE DISK AND TURBINE SHAFT ASSEMBLY - IMPROVED DURABILITY			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7288 R04 E1	REPLACEMENT OF OVERSPEED CONTROL WIRE ROPE			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7288 R04 E2	REPLACEMENT OF OVERSPEED CONTROL WIRE ROPE			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7292 R01 E1	INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS			CATEGORY 4			-			
	MOC :									
SB JT15D-72-7292 R01 E2	INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS			CATEGORY 4			-			
	MOC :									
SB JT15D-72-7293 R10 E1	INTRODUCTION OF IMPROVED HIGH TURBINE ROTOR BLADE (DIRECTIONALLY SOLIDIFIED)			CATEGORY 4			-			
	MOC :									
SB JT15D-72-7293 R10 E2	INTRODUCTION OF IMPROVED HIGH TURBINE ROTOR BLADE (DIRECTIONALLY SOLIDIFIED)			CATEGORY 4			-			
	MOC :									
SB JT15D-72-7364 R03 E1	CONVERSION OF JT15D-4 ENGINE TO JT15D-4B CONFIGURATION			CATEGORY 8			-			
	MOC :									
SB JT15D-72-7364 R03 E2	CONVERSION OF JT15D-4 ENGINE TO JT15D-4B CONFIGURATION			CATEGORY 8			-			
	MOC :									
SB JT15D-72-7459 R01 E1	REPLACEMENT OF IGNITER (SUPERSEDED BY SB 72-7459 R02)			CATEGORY 8			A/R			
	MOC :									
SB JT15D-72-7459 R01 E2	REPLACEMENT OF IGNITER (SUPERSEDED BY SB 72-7459 R02)			CATEGORY 8			A/R			
	MOC :									
SB JT15D-72-7459 R02 E1	REPLACEMENT OF IGNITER			CATEGORY 8			-			
	MOC :									

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB JT15D-72-7459 R02 E2	REPLACEMENT OF IGNITER			CATEGORY 8			-			
	MOC :									
SB JT15D-72-7522 R06 E1	MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY SB 72-7522 R07)			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7522 R06 E2	MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY SB 72-7522 R07)			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7522 R07 E1	MODIFICATION OF GAS GENERATOR CASE			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7522 R07 E2	MODIFICATION OF GAS GENERATOR CASE			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7565 R01 E1	REPLACEMENT OF UPPER TOWER SHAFT DUPLEX BEARING			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7565 R01 E2	REPLACEMENT OF UPPER TOWER SHAFT DUPLEX BEARING			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7588 R02 E1	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			CATEGORY 8			-			
	MOC :									
SB JT15D-72-7588 R02 E2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			CATEGORY 8			-			
	MOC :									
SB JT15D-72-7589 R01 E1	HIGH TURBINE DISC BALANCING ASSEMBLY - REPLACEMENT OF			CATEGORY 8			-			
	MOC :									
SB JT15D-72-7589 R01 E2	HIGH TURBINE DISC BALANCING ASSEMBLY - REPLACEMENT OF			CATEGORY 8			-			
	MOC :									
SB JT15D-72-7618 R02 E1	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
	MOC :									
SB JT15D-72-7618 R02 E2	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
	MOC :									
SB JT15D-72-7618 R03 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
	MOC :									
SB JT15D-72-7618 R03 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
	MOC :									

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB JT15D-72-7621 R01 E1	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7621 R01 E2	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7625 R01 E1	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7625 R01 E2	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7625 E1	REPLACEMENT OF GASKET (SUPERSEDED BY SB 72-7625 R01)			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7625 E2	REPLACEMENT OF GASKET (SUPERSEDED BY SB 72-7625 R01)			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7627 E1	LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL -REPLACEMENT OF			CATEGORY 6			-			
	MOC :									
SB JT15D-72-7627 E2	LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL -REPLACEMENT OF			CATEGORY 6			-			
	MOC :									
SB JT15D-72-7633 E1	ALTERNATE SOURCE RETAINING RING			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7633 E2	ALTERNATE SOURCE RETAINING RING			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7634 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7634 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7636 R01 E1	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7636 R01 E2	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7636 E1	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7636 E2	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7			-			
	MOC :									

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB JT15D-72-7639 R01 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R02)	YBSU		CATEGORY 3	MTH HRS LDG	14-Mar-2022 13345.4 10814		-			N/A
	MOC : NOT APPLICABLE - N/A AT COMPANY CONVENIENCE										
SB JT15D-72-7639 R01 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R02)			CATEGORY 3	MTH HRS			400		13435.97	53.27
	MOC :										
SB JT15D-72-7639 R02 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 3				-			
	MOC :										
SB JT15D-72-7639 R02 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 3				-			
	MOC :										
SB JT15D-72-7639 R03 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB JT15D-72-7639 R03 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB JT15D-72-7639 R04 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB JT15D-72-7639 R04 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 7				-			
	MOC :										
SB JT15D-72-7639 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)			CATEGORY 4				-			
	MOC :										
SB JT15D-72-7639 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)			CATEGORY 4				-			
	MOC :										
SB JT15D-72-7640 E1	REPLACEMENT OF SHIPPING PLUG			CATEGORY 7				-			
	MOC :										
SB JT15D-72-7640 E2	REPLACEMENT OF SHIPPING PLUG			CATEGORY 7				-			
	MOC :										
SB JT15D-72-7642 R01 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 10				-			
	MOC :										
SB JT15D-72-7642 R01 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 10				-			
	MOC :										
SB JT15D-72-7642 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 9				-			
	MOC :										

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SB JT15D-72-7642 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS **MOC :**			CATEGORY 9			-			
SB JT15D-72-7643 E1	REPLACEMENT OF SHIPPING CONTAINER **MOC :**			CATEGORY 7			-			
SB JT15D-72-7643 E2	REPLACEMENT OF SHIPPING CONTAINER **MOC :**			CATEGORY 7			-			
SB JT15D-72-7644 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS **MOC :**			CATEGORY 7			-			
SB JT15D-72-7644 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS **MOC :**			CATEGORY 7			-			
SB JT15D-72-7655 R01 E1	INSPECTION OF - TURBOFAN ENGINE IMPELLER REAR FACE **MOC :**			CATEGORY 3			HSI			
SB JT15D-72-7655 R01 E2	INSPECTION OF - TURBOFAN ENGINE IMPELLER REAR FACE **MOC :**			CATEGORY 3			HSI			
SB JT15D-72-7655 E1	INSPECTION OF IMPELLER REAR FACE **MOC :**			CATEGORY 3			-			
SB JT15D-72-7655 E2	INSPECTION OF IMPELLER REAR FACE **MOC :**			CATEGORY 3			-			
SB JT15D-72-7656 E1	MODIFICATION OF IMPELLER **MOC :**			CATEGORY 7			-			
SB JT15D-72-7656 E2	MODIFICATION OF IMPELLER **MOC :**			CATEGORY 7			-			
SB JT15D-72-7659 E1	INTRODUCTION OF NUT INTERCHANGEABILITY CONTROL (IC) NUMBER **MOC :**			CATEGORY 9			-			
SB JT15D-72-7659 E2	INTRODUCTION OF NUT INTERCHANGEABILITY CONTROL (IC) NUMBER **MOC :**			CATEGORY 9			-			
ASB S550-73-01A R03 *73SBA01 : S55R3*	9912031-6 FUEL FLOW TRANSMITTER INSPECTION **MOC :** COMPLIED WITH	BAF			MTH 19-Nov-1990 HRS 2122		N/A			Complete
ASB S550-73-01A *73SBA01*	9912031-6 FUEL FLOW TRANSMITTER INSPECTION (SUPERSEDED BY S550-73-01A R01) **MOC :** COMPLIED WITH	CMH		MANDATORY	MTH 09-Sep-1989 HRS 1309		A/R			Complete
SB S550-73-02 R01 *73SB-02 : S55R1*	9912031-6 FUEL FLOW TRANSMITTER THREAD INSPECTION **MOC :** COMPLIED WITH	BAF		MANDATORY	MTH 19-Nov-1990 HRS 2122		A/R			Complete

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SL CIL-74-01 R01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE	EDLN		MANDATORY	DAYS 12-Sep-2013 HRS 13137.92 LDG 10651		-			Complete
	MOC : COMPLIED WITH									
SL CIL-74-01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE (SUPERSEDED BY CIL-74-01 R01)			MANDATORY	DAYS		-			
	MOC :									
SL S550-74-02 *74SL-02*	IGNITION - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 7567R1 TURBOFAN ENGINE IGNITER BOX GROUNDING STRAP - INTRODUCTION OF	HRZ		RECOMMENDED	MTH 23-Feb-2001 HRS 10038		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-78-04 *78SB-04*	EXHAUST - THRUST REVERSER THROTTLE LOAD LIMITER MODIFICATION (SUPERSEDED BY S550-78-04 R01)	TOL		RECOMMENDED	MTH 17-Aug-1992 HRS 3627		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-78-05 *78SB-05*	EXHAUST - THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT			OPTIONAL	MTH		A/R			
	MOC :									
SL S550-78-02 *78SL-02*	THRUST REVERSER JUNCTION BOX MODIFICATION (SUPERSEDED BY SLS550-78-02 R01)	TOL		RECOMMENDED	MTH 09-Jul-1987 HRS 667		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-78-04 R02 *78SL-04 : S55R2*	THRUST REVERSER DOOR MODIFICATION	CMH		RECOMMENDED	MTH 17-Sep-1991 HRS 2917		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-78-04 *78SL-04*	THRUST REVERSER DOOR MODIFICATION (SUPERSEDED BY SLS550-78-04 R01)	CMH		RECOMMENDED	MTH 15-Jan-1990 HRS 1473		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-78-05 *78SL-05*	THRUST REVERSER SYSTEM OPERATIONAL TEST (SUPERSEDED BY SLS550-78-05 R01)	SMF		RECOMMENDED	MTH 08-Aug-1990 HRS 1897		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-78-08 *78SL-08*	THRUST REVERSER STANG FAIRING SUPPORT FORMER REPLACEMENT	MKE		RECOMMENDED	MTH 03-Mar-1995 HRS 6000		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-78-10 R01 *78SL-10 : S55R1*	TRANSMITTAL OF NORDAM SERVICE BULLETIN CITSII 78-12 R1, EXHAUST - THRUST REVERSER - REPLACEMENT OF THRUST REVERSER STANG FAIRING SUPPORT FORMER	ICT		RECOMMENDED	MTH 20-Jun-1997 HRS 8398		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-79-01 *79SL-01*	NEW OIL FILLER NECK ASSEMBLY	LGB		RECOMMENDED	MTH 22-May-1990 HRS 1721		A/R			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Service Bulletins

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
SIL GEN-153 R09 E1	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SIL GEN-153 R09 E2	P&WC'S OIL ANALYSIS TECHNOLOGY SERVICE LOGISTICS INFORMATION			INFORMATIONAL			-			
	MOC :									
SB S550-80-01 *80SB-01*	STARTING - REPLACEMENT OF SUPPRESSION DIODE WITH TRANSZORB			OPTIONAL MTH			A/R			
	MOC :									
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
	MOC :									
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
	MOC :									
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
	MOC :									
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
	MOC :									
SL CIL-99-05 REV 1	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL MTH			-			
	MOC :									
SL CIL-99-05	MISCELLANEOUS - INSTALLATION OF CESSNA VARIANT PART NUMBERS			INFORMATIONAL			-			
	MOC :									

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
CASA AD/GAS/1 AMDT 10 PARA (1)	EMPTY APPLICABLE COMPRESSED GAS SYLINDERS, INSPECT THE GAS CYLINDER ASSEMBLY, INCLUDING THE VALVE; HYDROSTATICALLY TEST AND UPDATE MARKING TO CONFORM WITH THIER MANUFACTURER'S AUSTRALIAN STANDARDS OR DOT SPECIFICATIONS EXCEPT AS VARIED IN PARAGRAPH 1									
		YMCY		MANDATORY	MTH 14-Apr-2016 HRS 13285.6 LDG 10753		-			N/A
	MOC : NOT APPLICABLE - AD/GAS/1 AMDT 10 NOT APPLICABLE AS AIRCRAFT IS NOT PART 42 THIS REQUIREMENT IS NOW COVERED BY CAO 100.5 APPX 1 CLAUSE 15									
CASA AD/GAS/1 AMDT 10 PARA (2)	INSPECT AND TEST VALVE AND/OR REGULATOR IN ACCORDACE WITH MANUFACTURER'S SPECIFICATIONS. IF NO MANUFACTURER'S SPECIFICATION IS AVAILABLE THEN THE VALVE IS TO BE INSPECTED IN ACCORDANCE WITH AS2337.1-2004 PARA 10.2.2									
		YMCY		MANDATORY	MTH 14-Apr-2016 HRS 13285.6 LDG 10753		-			N/A
	MOC : NOT APPLICABLE - AD/GAS/1 AMDT 10 NOT APPLICABLE AS AIRCRAFT IS NOT PART 42 THIS REQUIREMENT IS NOW COVERED BY CAO 100.5 APPX 1 CLAUSE 15									
CASA AD/GAS/1 AMDT 10 PARA (3)	RETIRE CYLINDER FROM SERVICE	YMCY		MANDATORY	MTH 14-Apr-2016 HRS 13285.6 LDG 10753		-			N/A
	MOC : NOT APPLICABLE - AD/GAS/1 AMDT 10 NOT APPLICABLE AS AIRCRAFT IS NOT PART 42 THIS REQUIREMENT IS NOW COVERED BY CAO 100.5 APPX 1 CLAUSE 15									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
CASA AD/GAS/1 AMDT 10 PARA (4)	RENDER CYLINDERS WHICH DO NOT COMPLY WITH THEIR SCHEDULED INSPECTION LIMITS OR TEST REQUIREMENTS UNFIT FOR FURTHER USE IN ACCORDANCE WITH AS2030	YMCY		MANDATORY	MTH 14-Apr-2016 HRS 13285.6 LDG 10753		-			N/A
	MOC : NOT APPLICABLE - AD/GAS/1 AMDT 10 NOT APPLICABLE AS AIRCRAFT IS NOT PART 42 THIS REQUIREMENT IS NOW COVERED BY CAO 100.5 APPX 1 CLAUSE 15									
CASA AD/GAS/1 AMDT 10	APPLIANCE AD - COMPRESSED GAS CYLINDERS - INSPECTION, TEST AND RETIREMENT	YMCY		MANDATORY	MTH 14-Apr-2016 HRS 13285.6 LDG 10753		-			N/A
	MOC : NOT APPLICABLE - AD/GAS/1 AMDT 10 NOT APPLICABLE AS AIRCRAFT IS NOT PART 42 THIS REQUIREMENT IS NOW COVERED BY CAO 100.5 APPX 1 CLAUSE 15									
CASA AD/GAS/1 AMDT 11 PARA (1)	EMPTY APPLICABLE COMPRESSED GAS SYLINDERS, INSPECT THE GAS CYLINDER ASSEMBLY, INCLUDING THE VALVE; HYDROSTATICALLY TEST AND UPDATE MARKING TO CONFORM WITH THIER MANUFACTURER'S AUSTRALIAN STANDARDS OR DOT SPECIFICATIONS EXCEPT AS VARIED IN PARAGRAPH 1			MANDATORY	MTH		-			
	MOC :									
CASA AD/GAS/1 AMDT 11 PARA (2)	INSPECT AND TEST VALVE AND/OR REGULATOR IN ACCORDACE WITH MANUFACTURER'S SPECIFICATIONS. IF NO MANUFACTURER'S SPECIFICATION IS AVAILABLE THEN THE VALVE IS TO BE INSPECTED IN ACCORDANCE WITH AS2337.1-2004 PARA 10.2.2			MANDATORY	MTH		-			
	MOC :									
CASA AD/GAS/1 AMDT 11 PARA (3)	RETIRE CYLINDER FROM SERVICE			MANDATORY	MTH		-			
	MOC :									
CASA AD/GAS/1 AMDT 11 PARA (4)	RENDER CYLINDERS WHICH DO NOT COMPLY WITH THEIR SCHEDULED INSPECTION LIMITS OR TEST REQUIREMENTS UNFIT FOR FURTHER USE IN ACCORDANCE WITH AS2030			MANDATORY			-			
	MOC :									
CASA AD/GAS/1 AMDT 11	APPLIANCE AD - COMPRESSED GAS CYLINDERS - INSPECTION, TEST AND RETIREMENT (SUPERSEDED BY CASA AD/GAS/1 AMDT 12)			MANDATORY	MTH		-			
	MOC :									
CASA AD/GAS/1 AMDT 12 PARA (1)	EMPTY APPLICABLE COMPRESSED GAS CYLINDERS, INSPECT THE GAS CYLINDER ASSEMBLY, INCLUDING THE VALVE; HYDROSTATICALLY TEST AND UPDATE MARKING TO CONFORM WITH THE APPLICABLE MANUFACTURER'S, AUSTRALIAN STANDARDS (AS) OR UNITED STATES DEPARTMENT OF TRANSPORTATION (DOT) SPECIFICATIONS EXCEPT AS VARIED IN PARAGRAPH 1			MANDATORY	MTH		-			
	MOC :									
CASA AD/GAS/1 AMDT 12 PARA (2)	INSPECT AND TEST VALVE AND/OR REGULATOR IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS. IF NO MANUFACTURER'S SPECIFICATION ARE AVAILABLE THEN THE VALVE IS TO BE INSPECTED IN ACCORDANCE WITH AS2337.1-2004 PARA 10.2.2, AS IN FORCE FROM TIME TO TIME.			MANDATORY	MTH		-			
	MOC :									
CASA AD/GAS/1 AMDT 12 PARA (3)	RETIRE CYLINDER FROM SERVICE			MANDATORY	MTH		-			
	MOC :									
CASA AD/GAS/1 AMDT 12 PARA (4)	RENDER CYLINDERS WHICH DO NOT COMPLY WITH THEIR SCHEDULED INSPECTION LIMITS OR TEST REQUIREMENTS UNFIT FOR FURTHER USE IN ACCORDANCE WITH AS2030, AS IN FORCE FROM TIME TO TIME.			MANDATORY	MTH		-			
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
CASA AD/GAS/1 AMDT 12	APPLIANCE AD - COMPRESSED GAS CYLINDERS - INSPECTION, TEST AND RETIREMENT			MANDATORY	MTH		-			
	MOC :									
CASA CAO 100.5 APPX 1 CLAUSE 15	RECHARGEABLE COMPRESSED GAS CYLINDERS REGULATOR/ VALVE INSPECTION	YPAD		MANDATORY	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		36		01-Jul-2024	-24 m 23 d Complete **Over Due**
	MOC : COMPLIED WITH - CYLINDER REFITTED AFTER INSP/TEST IAW S550 MM 35-11-00 ROTOR POWER ARC # OB-41495 REFERS. REGULATOR LEFT IN OFF POSITION REFER TASK #217									
CASA CAO 100.5 APPX 1 CLAUSE 12	TOWING RELEASE SYSTEMS	YPAD		MANDATORY	MTH 21-Apr-2016 HRS 13285.6 LDG 10753		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, EQUIPMENT NOT INSTALLED									
CASA CAO 100.5 APPX 1 CLAUSE 16	COMBUSTION TYPE HEATERS	YPAD		MANDATORY	MTH 21-Apr-2016 HRS 13285.6 LDG 10753		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, EQUIPMENT NOT INSTALLED									
FAA 1990-07-10 *21AD-01*	TO PREVENT FAILURE OF THE ELEVATOR OR RUDDER CONTROL CABLES	CMH		SUPERSEDED	MTH 13-May-1990 HRS 1695		-			Complete
	MOC : COMPLIED WITH									
FAA 1993-05-15 *78AD-01*	MODIFY THE THRUST REVERSER THROTTLE LOAD LIMITER	CMH		MANDATORY	MTH 20-Apr-1993 HRS 4199		A/R			Complete
	MOC : COMPLIED WITH									
FAA 1995-25-10 *21AD-02*	REPLACEMENT OF OUTFLOW/SAFETY VALVES WITH SERVICEABLE VALVES.	CMH		MANDATORY	MTH 22-Feb-1996 HRS 7001		A/R			Complete
	MOC : COMPLIED WITH									
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	EDLN		MANDATORY	DAYS 27-Aug-2013 HRS 13114 LDG 10637		-			N/A
	MOC : NOT APPLICABLE - BY MOTOR PN:ES61108-1									
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A\C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	EDLN		MANDATORY	DAYS 27-Aug-2013 HRS 13114 LDG 10637		-			N/A
	MOC : NOT APPLICABLE - BY MOTOR PN:ES61108-1									
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION	EDLN		MANDATORY	MTH 27-Aug-2013 HRS 13114 LDG 10637		-			N/A
	MOC : NOT APPLICABLE - BY MOTOR PN:ES61108-1									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM	EDLN	MANDATORY		MTH 27-Aug-2013 HRS 13114 LDG 10637		A/R			N/A
	MOC : NOT APPLICABLE - BY MOTOR PN:ES61108-1									
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM	EDLN	MANDATORY		MTH 27-Aug-2013 HRS 13114 LDG 10637		A/R			N/A
	MOC : NOT APPLICABLE - BY MOTOR PN:ES61108-1									
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS	EDLN	MANDATORY		MTH 27-Aug-2013 HRS 13114 LDG 10637		-			N/A
	MOC : NOT APPLICABLE - BY MOTOR PN:ES61108-1									
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM	EDLN	MANDATORY		MTH 27-Aug-2013 HRS 13114 LDG 10637		-			N/A
	MOC : NOT APPLICABLE - BY MOTOR PN:ES61108-1									
FAA 2015-17-12 PARA (G)	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED	YBSU	MANDATORY		DAYS 11-Jan-2016 HRS 13282.8 LDG 10746		-			N/A
	MOC : NOT APPLICABLE - INSPECTION OF A/C COMPRESSOR MOTOR CARRIED OUT P/N FWA1134104-1 OR -5 NOT INSTALLED, THEREFORE FAA AD 2015-17-12 NOT APPLICABLE									
FAA 2015-17-12 PARA (H)	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND	YBSU	MANDATORY		MTH DAYS 11-Jan-2016 HRS 13282.8 LDG 10746		-			N/A
	MOC : NOT APPLICABLE - INSPECTION OF A/C COMPRESSOR MOTOR CARRIED OUT P/N FWA1134104-1 OR -5 NOT INSTALLED, THEREFORE FAA AD 2015-17-12 NOT APPLICABLE									
FAA 2015-17-12 PARA (I)	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)	YBSU	MANDATORY		MTH 11-Jan-2016 HRS 13282.8 LDG 10746		-			N/A
	MOC : NOT APPLICABLE - INSPECTION OF A/C COMPRESSOR MOTOR CARRIED OUT P/N FWA1134104-1 OR -5 NOT INSTALLED, THEREFORE FAA AD 2015-17-12 NOT APPLICABLE									
FAA 2015-17-12 PARA (K)	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)	YBSU	MANDATORY		MTH 11-Jan-2016 HRS 13282.8 LDG 10746		-			N/A
	MOC : NOT APPLICABLE - INSPECTION OF A/C COMPRESSOR MOTOR CARRIED OUT P/N FWA1134104-1 OR -5 NOT INSTALLED, THEREFORE FAA AD 2015-17-12 NOT APPLICABLE									

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
FAA 2015-17-12 PARA (L)	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE	YBSU	MANDATORY		MTH HRS LDG	11-Jan-2016 13282.8 10746	-				N/A
	MOC : NOT APPLICABLE - INSPECTION OF A/C COMPRESSOR MOTOR CARRIED OUT P/N FWA1134104-1 OR -5 NOT INSTALLED, THEREFORE FAA AD 2015-17-12 NOT APPLICABLE										
FAA 2015-17-12 PARA (M)	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY	YBSU	MANDATORY		MTH DAYS HRS LDG	 11-Jan-2016 13282.8 10746	-				N/A
	MOC : NOT APPLICABLE - INSPECTION OF A/C COMPRESSOR MOTOR CARRIED OUT P/N FWA1134104-1 OR -5 NOT INSTALLED, THEREFORE FAA AD 2015-17-12 NOT APPLICABLE										
FAA 2015-17-12	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA	YBSU	MANDATORY		MTH HRS LDG	11-Jan-2016 13282.8 10746	-				N/A
	MOC : NOT APPLICABLE - INSPECTION OF A/C COMPRESSOR MOTOR CARRIED OUT P/N FWA1134104-1 OR -5 NOT INSTALLED, THEREFORE FAA AD 2015-17-12 NOT APPLICABLE										
LBA D-2013-181	AIR CONDITIONING - AIR CONDITIONING A/C COMPRESSOR MOTOR - INSPECTION / REPLACEMENT		MANDATORY		MTH		-				
	MOC :										
LBA D-2015-223	AIR CONDITIONING - BRUSHES IN THE AIR CONDITIONING COMPRESSOR MOTOR ASSEMBLY - INSPECTIONS / REPLACEMENT	YBSU	MANDATORY		MTH HRS LDG	11-Jan-2016 13282.8 10746	-				N/A
	MOC : NOT APPLICABLE - INSPECTION OF A/C COMPRESSOR MOTOR CARRIED OUT P/N FWA1134104-1 OR -5 NOT INSTALLED, THEREFORE FAA AD 2015-17-12 NOT APPLICABLE										
CASA CAO 100.5 APPX 1 CLAUSE 9	MAINTENANCE OF COCKPIT VOICE RECORDERS SYSTEMS	UNK	MANDATORY		MTH HRS LDG	02-Dec-2022 13355.2 10819	12			02-Dec-2023 **Over Due**	-31 m 22 d Complete
	MOC : COMPLIED WITH										
LBA D-2013-235	APPLIANCE AD - EMERGENCY LOCATOR TRANSMITTER - BATTERY WIRING INSTALLATION DISCREPANCIES		MANDATORY		MTH		-				
	MOC :										
LBA D-2014-116	APPLIANCE AD - COMMUNICATIONS - COCKPIT VOICE RECORDER - REPLACEMENT	YBSU	MANDATORY		MTH HRS LDG	11-Jan-2016 13282.8 10746	-				N/A
	MOC : NOT APPLICABLE - EASA AD 2014-0088 (1) FOUND NOT APPLICABLE AS FAIRCHILD GA100 CVR INSTALLED										
FAA 1988-06-02	ELECTRICAL POWER		MANDATORY				-				
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
CASA AD/EMY/2 AMDT 07	APPLIANCE AD - INSPECT AND TEST LIFE JACKETS AND INFLATABLE FLOTATION DEVICES			MANDATORY	MTH 09-Feb-2022 HRS 13343.9 LDG 10812		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE DUE TO COMPONENTS NOT INSTALLED.									
CASA AD/EMY/4 AMDT 07	APPLIANCE AD - INSPECT AND TEST LIFE RAFTS	YMCY		MANDATORY	MTH 14-Apr-2016 HRS 13285.6 LDG 10753		-			N/A
	MOC : NOT APPLICABLE - AD/EMY/4 AMDT 7 NOT APPLICABLE AS AIRCRAFT IS NOT PART 42 THIS REQUIREMENT IS NOW COVERED BY CAO 100.5 APPX 1 CLAUSE 11									
CASA AD/RES/20 AMDT 01	APPLIANCE AD - EON CORPORATION E6000 BUCKLE ASSEMBLIES			MANDATORY	MTH		-			
	MOC :									
CASA CAO 100.5 APPX 1 CLAUSE 11 (1)	LIFE RAFTS	BNE		MANDATORY	MTH 16-Nov-2017 HRS 13315.6 LDG 10794		-			N/A
	MOC : NOT APPLICABLE - LIFE RAFTS NOT FITTED.									
CASA CAO 100.5 APPX 1 CLAUSE 11 (2)	LIFE JACKETS AND INFLATABLE FLOTATION DEVICES			MANDATORY	MTH 09-Feb-2022 HRS 13343.9 LDG 10812		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE NO FLOATATION DEVICES ON AIRCRAFT.									
FAA 1987-03-15 *25AD-01*	SUPERSEDED BY AD 1988-24-16	LEX		SUPERSEDED	MTH 04-Feb-1987 HRS 516		-			Complete
	MOC : COMPLIED WITH									
FAA 1988-24-16 *25AD-03*	TO PRECLUDE WIRING FAILURE, WHICH CAN RESULT IN CABIN SMOKE AND/OR FIRE	ICT		MANDATORY	MTH 14-Dec-1988 HRS 987		A/R			Complete
	MOC : COMPLIED WITH									
FAA 1989-06-01 *25AD-04*	APPLIANCE AD - TO PREVENT THE IMPROPER FUNCTIONING OF THE CO2 INFLATORS	ICT		MANDATORY	MTH 31-May-1989 HRS 1213		A/R			Complete
	MOC : COMPLIED WITH									
FAA 1998-25-10 *25AD-07*	APPLIANCE AD - TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM	SAT		MANDATORY	MTH 12-Jun-1999 HRS 9403		A/R			Complete
	MOC : COMPLIED WITH									
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	YPAD			MTH 01-Jul-2021 HRS 13322.6 LDG 10796		-			N/A
	MOC : NOT APPLICABLE									
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	YPAD		MANDATORY	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		-			N/A
	MOC : NOT APPLICABLE									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	YPAD	MANDATORY	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		-				N/A
	MOC : NOT APPLICABLE - FOUND NOT APPLICABLE AS ARTEX PNO 453-5000-(218) SNO 01927 ELT FOUND FITTED.									
FAA 2021-07-13 PARA (E)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE		MANDATORY	MTH		-				
	MOC :									
FAA 2021-07-13 PARA (E)(2)	MEASURE THE THICHNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE		MANDATORY	MTH		-				
	MOC :									
FAA 2021-07-13 PARA (E)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER		MANDATORY			-				
	MOC :									
FAA 2021-07-13	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT		MANDATORY			-				
	MOC :									
FAA 2024-26-02 PARA (G)(1)	INSPECT THE BUCKLE HANDLE FOR A CRACK AND IF CRACKED, BEFORE FURTHER FLIGHT, REPLACE IT WITH AN AIRWORTHY BUCKLE		MANDATORY	MTH		6			07-Sep-2025	-10 m 17 d **Over Due**
	MOC :									
FAA 2024-26-02 PARA (G)(2)	MEASURE THE THICHNESS OF THE BUCKLE HANDLE VANE; IF THICKNESS IS 0.125 INCH OR GREATER, BEFORE FURTHER FLIGHT, REMOVE THE BUCKLE FROM SERVICE AND REPLACE IT WITH AN AIRWORTHY BUCKLE		MANDATORY	MTH		12			07-Mar-2026	-4 m 17 d **Over Due**
	MOC :									
FAA 2024-26-02 PARA (G)(3)	DO NOT INSTALL A BUCKLE OR RESTRAINT SYSTEM WITH A BUCKLE P/N 1111430 OR 1111475, ALL DASH NUMBERS, WITH A HANDLE VANE THICKNESS OF 0.125 INCH OR GREATER		MANDATORY			-				
	MOC :									
FAA 2024-26-02	APPLIANCE AD - EQUIPMENT AND FURNISHING - SEAT RESTRAINT SYSTEM PLASTIC ROTARY BUCKLE HANDLE - INSPECTION/REPLACEMENT		MANDATORY			-				
	MOC :									
LBA D-2012-237 R01 PARA (A)	FIRE PROTECTION IN LAVATORIES INSTALL PLACARDS		MANDATORY			-				
	MOC :									
LBA D-2012-237 R01 PARA (B)	FIRE PROTECTION IN LAVATORIES ANNOUNCMENT PROCEDURES		MANDATORY			-				
	MOC :									
LBA D-2012-237 R01 PARA (C)	FIRE PROTECTION IN LAVATORIES ASHTRAY INSTALLATION		MANDATORY			-				
	MOC :									
LBA D-2012-237 R01 PARA (D)	FIRE PROTECTION IN LAVATORIES ALLOWANCES OF PARTIALLY MISSING OR INOPERATIVE ASHTRAYS		MANDATORY	MTH		A/R				
	MOC :									
LBA D-2012-237 R01 PARA (E)	FIRE PROTECTION IN LAVATORIES INSPECTIONS		MANDATORY	MTH HRS		1000			13928.1	545.4
	MOC :									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
LBA D-2012-237 R01 PARA (F)	FIRE PROTECTION IN LAVATORIES FIRE PROTECTING CHARACTERISTICS OF THE LAVATORY EQUIPMENT			MANDATORY			-			
	MOC :									
LBA D-2012-237 R01 PARA (G)	FIRE PROTECTION IN LAVATORIES FIRE/SMOKE ALARM SYSTEMS OR FIRE EXTINGUISHING SYSTEMS			MANDATORY			-			
	MOC :									
LBA D-2012-237 R01 PARA (H)	FIRE PROTECTION IN LAVATORIES OCCURRENCE REPORTS			MANDATORY			-			
	MOC :									
LBA D-2012-237 R01	APPLIANCE AD - FIRE PROTECTION IN LAVATORIES			MANDATORY	MTH		-			
	MOC :									
LBA D-2013-041 R01	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT (SUPERSEDED BY D-2013-041 R02)	EDLN		MANDATORY	MTH 27-Aug-2013 HRS 13114 LDG 10637		-			N/A
	MOC : NOT APPLICABLE - BY APPENDIX LIST									
LBA D-2013-041 R02	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT (SUPERSEDED BY D-2013-041 R03)	EDLN		MANDATORY	MTH 27-Aug-2013 HRS 13114 LDG 10637		-			N/A
	MOC : NOT APPLICABLE - BY APPENDIX LIST									
LBA D-2013-041	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELTS / TORSO RESTRAINT SYSTEMS - INSPECTION / REPLACEMENT (SUPERSEDED BY D-2013-041 R01)	EDLN		MANDATORY	MTH 27-Aug-2013 HRS 13114 LDG 10637		-			N/A
	MOC : NOT APPLICABLE - BY APPENDIX LIST									
LBA D-2014-026 R01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT (SUPERSEDED BY D-2014-026 R02)			MANDATORY			-			
	MOC :									
LBA D-2014-026 R02	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT			MANDATORY			-			
	MOC :									
LBA D-2014-026	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR - MODIFICATION AIRCRAFT FLIGHT MANUAL - AMENDMENT (SUPERSEDED BY D-2014-026 R01)			MANDATORY	MTH		-			
	MOC :									
LBA D-2014-149	APPLIANCE AD - EQUIPMENT / FURNISHINGS - CRASH POSITION INDICATOR SYSTEM - REPLACEMENT / AIRCRAFT FLIGHT MANUAL - AMENDMENT			MANDATORY			-			
	MOC :									
LBA D-2014-223	APPLIANCE AD - EQUIPMENT & FURNISHINGS - SAFETY BELT ATTACHMENT BOLTS - INSPECTION / REPLACEMENT			MANDATORY			-			
	MOC :									
LBA D-2015-027	APPLIANCE AD - EQUIPMENT / FURNISHING - RESTRAINT SYSTEM ROTARY BUCKLE SUB-ASSEMBLY - IDENTIFICATION / REPLACEMENT			MANDATORY	MTH		-			
	MOC :									

NOTE: Item Codes in *italics* show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
FAA 2001-22-14 *26AD-01*	APPLIANCE AD - TO PREVENT DAMAGE TO FIRE EXTINGUISHING SYSTEM COMPONENTS CAUSED BY A FIRE EXTINGUISHING SYSTEM BOTTLE CARTRIDGE ACTIVATING WITH EXCESSIVE ENERGETIC	PIM		MANDATORY	MTH HRS	09-Sep-2004 10186		A/R			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2006-04-10 *26AD-02*	SUPERSEDED BY 2007-11-17	MGL		SUPERSEDED	MTH HRS LDG	15-Oct-2010 11820 9816		-			N/A
	MOC : NOT APPLICABLE - N/A BY INSTALLED EQUIPMENT.										
FAA 2007-11-17 *26AD-06*	ENSURE FIRE EXTINGUISHING BOTTLES ARE ACTIVATED IN THE EVENT OF AN ENGINE OR APU FIRE	DLN		MANDATORY	MTH HRS	25-Jan-2008 10881		A/R			Complete
	MOC : COMPLIED WITH										
FAA 2010-04-16 PARA (G) *26AD-07*	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT			MANDATORY	DAYS HRS LDG	15-Oct-2010 11820 9816		A/R			N/A
	MOC : NOT APPLICABLE - N/A BY INSTALLED EQUIPMENT.										
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI	MGL		MANDATORY	MTH HRS LDG	15-Oct-2010 11820 9816		A/R			N/A
	MOC : NOT APPLICABLE - N/A BY INSTALLED EQUIPMENT.										
FAA 2006-06-03 *28AD-02*	PREVENT FUEL VAPOR IGNITION	FXE		MANDATORY	MTH HRS	23-Aug-2006 10545		A/R			Complete
	MOC : COMPLIED WITH										
CASA AD/REC/1 AMDT 03	APPLIANCE AD - CHECK AND FUNCTIONALLY TEST THE COCKPIT VOICE RECORDING INSTALLATION			MANDATORY	MTH			-			
	MOC :										
CASA AD/REC/1 AMDT 04	APPLIANCE AD - CHECK AND FUNCTIONALLY TEST THE COCKPIT VOICE RECORDING INSTALLATION	YMCY		MANDATORY	MTH HRS LDG	14-Apr-2016 13285.6 10753		-			N/A
	MOC : NOT APPLICABLE - AD/REC/1 AMDT 4 NOT APPLICABLE AS AIRCRAFT IS NOT PART 42 THIS REQUIREMENT IS NOW COVERED BY CAO 100.5 APPX 1 CLAUSE 9 NEXT DUE 11-NOV-16										
CASA AD/REC/1 AMDT 05	APPLIANCE AD - MAINTENANCE OF COCKPIT VOICE RECORDING SYSTEMS			MANDATORY	MTH			-			
	MOC :										
CASA AD/REC/1 AMDT 2	CHECK AND FUNCTIONALLY TEST THE COCKPIT VOICE RECORDING INSTALLATION.			MANDATORY	MTH HRS	11-Nov-2015 13282.8		-			Complete
	MOC : COMPLIED WITH										
FAA 2021-23-12	APPLIANCE AD - INDICATING / RECORDING / NAVIGATION - RADIO (RADAR) ALTIMETER - AFM REVISION TO INCORPORATE LIMITATIONS	YBSU		MANDATORY	MTH HRS LDG	14-Mar-2022 13345.4 10814		-			N/A
	MOC : NOT APPLICABLE - N/A DUE AUSTRALIAN AIRSPACE										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)	QRCB		MANDATORY	MTH 18-Jul-2023 HRS 13379.2 LDG 10843		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE NOT OPERATED IN THE USA.									
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)	QRCB		MANDATORY	MTH 18-Jul-2023 HRS 13379.2 LDG 10843		-			N/A
	MOC : NOT APPLICABLE - N/A A/C NOT OPERATED IN USA									
FAA 2023-10-02	APPLIANCE AD - INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION	QRCB		MANDATORY	MTH 18-Jul-2023 HRS 13379.2 LDG 10843		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE NOT OPERATED IN THE USA.									
FAA 2026-13-02 PARA (H)	AIRPLANE FLIGHT MANUAL (AFM) REVISION			MANDATORY	MTH		BF/F BF/F			New Req
	MOC :									
FAA 2026-13-02	APPLIANCE AD - NAVIGATION - OPERATIONAL LIMITATIONS IN CANADA DUE TO 5G C-BAND WIRELESS BROADBAND INTERFERENCE			MANDATORY	MTH		-			
	MOC :									
TCCA CF-2024-14 PART III	TERMINATING ACTION FOR AFM LIMITATIONS			MANDATORY			-			
	MOC :									
TCCA CF-2024-14 PART II	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM			MANDATORY	MTH		DUE DUE		29-May-2024	-25 m 25 d **Over Due**
	MOC :									
FAA 1988-13-03 R01 *32AD-02 : S55R1*	TO PREVENT LOSS OF CONTROL OF THE AIRPLANE DURING LANDING OR TAKEOFF DUE TO FAILURE OF THE COTTER PINS SECURING THE MAIN LANDING GEAR TORQUE LINK CONNECTIONS	ICT		MANDATORY	MTH 31-May-1989 HRS 1213		A/R			Complete
	MOC : COMPLIED WITH									
FAA 1988-13-03 *32AD-02*	TO PREVENT LOSS OF CONTROL OF THE AIRPLANE DURING LANDING OR TAKEOFF DUE TO FAILURE OF THE COTTER PINS SECURING THE MAIN LANDING GEAR TORQUE LINK CONNECTIONS (SUPERSEDED BY 1988-13-03 R01)	CMH		SUPERSEDED	MTH 20-Jul-1988 HRS 784		-			Complete
	MOC : COMPLIED WITH									
FAA 1990-07-08 *33AD-02*	APPLIANCE AD - SUPERSEDED BY AD 1990-07-08 R1	CMH		SUPERSEDED	MTH 18-Dec-1990 HRS 2198		-			Complete
	MOC : COMPLIED WITH									
FAA 1990-14-06 *33AD-03*	APPLIANCE AD - SUPERSEDED BY AD 1995-22-01	CMH		SUPERSEDED	MTH 05-Sep-1990 HRS 1948		-			Complete
	MOC : COMPLIED WITH									
FAA 1995-22-01 *33AD-04*	APPLIANCE AD - TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK AND POSSIBLE ELECTROMAGNETIC INTERFERENCE CAUSED BY HIGH VOLTAGE ARCING	LNN		MANDATORY	MTH 07-Dec-1995 HRS 6803		A/R			Complete
	MOC : COMPLIED WITH									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
CASA AD/RAD/47 AMDT 03	APPLIANCE AD - PERIODIC TESTING OF ATC TRANSPONDERS			MANDATORY	MTH			-			
	MOC :										
CASA AD/RAD/47 AMDT 04	APPLIANCE AD - PERIODIC TESTING OF ATC TRANSPONDERS	YMCY		MANDATORY	MTH HRS LDG	14-Apr-2016 13285.6 10753		-			N/A
	MOC : NOT APPLICABLE - AD/RAD/47 AMDT 4 NOT APPLICABLE AS AIRCRAFT IS NOT PART 42 THIS REQUIREMENT IS NOW COVERED BY CAO 100.5 APPX 1 CLAUSE 14 NEXT DUE 4-FEB-17										
CASA CAO 100.5 APPX 1 CLAUSE 14	PERIODIC TESTING OF ATC TRANSPONDERS	UNK		MANDATORY	MTH HRS LDG	05-Apr-2023 13357.9 10821		24		05-Apr-2025 **Over Due**	-15 m 19 d Complete
	MOC : COMPLIED WITH										
EASA 2024-0024	APPLIANCE AD - NAVIGATION - DIGITAL AIR DATA COMPUTER - REPLACEMENT			MANDATORY	MTH			12		07-Feb-2025 **Over Due**	-17 m 17 d
	MOC :										
FAA 1990-03-02 *34AD-01*	APPLIANCE AD - SUPERSEDED BY AD 1990-06-13	CMH		SUPERSEDED	MTH HRS	12-Mar-1990 1517		-			Complete
	MOC : COMPLIED WITH										
FAA 1990-06-13 *34AD-02*	APPLIANCE AD - TO PREVENT ERRONEOUS ATTITUDE DISPLAY	CMH		MANDATORY	MTH HRS	24-Mar-1990 1557		A/R			Complete
	MOC : COMPLIED WITH										
FAA 1998-25-02 *34AD-06*	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS	SAT		MANDATORY	MTH HRS	12-Jun-1999 9403		A/R			Complete
	MOC : COMPLIED WITH										
FAA 2001-23-17 *34AD-26*	APPLIANCE AD - TO PREVENT INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT	PIM		MANDATORY	MTH HRS	09-Sep-2004 10186		A/R			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2003-13-08 *34AD-13*	APPLIANCE AD - TERRAIN AWARENESS WARNING SYSTEMS (TAWS)	PIM		MANDATORY	MTH HRS	16-Sep-2004 10194		A/R			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2004-08-15 *34AD-14*	APPLIANCE AD - CORRECTION: GOODRICH AVIONICS SYSTEMS,INC TAWS8000 TERRAIN AWARENESS WARNING SYSTEM	PIM		MANDATORY	MTH HRS	16-Sep-2004 10194		A/R			Complete
	MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
FAA 2006-16-18 *34AD-34*	APPLIANCE AD - SUPERSEDED BY AD 2006-16-18 R01	FXE		SUPERSEDED	MTH HRS	27-Apr-2007 10668		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE-EQUIPMENT NOT INSTALLED										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
FAA 2014-05-27	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. TPR-720 AND TPR-900 MODE S TRANSPONDERS - TEST AND CALIBRATION	YMCY		MANDATORY	MTH 14-Apr-2016 HRS 13285.6 LDG 10753		-			N/A
	MOC : NOT APPLICABLE - AD 2014-05-07 NOT APPLICABLE DUE TO EQUIPMENT INSTALLED									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION			MANDATORY	MTH		-			
	MOC :									
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.			MANDATORY	MTH		-			
	MOC :									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS			MANDATORY			-			
	MOC :									
FAA 2025-07-01	APPLIANCE AD - THOMMEN AIRCRAFT EQUIPMENT AG (THOMMEN) AC32 DIGITAL AIR DATA COMPUTERS (ADCS)			MANDATORY	MTH		12		15-May-2026	-2 m 9 d **Over Due**
	MOC :									
LBA D-2006-331 R01	APPLIANCE AD - CANCELLED: NAVIGATION SYSTEMS - MODE S AND C TRANSPONDERS - CHECK (SUPERSEDED BY D-2006-331 R02)			CANCELLED			-			
	MOC :									
LBA D-2006-331 R02	APPLIANCE AD - CANCELLED: NAVIGATION SYSTEMS - MODE S AND C TRANSPONDERS - CHECK			MANDATORY			-			
	MOC :									
LBA D-2010-011 R01	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDER AIRCRAFT TYPE MODE STRAPPING - CHECK / MODIFICATION			MANDATORY	MTH		-			
	MOC :									
LBA D-2014-120 R01	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDERS - TEST / CALIBRATION			MANDATORY			-			
	MOC :									
LBA D-2014-120	APPLIANCE AD - NAVIGATION - MODE S TRANSPONDERS - TEST / CALIBRATION (SUPERSEDED BY D-2014-120 R01)			MANDATORY			-			
	MOC :									
LBA D-2015-116	APPLIANCE/EMERGENCY AD - AIRPLANE FLIGHT MANUAL (SUPPLEMENT) - AMENDMENT			MANDATORY	MTH		-			
	MOC :									
LBA D-2015-130	APPLIANCE AD - NAVIGATION - ATTITUDE HEADING REFERENCE SYSTEM - MODIFICATION / REPLACEMENT			MANDATORY	MTH		-			
	MOC :									
TCCA CF-2023-46 PART III	AFM REVISION AFTER 30 JUNE 2023	QRCB		MANDATORY	MTH 18-Jul-2023 HRS 13379.2 LDG 10843		-			N/A
	MOC : NOT APPLICABLE - N/A A/C NOT OPERATED IN USA									
TCCA CF-2023-46 PART II	AIRPLANE/AIRCRAFT FLIGHT MANUAL (AFM) REVISION UNTIL 30 JUNE 2023	QRCB		MANDATORY	MTH 18-Jul-2023 HRS 13379.2 LDG 10843		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE NOT OPERATED IN THE USA.									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
TCCA CF-2023-46	APPLIANCE AD - NAVIGATION - AEROPLANE - PROHIBITION OF OPERATIONS REQUIRING RADIO ALTIMETER WHEN OPERATING IN THE CONTIGUOUS UNITED STATES DUE TO 5G C-BAND WIRELESS BROADBAND INTERFERENCE	QRCB		MANDATORY	MTH HRS LDG	18-Jul-2023 13379.2 10843		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE NOT OPERATED IN THE USA.										
TCCA CF-2024-14	APPLIANCE AD - NAVIGATION - AEROPLANE - LIMITATIONS OF OPERATIONS WITH NON-TOLERANT RADIO ALTIMETER WHEN OPERATING IN CANADA DUE TO 5G C-BAND WIRELESS BROADBAND INTERFERENCE			MANDATORY				-			
	MOC :										
EASA 2025-0222	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS			MANDATORY	DAYS			30		19-Nov-2025	-8 m 5 d **Over Due**
	MOC :										
EASA 2025-0297 PARA (1)	REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD			MANDATORY	DAYS			-			
	MOC :										
EASA 2025-0297 PARA (2)	ACCOMPLISHMENT OF THE ACTION AS REQUIRED BY PARA (1) OF THIS AD CAN BE DEFERRED IN ACCORDANCE WITH THE APPLICABLE INSTRUCTIONS AND LIMITATIONS OF THE APPLICABLE AIRCRAFT MMEL ITEMS, PROVIDED THAT THOSE MMEL ITEMS ARE INCLUDED IN THE OPERATOR APPROVED MEL, AND THAT THE MINIMUM REQUIRED INSTALLED PBES ARE CONFIRMED NOT AFFECTED BY THIS AD				MTH			-			
				MANDATORY							
	MOC :										
EASA 2025-0297 PARA (3)	PART INSTALLATION: STARTING FROM THE APPLICABILITY DATE AS IDENTIFIED IN TABLE 1 OF THIS AD, AS APPLICABLE, DEPENDING ON PBE LOCATION, DO NOT INSTALL AN AFFECTED PBE ON ANY AIRCRAFT			MANDATORY	DAYS			-			
	MOC :										
EASA 2025-0297 PARA (4)	LIFE LIMIT: REMOVE FROM SERVICE			MANDATORY	MTH			-			
	MOC :										
EASA 2025-0297 R01 PARA (1)	REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD			MANDATORY	DAYS			14		20-Jan-2026	-6 m 4 d **Over Due**
	MOC :										
EASA 2025-0297 R01 PARA (2)	ACCOMPLISHMENT OF THE ACTION AS REQUIRED BY PARA (1) OF THIS AD CAN BE DEFERRED IN ACCORDANCE WITH THE APPLICABLE INSTRUCTIONS AND LIMITATIONS OF THE APPLICABLE AIRCRAFT MMEL ITEMS, PROVIDED THAT THOSE MMEL ITEMS ARE INCLUDED IN THE OPERATOR APPROVED MEL, AND THAT THE MINIMUM REQUIRED INSTALLED PBES ARE CONFIRMED NOT AFFECTED BY THIS AD				MTH			-			
				MANDATORY							
	MOC :										
EASA 2025-0297 R01 PARA (3)	PART INSTALLATION: STARTING FROM THE APPLICABILITY DATE AS IDENTIFIED IN TABLE 1 OF THIS AD, AS APPLICABLE, DEPENDING ON PBE LOCATION, DO NOT INSTALL AN AFFECTED PBE ON ANY AIRCRAFT			MANDATORY	DAYS			14			
	MOC :										
EASA 2025-0297 R01 PARA (4)	LIFE LIMIT: REMOVE FROM SERVICE			MANDATORY	MTH			120			
	MOC :										
EASA 2025-0297 R01	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE			MANDATORY	MTH			-			New Req
	MOC :										
EASA 2025-0297	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE			MANDATORY	MTH			-			
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
FAA 1994-19-06 *35AD-01*	APPLIANCE AD - TO PREVENT THE FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING	CMH		MANDATORY	MTH 07-Nov-1994 HRS 5724		A/R			Complete
	MOC : COMPLIED WITH									
FAA 1999-08-21 *35AD-02*	APPLIANCE AD - TO PREVENT REDUCED OXYGEN CONSUMPTION WHEN PASSENGERS ARE REQUIRED TO USE DEFECTIVE OXYGEN MASKS	SAT		MANDATORY	MTH 12-Jun-1999 HRS 9403		A/R			Complete
	MOC : COMPLIED WITH									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	YBSU		MANDATORY	MTH 08-Nov-2016 HRS 13303.1 LDG 10775		-			N/A
	MOC : NOT APPLICABLE - FAA AD 2016-11-20 FOUND TO BE NO APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12	YBSU		MANDATORY	MTH 08-Nov-2016 HRS 13303.1 LDG 10775		-			N/A
	MOC : NOT APPLICABLE - FAA AD 2016-11-20 FOUND TO BE NO APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12	YBSU		MANDATORY	MTH 08-Nov-2016 HRS 13303.1 LDG 10775		-			N/A
	MOC : NOT APPLICABLE - FAA AD 2016-11-20 FOUND TO BE NO APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12	YBSU		MANDATORY	MTH 08-Nov-2016 HRS 13303.1 LDG 10775		-			N/A
	MOC : NOT APPLICABLE - FAA AD 2016-11-20 FOUND TO BE NO APPLICABLE DUE TO EQUIPMENT NOT INSTALLED.									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	YPAD		MANDATORY	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		-			N/A
	MOC : NOT APPLICABLE									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	YPAD		MANDATORY	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		-			N/A
	MOC : NOT APPLICABLE									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	YPAD		MANDATORY	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		-			N/A
	MOC : NOT APPLICABLE									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No	C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	YPAD	MANDATORY	MTH 01-Jul-2021 HRS 13322.6 LDG 10796		-				N/A
	MOC : NOT APPLICABLE - FOUND TO BE NA BY MANUFACTURER, PURITAN-BENNET AERO SYSTEMS CO. 2 X PART NO 174045-15, SERIAL NO 07476 & NOT KNOWN AS LABEL MISSING.									
FAA 2025-25-02	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - OPERATIONAL INSTRUCTIONS		MANDATORY	DAYS		-				
	MOC :									
FAA 2025-26-06	APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT		MANDATORY	DAYS			30		13-Feb-2026	-5 m 11 d **Over Due**
	MOC :									
FAA 2026-03-09 PARA (G) EASA (1)	REPLACE THE AFFECTED PBE WITH A PBE NOT AFFECTED BY THIS AD		MANDATORY	DAYS			14		26-Mar-2026	-3 m 28 d **Over Due**
	MOC :									
FAA 2026-03-09 PARA (G) EASA (2)	ACCOMPLISHMENT OF THE ACTION AS REQUIRED BY PARA (1) OF THIS AD CAN BE DEFERRED IN ACCORDANCE WITH THE APPLICABLE INSTRUCTIONS AND LIMITATIONS OF THE APPLICABLE AIRCRAFT MMEL ITEMS, PROVIDED THAT THOSE MMEL ITEMS ARE INCLUDED IN THE OPERATOR APPROVED MEL, AND THAT THE MINIMUM REQUIRED INSTALLED PBES ARE CONFIRMED NOT AFFECTED BY THIS AD				MTH		-			
			MANDATORY							
	MOC :									
FAA 2026-03-09 PARA (G) EASA (3)	PART INSTALLATION: STARTING FROM THE APPLICABILITY DATE AS IDENTIFIED IN TABLE 1 OF THIS AD, AS APPLICABLE, DEPENDING ON PBE LOCATION, DO NOT INSTALL AN AFFECTED PBE ON ANY AIRCRAFT		MANDATORY	DAYS			14			
	MOC :									
FAA 2026-03-09 PARA (G) EASA (4)	LIFE LIMIT: REMOVE FROM SERVICE		MANDATORY	MTH			120			
	MOC :									
FAA 2026-03-09	APPLIANCE AD - OXYGEN - PORTABLE BREATHING EQUIPMENT - REMOVAL FROM SERVICE		MANDATORY	MTH			-			
	MOC :									
LBA D-2012-445 R01	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT		MANDATORY	MTH 28-Mar-2013 HRS 12903 LDG 10486			-			N/A
	MOC : NOT APPLICABLE - P/N MODELS INSTALLED (NO INFLATABLE HARNESSES)									
LBA D-2012-445	APPLIANCE AD - OXYGEN - FLIGHT CREW OXYGEN MASK REGULATOR - IDENTIFICATION / OPERATIONAL PROCEDURE / REPLACEMENT (SUPERSEDED BY D-2012-445 R01)	EDLN	MANDATORY	MTH 28-Mar-2013 HRS 12903 LDG 10486			-			N/A
	MOC : NOT APPLICABLE - P/N MODELS INSTALLED (NO INFLATABLE HARNESSES)									
LBA D-2014-164	APPLIANCE AD - OXYGEN - OXYGEN MASK REGULATOR INFLATABLE HARNESS / INFLATION HOSE - IDENTIFICATION / REPLACEMENT		MANDATORY				-			
	MOC :									
CASA AD/GENERAL/37 AMDT 10	APPLIANCE AD - EMERGENCY EXITS	YMCY	MANDATORY	MTH 14-Apr-2016 HRS 13285.6 LDG 10753			-			N/A
	MOC : NOT APPLICABLE - AD/GEN/37 AMDT 10 NOT APPLICABLE AS AIRCRAFT IS NOT PART 42 THIS REQUIREMENT IS NOW COVERED BY CAO 100.5 APPX 1 CLAUSE 10									

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
CASA CAO 100.5 APPX 1 CLAUSE 10	EMERGENCY EXITS	UNK		MANDATORY	MTH HRS LDG	05-Apr-2023 13357.9 10821		6		05-Oct-2023	-33 m 19 d Complete **Over Due**
	MOC : COMPLIED WITH										
FAA 1988-11-07 *57AD-01*	TO PREVENT LOSS OF A FLAP PANEL	MDT		MANDATORY	MTH HRS	02-Jun-1988 775		A/R			Complete
	MOC : COMPLIED WITH										
CASA CAO 100.5 APPX 1 CLAUSE 7	WOODEN PROPELLERS - INSPECTIONS	YPAD		MANDATORY	MTH HRS LDG	21-Apr-2016 13285.6 10753		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, EQUIPMENT NOT INSTALLED										
CASA CAO 100.5 APPX 1 CLAUSE 8	FEATHERING PROPELLERS - FUNCTIONAL CHECK	YPAD		MANDATORY	MTH HRS LDG	21-Apr-2016 13285.6 10753		-			N/A
	MOC : NOT APPLICABLE - NOT APPLICABLE, EQUIPMENT NOT INSTALLED										
AD 72-01	JT15D FAN BLADE INSP	LEX			MTH HRS	20-May-1987 628		-			Complete
	MOC : COMPLIED WITH										
AD 72-03	HP TURB. BLADE SHIFT	CMH			MTH HRS	29-Apr-1991 2497		-			Complete
	MOC : COMPLIED WITH										
AD 72-04	GAS GEN CASE INSP	CMH			MTH HRS	17-Sep-1991 2917		-			Complete
	MOC : COMPLIED WITH										
FAA 1993-18-08 E1	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693	CEL		MANDATORY	MTH HRS	21-Jun-2007 9390.5		-			Complete
	MOC : COMPLIED WITH										
FAA 1993-18-08 E2	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693	CEL		MANDATORY	MTH HRS	21-Jun-2007 9561.9		-			Complete
	MOC : COMPLIED WITH										
TCCA CF-2022-27 PARA (A) E1	PERFORM A ONE-TIME INSPECTION ON THE BACK FACE OF THE IMPELLER;' IF ANY UNACCEPTABLE MACHINING WITNESS LINES, OR CRACK INDICATIONS ARE FOUND, BEFORE FURTHER FLIGHT, REPLACE THE IMPELLER P/N 3020365 WITH A NON-P/N 3020365 IMPELLER			MANDATORY	MTH HRS			HSI HSI HSI		13548.2	165.5
	MOC :										
TCCA CF-2022-27 PARA (A) E2	PERFORM A ONE-TIME INSPECTION ON THE BACK FACE OF THE IMPELLER;' IF ANY UNACCEPTABLE MACHINING WITNESS LINES, OR CRACK INDICATIONS ARE FOUND, BEFORE FURTHER FLIGHT, REPLACE THE IMPELLER P/N 3020365 WITH A NON-P/N 3020365 IMPELLER			MANDATORY	MTH HRS			HSI HSI HSI		13770.8	388.1
	MOC :										
TCCA CF-2022-27 PARA (C) E1	REMOVE THE IMPELLER P/N 3020365 AND REPLACE WITH A NON-P/N 3020365 IMPELLER			MANDATORY	MTH HRS			E/OVH E/OVH E/OVH		13498.8	116.1
	MOC :										

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Airworthiness Directives

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
TCCA CF-2022-27	REMOVE THE IMPELLER P/N 3020365 AND REPLACE WITH A NON-P/N 3020365 IMPELLER										
PARA (C)				MANDATORY	MTH			E/OVH			
E2					HRS			E/OVH		13670.6	287.9
								E/OVH			
	MOC :										
TCCA CF-2022-27	ENGINE - ENGINE COMPRESSOR SECTION - IMPELLER FRACTURE DUE TO MACHINING STEP										
E1				MANDATORY				-			
	MOC :										
TCCA CF-2022-27	ENGINE - ENGINE COMPRESSOR SECTION - IMPELLER FRACTURE DUE TO MACHINING STEP										
E2				MANDATORY				-			
	MOC :										

Factory Installed

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
21FO-03D	FLOOD COOLING FACTORY OPTION			21D	MTH	13-Mar-1986		-			
21FO-03 : 550/D		*CF		FO							
21FO-04A	COCKPIT AIR SUPPLEMENTAL FACTORY OPTION				MTH	13-Mar-1986		-			
21FO-04 : 550/A		*CF		179A							
				FO							
24FO-01B	BATTERY & MONITOR FOR 20 CELL FACTORY OPTION				MTH	13-Mar-1986		-			
24FO-01 : 550/B		*CF		12B							
				FO							
25FO-05J	STRGE DRAWER #3 AFT FCG SEAT LATERL TRACK FACTORY OPTION										
25FO-05 : 550/J		*CF		104J	MTH	13-Mar-1986		-			
				FO							
25FO-05L	STRGE DRAWER #4 AFT FCG SEAT LATERL TRACK FACTORY OPTION										
25FO-05 : 550/L		*CF		104L	MTH	13-Mar-1986		-			
				FO							
25FO-05M	STRGE DRAWER #5 FWD FCG SEAT LATERL TRACK FACTORY OPTION										
25FO-05 : 550/M		*CF		104M	MTH	13-Mar-1986		-			
				FO							
25FO-05N	STRGE DRAWER FWD FCG SEAT LATERAL TRACK FACTORY OPTION										
25FO-05 : 550/N		*CF		104N	MTH	13-Mar-1986		-			
				FO							
25FO-05W	STORAGE DRAWER #10 SEAT LATERAL TRACK FACTORY OPTION										
25FO-05 : 550/W		*CF		104W	MTH	13-Mar-1986		-			
				FO							
25FO-10B	CENTER CLUB SEATING FACTORY OPTION				MTH	13-Mar-1986		-			
25FO-10 : 550/B		*CF		112B							
				FO							
25FO-20U	EXECUTIVE TABLE LH USED W/CENTER CLUB FACTORY OPTION										
25FO-20 : 550/U		*CF		124U	MTH	13-Mar-1986		-			
				FO							
25FO-20V	EXECUTIVE TABLE RH USED W/CENTER CLUB FACTORY OPTION										
25FO-20 : 550/V		*CF		124V	MTH	13-Mar-1986		-			
				FO							
25FO-22B	FLUSH TOILET AFT RELIEF TUBE ONLY FACTORY OPTION				MTH	13-Mar-1986		-			
25FO-22 : 550/B		*CF		131B							
				FO							
25FO-37	CHIMES UNIT FACTORY OPTION			166	MTH	13-Mar-1986		-			
		*CF		FO							
27FO-01A	ELECTRIC TRIM SWITCH COPILOT FACTORY OPTION				MTH	13-Mar-1986		-			
27FO-01 : 550/A		*CF		33A							
				FO							
31FO-02	CLOCK DIGITAL ELECTRIC 24 HOUR RH FACTORY OPTION				MTH	13-Mar-1986		-			
		*CF		182							
				FO							

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.

CESCOM 10 - Aircraft Status Report

Owner: **GUY HINGSTON**
Aircraft Model: **S550 - CITATION SII**
Aircraft Serial: **S550-0086**
Unit: **0086** Reg No: **VH-SQM**
Airworthiness: **13-Mar-1986**
Print Date: **24-Jul-2026 1:12AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	**13382.7**	**10844**	**24-Jul-2026**	**.9**
ENG 1	**10390.2**	**7793**	**24-Jul-2026**	**.9**
ENG 2	**10188.8**	**7949**	**24-Jul-2026**	**.9**

Factory Installed

Item Code / Position	Description / Drawing # / Task #	City	Mod Lvl	Part Number / Part Serial No		C/W Time 1 / C/W Time 2	Adj. + or -	TBO 1 / TBO 2	TSO 1 / TSO 2	DUE 1 / DUE 2	Remains / Remains
33FO-02B *33FO-02 : 550/B*	LIGHT-RECOGNITION WING-TIP MOUNTED FACTORY OPTION	*CF		49B FO	MTH	13-Mar-1986		-			
34FO-03	HORIZON GYRO ELECTRIC STANDBY FACTORY OPTION	*CF		142 FO	MTH	13-Mar-1986		-			
34FO-04	LOCATOR BEACON EMERGENCY FACTORY OPTION	*CF		175 FO	MTH	13-Mar-1986		-			
34FO-07D *34FO-07 : 550/D*	2ND TRANSPONDER- COLLINS TDR-90 FACTORY OPTION	*CF		623D FO	MTH	13-Mar-1986		-			
34FO-15B *34FO-15 : 550/B*	FLIGHT DIRECTOR LH-5 " SINGLE CUE SPERRY FACTORY OPTION	*CF		679B FO	MTH	13-Mar-1986		-			
34FO-15J *34FO-15 : 550/J*	FLIGHT DIRECTOR REM CRS & HDG SGL SPERRY FACTORY OPTION	*CF		679J FO	MTH	13-Mar-1986		-			
34FO-16J *34FO-16 : 550/J*	2ND DME COLLINS DME4 0 FACTORY OPTION	*CF		681J FO	MTH	13-Mar-1986		-			
34FO-20X *34FO-20 : 550/X*	VLF NAV GLOBAL GNS500A SER 3 AFT FACTORY OPTION	*CF		693X FO	MTH	13-Mar-1986		-			
34FO-94N *34FO-94 : 550/N*	RAD ALT SPERRY AA300 W/SEP COPILOT INDICA FACTORY OPTION	*CF		673N FO	MTH	13-Mar-1986		-			
35FO-02B *35FO-02 : 550/B*	OXYGEN SYSTEM 64 CUBIC FEET FACTORY OPTION	*CF		66B FO	MTH	13-Mar-1986		-			
73FO-01C *73FO-01 : 550/C*	ENGINE SYNCHRONIZING INSTRUMENT W/TH REV FACTORY OPTION	*CF		76C FO	MTH	13-Mar-1986		-			
78FO-01	THRUST REVERSERS FACTORY OPTION	*CF		193 FO	MTH	13-Mar-1986		-			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.